



THE PORT AUTHORITY OF NEW YORK AND NEW JERSEY

MEMORANDUM

To: August Preschle, Manager, World Trade Center Operations  
 From: Harry R. Pool, Jr.  
 Date: March 24, 1988  
 Subject: THE WORLD TRADE CENTER - ASBESTOS INVESTIGATION AND ANALYSIS REPORT  
 Copy to: F. Boyce, N. Budeiri, D. Darcy, J. Davison, D. Hahn, P. LaRocco,  
 D. Leahy, R. Linn, P. Maurer, D. Montalbano, J. Pearse,  
 S. Samperl, V. Strom

The baseline asbestos survey of the World Trade Center, whose objective was to locate, identify and assess the condition of asbestos containing materials (ACM) throughout the complex, has been completed. This investigation consisted of three phases: the identification of the location of possible ACM throughout the facility; the collection and laboratory analysis of bulk samples; and the development of an environmental risk assessment.

Air monitoring to date at the facility indicates air quality levels are well within current Federal standards.

Buildings One, Two, Four, Five, and the associated sub-grades were sampled for the presence of ACM in some or all of the following materials: sprayed-on fire retardant on structural support beams, concrete slabs and metal deck ceilings; insulation on heat transfer pipes and insulation on heating and cooling equipment; ceiling tiles; floor tiles; and other materials serving as insulation or acoustical barriers. Sampling of materials, products and locations will continue on an as needed basis at the request of the facility to further define ACM locations and to further define ACM in the vicinity of proposed building alterations.

The Vista Hotel (Building Three) received limited sampling since this structure was built well past the moratorium on the use of asbestos products for insulation and as a fire retardant.

This survey was conducted over the period January 1986 through August 1987, during which time over 15,000 bulk and air samples were collected and analyzed.

The investigation was accomplished by entering areas, both occupied and vacant, to locate possible sources of ACM. The type of possible ACM as well as the building number, sample location, and area description were indicated on the bulk sampling form. In addition, the sampling results are being plotted by WTC staff on the layout plan of each floor for distribution to the applicable operations, planning and construction personnel.

PA0001289

A prioritization system has been developed which will inform the facility as to those areas requiring an Immediate Response. In addition, this system will rate other locations as Priority, Operations and Maintenance, Controlled Condition, or free of asbestos materials (ACM free). The categorization of all surveyed areas and the definitions used in the risk assessment are as follows:

Immediate Response Condition

An Immediate Response Condition (IRC) exists if there is an unavoidable risk potential due to the disturbance of asbestos fallout material within a specific area, which includes evidence of asbestos material separated from initial installation, deteriorated condition of existing asbestos material, high risk of contact, or the possibility of causing unacceptable levels of airborne asbestos fibers in areas frequented by employees and/or patrons. Air sampling should be initiated in all areas rated as IRC (Immediate Response Condition). Redesignation of these locations should take place after the Immediate Response has been completed.

The following locations at the World Trade Center are defined as IRC: the roofs of elevator cars in Tower One within the shafts where delamination has occurred and the B-6 Level Mechanical Room which has fallout material present in one localized area.

World Trade Center management has been briefed on these conditions and provided with a list of specific locations. In addition, the World Trade Center has requested the Inspection and Safety Division to employ the cleanup and disposal call-in contractor to assist in cleaning these areas. A regular monitoring program to detect similar fallout materials in the future should also be initiated.

After receiving immediate notification from the Inspection and Safety Division, the facility responded by initiating and carrying out cleanup and repair activities utilizing the services of licensed asbestos contracting firms to alleviate those conditions existing as IRC designated locations.

These efforts have resulted in the reclassification of the following IRC areas:

<u>Location</u>	<u>Site</u>	<u>Reclassification</u>
Roofs of elevator cars within the shafts.	1 WTC	Operations & Maintenance
B-6 level mechanical equipment room.	1 WTC	Operations & Maintenance

Priority Area

In order for a location to be designated a Priority Area, the asbestos material must be in disrepair or accessible to the extent that worker activity, or other forces, could produce an increase in the level of airborne

PAG001290

asbestos fibers. As with an IRC, Priority Areas should receive air sampling as an additional input for the risk assessment analysis. Periodic re-inspection of conditions in a Priority Area is mandatory. Once a Priority Area is identified by the Inspection and Safety Division, the facility must institute the appropriate measures. All aspects of an Operations and Maintenance Area must also be followed.

The following locations at the World Trade Center are defined as Priority Areas: the northwest corner of the B-2 Level Parking Lot and the northwest corner of the B-4 Level Parking Lot. In addition, all areas in Zone One, One World Trade Center, which did not have the fire safety sprinkler system installed because of the presence of ACM should be considered a Priority Area.

#### Operations and Maintenance

This type of asbestos condition is frequently found where the ACM is installed in a location that is not directly accessible to employees or the public. However, for operational or maintenance purposes, employees may be required to work in close proximity and thereby increase the risk of disturbance to the asbestos. In these areas, workers and building occupants must be alerted to the location of the ACM as applicable, and personnel must be trained in proper cleaning, maintenance, repairs, and renovations. All such areas must be periodically reinspected by the facility.

Based upon our investigation, it has been determined that the Mechanical Equipment rooms where asbestos containing fireproofing and pipe insulation has been identified fall under the category of Operations and Maintenance. In addition, all other World Trade Center areas where asbestos containing sprayed-on fireproofing has been identified (see Summary Tables which follow) also fall under the category of Operations and Maintenance.

#### Controlled Condition

Routine monitoring should be performed when asbestos material is found to be in a Controlled Condition, i.e., when the potential for disturbance is remote (e.g. asbestos within a steel fire floor, most asbestos vinyl tile installations, completely encased ACM, etc.). This type of condition often involves nonfriable material or friable material that is inaccessible under normal circumstances. Reinspection in a Controlled Condition Area is less important than for Operations and Maintenance Areas, however should be performed periodically by the facility to insure the continuity of the controlled condition.

The following locations at the World Trade Center are defined as Controlled Areas: all vinyl floor tiles containing asbestos material, the steel doors containing asbestos fireproofing, and all structurally contained ACM areas. A local exhaust ventilation and collection system equipped with a HEPA (High Efficiency Particulate Absolute) filtration unit designed and operated to capture particulate asbestos material produced by the stripping, cutting or disturbing of asbestos containing materials shall be utilized when work is performed in these areas.

PAG001291

A summary table of all areas and their respective risk assessment ratings immediately follows this memo.

The United States Customs House (Building Six) was surveyed and sampled by an outside consulting firm in accordance with the U.S. General Services Administration Contract. We have secured a copy of the consultant's report on Building Six and it reveals that there are various locations which contain ACM. Although somewhat concerned about the limited number of samples taken by the U.S. Customs consultant, we have nevertheless passed this report along to World Trade Center staff for their edification.

We have consulted, and will continue to consult, with World Trade Center staff on all aspects of the asbestos control program. It is also important to maintain a continuing awareness that any operations and maintenance or construction activity that may disturb ACM shall be carried out in a manner which assures the safety of employees, the public, and the environment in accordance with applicable regulations as well as Port Authority specifications.

The attached report describes conditions as observed at the time and date of the investigation. Physical conditions in some areas may have since changed, thereby altering the attached report. Prior to the development of any abatement plan or control procedure(s), those areas should be visually inspected to determine actual conditions.

A statistical analysis has been completed to establish numbers of samples required per floor to obtain a statistically significant determination and to verify the findings of the survey.

We would like to extend our thanks for the excellent cooperation we have received from the World Trade Center Operations and Maintenance staff. In particular, we acknowledge the outstanding assistance provided by Mr. Frank Boyce and Mr. Jeff Pearse during this investigation.

We will continue to provide further assistance on asbestos related matters. Should you have any questions regarding these findings, please call me at PATHside (201) 963-7476.

Harry R. Pool, Jr., Acting Manager  
Environmental Management Division

AN/wgo  
Att.

PA0001292

HD00044204



ASBESTOS INVESTIGATION AND ANALYSIS REPORT  
WORLD TRADE CENTER  
VOLUME I OF II

ENVIRONMENTAL MANAGEMENT DIVISION  
MARCH 21, 1983

PAG0001288

A prioritization system has been developed which will inform the facility as to those areas requiring an Immediate Response. In addition, this system will rate other locations as Priority, Operations and Maintenance, Controlled Condition, or free of asbestos materials (ACM free). The categorization of all surveyed areas and the definitions used in the risk assessment are as follows:

#### Immediate Response Condition

An Immediate Response Condition (IRC) exists if there is an unavoidable risk potential due to the disturbance of asbestos fallout material within a specific area, which includes evidence of asbestos material separated from initial installation, deteriorated condition of existing asbestos material, high risk of contact, or the possibility of causing unacceptable levels of airborne asbestos fibers in areas frequented by employees and/or patrons. Air sampling should be initiated in all areas rated as IRC (Immediate Response Condition). Redesignation of these locations should take place after the Immediate Response has been completed.

The following locations at the World Trade Center are defined as IRC: the roofs of elevator cars in Tower One within the shafts where delamination has occurred and the B-6 Level Mechanical Room which has fallout material present in one localized area.

World Trade Center management has been briefed on these conditions and provided with a list of specific locations. In addition, the World Trade Center has requested the Inspection and Safety Division to employ the cleanup and disposal call-in contractor to assist in cleaning these areas. A regular monitoring program to detect similar fallout materials in the future should also be initiated.

After receiving immediate notification from the Inspection and Safety Division, the facility responded by initiating and carrying out cleanup and repair activities utilizing the services of licensed asbestos contracting firms to alleviate those conditions existing as IRC designated locations.

These efforts have resulted in the reclassification of the following IRC areas:

<u>Location</u>	<u>Size</u>	<u>Reclassification</u>
Roofs of elevator cars within the shafts.	1 WTC	Operations & Maintenance
B-6 level mechanical equipment room.	1 WTC	Operations & Maintenance

#### Priority Area

In order for a location to be designated a Priority Area, the asbestos material must be in disrepair or accessible to the extent that worker activity, or other forces, could produce an increase in the level of airborne

PAG001290

asbestos fibers. As with an IRC, Priority Areas should receive air sampling as an additional input for the risk assessment analysis. Periodic re-inspection of conditions in a Priority Area is mandatory. Once a Priority Area is identified by the Inspection and Safety Division, the facility must institute the appropriate measures. All aspects of an Operations and Maintenance Area must also be followed.

The following locations at the World Trade Center are defined as Priority Areas: the northwest corner of the B-2 Level Parking Lot and the northwest corner of the B-4 Level Parking Lot. In addition, all areas in Zone One, One World Trade Center, which did not have the fire safety sprinkler system installed because of the presence of ACM should be considered a Priority Area.

#### Operations and Maintenance

This type of asbestos condition is frequently found where the ACM is installed in a location that is not directly accessible to employees or the public. However, for operational or maintenance purposes, employees may be required to work in close proximity and thereby increase the risk of disturbance to the asbestos. In these areas, workers and building occupants must be alerted to the location of the ACM as applicable, and personnel must be trained in proper cleaning, maintenance, repairs, and renovations. All such areas must be periodically reinspected by the facility.

Based upon our investigation, it has been determined that the Mechanical Equipment rooms where asbestos containing fireproofing and pipe insulation has been identified fall under the category of Operations and Maintenance. In addition, all other World Trade Center areas where asbestos containing sprayed-on fireproofing has been identified (see Summary Tables which follow) also fall under the category of Operations and Maintenance.

#### Controlled Condition

Routine monitoring should be performed when asbestos material is found to be in a Controlled Condition, i.e., when the potential for disturbance is remote (e.g. asbestos within a steel fire floor, most asbestos vinyl tile installations, completely encased ACM, etc.). This type of condition often involves nonfriable material or friable material that is inaccessible under normal circumstances. Reinspection in a Controlled Condition Area is less important than for Operations and Maintenance Areas, however should be performed periodically by the facility to insure the continuity of the controlled condition.

The following locations at the World Trade Center are defined as Controlled Areas: all vinyl floor tiles containing asbestos material, the steel doors containing asbestos fireproofing, and all structurally contained ACM areas. A local exhaust ventilation and collection system equipped with a HEPA (High Efficiency Particulate Absolute) filtration unit designed and operated to capture particulate asbestos material produced by the stripping, rutting or disturbing of asbestos containing materials shall be utilized when work is performed in these areas.

PAG001291

A summary table of all areas and their respective risk assessment ratings immediately follows this memo.

The United States Customs House (Building Six) was surveyed and sampled by an outside consulting firm in accordance with the U.S. General Services Administration Contract. We have secured a copy of the consultant's report on Building Six and it reveals that there are various locations which contain ACM. Although somewhat concerned about the limited number of samples taken by the U.S. Customs consultant, we have nevertheless passed this report along to World Trade Center staff for their edification.

We have consulted, and will continue to consult, with World Trade Center staff on all aspects of the asbestos control program. It is also important to maintain a continuing awareness that any operations and maintenance or construction activity that may disturb ACM shall be carried out in a manner which assures the safety of employees, the public, and the environment in accordance with applicable regulations as well as Port Authority specifications.

The attached report describes conditions as observed at the time and date of the investigation. Physical conditions in some areas may have since changed, thereby altering the attached report. Prior to the development of any abatement plan or control procedure(s), those areas should be visually inspected to determine actual conditions.

A statistical analysis has been completed to establish numbers of samples required per floor to obtain a statistically significant determination and to verify the findings of the survey.

We would like to extend our thanks for the excellent cooperation we have received from the World Trade Center Operations and Maintenance staff. In particular, we acknowledge the outstanding assistance provided by Mr. Frank Boyce and Mr. Jeff Pearce during this investigation.

We will continue to provide further assistance on asbestos related matters. Should you have any questions regarding these findings, please call me at PATHside (201) 963-7476.

Harry R. Pool, Jr., Acting Manager  
Environmental Management Division

AN/ugo  
Att.

PA0001292

HD00044204



WORLD TRADE CENTER

BUILDING ONE

SUMMARY TABLE

<u>IMMEDIATE RESPONSE</u> <u>CONDITION AREA</u>	<u>PRIORITY</u> <u>AREA</u>	<u>OPERATIONS MAINTENANCE</u> <u>AREA</u>	<u>NON-ACM</u> <u>AREA</u>
* None	B 2 NW corner B 2 NW corner	Floors: 32 & 39 41/42 48 74 75/76 MER 82,83 104 107 B-1 B-2 B-6	Floors: 43-47 49-73 77-81 84-103 105 & 106 108/109 B3, B4 & B5
	Floors: 1 - 31 33 - 37 40	Elevator shafts: 01 - 68 72 - 74	Elevator shafts: 69 - 71 75 - 98
		Elevator pits: 01 - 47 01 - 05 08 - 47	Elevator pits: 6,7

\* The IRC areas: Elevator car tops and B-6 MER have been reclassified as Operations and Maintenance areas.

PAG001293

HD00044205

WORLD TRADE CENTER

BUILDING TWO

SUMMARY TABLE

<u>IMMEDIATE RESPONSE</u> <u>CONDITION AREA</u>	<u>PRIORITY</u> <u>AREA</u>	<u>OPERATIONS MAINTENANCE</u> <u>AREA</u>	<u>NON-ACV</u> <u>AREA</u>
None	None	Floors: 1,6 7/8 MER 10 - 13 26 32 & 33 40 41/42 MER 43 74 75/76 MER B2 B5/B6 MER	Floors: 2 - 5 9 14 - 25 27 - 31 34 - 39 44 - 73 77 - 110 B1 B3 & B4
		Elevator shafts: 03 - 05 10 & 11 14 & 15 24 - 50 54 - 59 66 - 68	Elevator shafts: 1 & 2 6 - 9 12 & 13 16 - 23 51 - 53 60 - 65 69 - 98
		Elevator pics: 24 & 25 28 - 48	Elevator pics: 01 - 21 27

PA0001294

WORLD TRADE CENTER  
BUILDINGS 3, 4, 5, 6 AND SUB-LEVELS  
SUMMARY TABLE

<u>BUILDING NUMBER</u>	<u>IMMEDIATE RESPONSE CONDITION</u>	<u>PRIORITY AREA</u>	<u>OPERATIONS MAINTENANCE AREA</u>	<u>NON-ACM AREA</u>
Three	None	None	None	1, B1
Four	None	None	None	Floors: 2 - 9 B1 & B2
Five	None	None	None 2 5 9 B1	Floors: 3,4 6 - 8 B2 & B4 2
Six	None	None	None	None
Northeast Sub-levels	None	None	None	Floors: Concourse B1 & B2
Southeast Sub-levels	None	None	None	Floors: Concourse B2 & B4
Northwest Sub-Levels	None	None	Floors: B1, B2 & B4	Floors: Concourse B3, B5 & B6
Southwest Sub-Levels	None	None	Floor: B1, B2 & B6	Floors: B5

PA0001295

HD00044207

ASBESTOS INVESTIGATION AND ANALYSIS REPORT


THE WORLD TRADE CENTER

Acting Manager:	Harry R. Pool, Jr.
Project Supervisor:	Joseph Mullen
Laboratory Supervisor:	Austin Kreutz
Field Supervisor:	Philip Taylor
Field Inspectors:	Michael Denisen John Driscoll Mark Jakubek Charles Landi Ramon Leston Richard Lighchiser Frank Losagio Alfonse Niedermeyer Dushyant Patel David Placc Glenn Small Philip Taylor
Laboratory Analysts:	Hans Brown Mark Fish Austin Kreutz David W. Placc
Data Base Management:	David W. Placc Angel Rios Glenn Small
Data Base Entry:	W. Garrett Otto Angel Rios Glenn Small
Report Preparation:	Michael Denisen Andrew Driver Ramon Leston Richard Lighthiser Uday Mehta Alfonse Niedermeyer Glenn Small Philip Taylor


ENVIRONMENTAL MANAGEMENT DIVISION

PA0001296

HD00044208




HD00044209



FIELD INSPECTORS VISUALLY ASSESSING AN AREA FOR THE PRESENCE OF POSSIBLE ASBESTOS CONTAINING MATERIAL. ONCE IDENTIFIED, A "BULK" SAMPLE OF THE SUSPECT MATERIAL IS COLLECTED.




AFTER THE BULK SAMPLE IS COLLECTED, THE SAMPLE AND SAMPLING EQUIPMENT IS CLEANED FOLLOWED BY THE SAMPLING SITE BEING SEALED AND NUMBERED FOR FUTURE IDENTIFICATION.





THIS IS A TYPICAL FLOOR SUPPORT SYSTEM WITH JOIST AND METAL DECK COMPONENTS. AS CAN BE OBSERVED, THE TOP PHOTOGRAPH REPRESENTS A FLOOR SYSTEM WITHOUT SPRAYED-ON FIREPROOFING. THE BOTTOM PHOTOGRAPH EXHIBITS THE PHYSICAL CONDITION WITH ENCAPSULATED SPRAYED-ON FIREPROOFING ON A TYPICAL FLOOR.








THE TOP PHOTOGRAPH SHOWS A TYPICAL FLOOR SUPPORT SYSTEM WITH SPRAYED-ON FIREPROOFING TO WHICH IS MOUNTED AN AIR HANDLING UNIT. THE BOTTOM PHOTOGRAPH IS A TYPICAL WINDOW CONVECTOR UNIT WITH CEMENTITIOUS FIREPROOFING ON THE EXTERIOR FLOOR BEAMS.

THE FOLLOWING PHOTOGRAPHS REPRESENT VARIOUS MECHANICAL  
SYSTEMS IN THE EQUIPMENT ROOMS.






HD00044215




#### IMMEDIATE RESPONSE CONDITION

AN IMMEDIATE RESPONSE CONDITION EXISTS IF THERE IS AN UNAVOIDABLE RISK POTENTIAL DUE TO THE DISTURBANCE OF ASBESTOS FALLOUT MATERIAL WITHIN A SPECIFIC AREA, WHICH INCLUDES EVIDENCE OF ASBESTOS MATERIAL SEPARATED FROM INITIAL INSTALLATION, DETERIORATED CONDITION OF EXISTING ASBESTOS MATERIAL, HIGH RISK OF CONTACT AND/OR THE POSSIBILITY OF CAUSING UNACCEPTABLE LEVELS OF AIRBORNE ASBESTOS FIBERS IN AREAS FREQUENTED BY EMPLOYEES AND/OR PATRONS. AIR SAMPLING SHALL BE INITIATED IN ALL AREAS RATED AS IRC (IMMEDIATE RESPONSE CONDITION). THE AIR SAMPLING WILL BE CONDUCTED BY THE INSPECTION AND SAFETY DIVISION. REDESIGNATION OF THESE LOCATIONS SHOULD TAKE PLACE AFTER THE IMMEDIATE RESPONSE HAS BEEN COMPLETED.




#### PRIORITY AREA

IN ORDER FOR A LOCATION TO BE DESIGNATED A PRIORITY AREA, THE ASBESTOS MATERIAL MUST BE IN DISREPAIR OR ACCESSIBLE TO THE EXTENT THAT WORKER ACTIVITY OR OTHER FORCES COULD PRODUCE AN INCREASE IN THE LEVEL OF AIRBORNE ASBESTOS FIBERS. AS WITH AN IRC, PRIORITY AREAS SHOULD RECEIVE AIR SAMPLING AS ADDITIONAL INPUT FOR THE RISK ASSESSMENT ANALYSIS. PERIODIC REINSPECTION OF CONDITIONS IN A PRIORITY AREA ARE MANDATORY AND THESE AREAS SHOULD TOP THE LIST OF AREAS THAT WILL RECEIVE REMEDIAL ATTENTION. ONCE A PRIORITY AREA IS IDENTIFIED BY THE INSPECTION AND SAFETY DIVISION THE FACILITY MUST INSTITUTE THE APPROPRIATE MEASURES. ALL ASPECTS OF AN OPERATIONS AND MAINTENANCE AREA MUST ALSO BE FOLLOWED.



OPERATIONS AND MAINTENANCE AREA

THIS TYPE OF ASBESTOS CONDITION IS FREQUENTLY FOUND WHERE THE ACM IS USUALLY INSTALLED IN A LOCATION THAT IS NOT DIRECTLY ACCESSIBLE TO EMPLOYEES OR THE PUBLIC. HOWEVER, FOR OPERATIONAL OR MAINTENANCE PURPOSES EMPLOYEES MAY BE REQUIRED TO WORK IN CLOSE PROXIMITY AND INCREASE THE RISK OF DISTURBANCE TO THE ASBESTOS. IN THESE AREAS, WORKERS AND BUILDING OCCUPANTS MUST BE ALERTED TO THE LOCATION OF THE ACM AS APPLICABLE; PERSONNEL MUST BE TRAINED IN PROPER CLEANING, MAINTENANCE, REPAIRS, AND RENOVATIONS; AND ALL SUCH AREAS MUST BE PERIODICALLY REINSPECTED BY THE FACILITY.



# TYPICAL FLOOR PLAN

## BUILDING ASBESTOS SURVEY

### LEGEND

- NON-ASBESTOS MATERIAL
- ▼ ASBESTOS CONTAINING MATERIAL
- ◆ AIR SAMPLING LOCATION

PAG001307

## EXPLANATION OF THE DATA REPORT

This report is a collation of a computer generated analysis of the World Trade Center bulk sample database, the results of a statistical analysis of portions of the same database performed by a consultant, and a qualitative interpretation of the data-base by the staff of the Inspection and Safety Division. The following notes describe the format of the data summary and the terms used in the summary.

### Format

The report consists of a summary, laboratory procedures and sixteen sections, one for each of the buildings and sub-grade areas. Each of the major sections is further divided into three sub-sections. The first of each sub-section is a list of floors where no asbestos containing material (ACM) was found and the number of samples taken on those floors. The second sub-section is a list of the floors where ACM was found. Included in this sub-section are the number of samples and the number of samples found to contain ACM according to the location of the sample (e.g. ceiling, convactor etc.). The last sub-section is a listing of all samples, including location and laboratory result, taken from sampling areas that were found to be positive for ACM.

### Definitions

Sample: A single container of material obtained for the purpose of submission to the laboratory for the analysis of the presence, type and proportion of asbestos.

Resample: A sample taken for the purpose of receiving inconclusive or anomalous analytical results from a previous sample.

Sampling area: The location where a sample, or a sample and one or more resamples, were taken.

Positive: A sample or sampling area found to contain greater than one percent asbestos.

Trace: A barely perceivable indication of asbestos that is much less than the USEPA limit for ACM.

Ceiling structures: The metal decking, concrete slab or other structure that is the inside or top covering of a room, opposite the floor, and its supporting beams, trusses and joists.

Piping/HVAC: Any duct, boiler, chiller, heat transfer or other pipe that make up the internal plumbing or heating, ventilation and air-conditioning system.

PAG001308



Convectors: The area containing the heat diffuser units along the perimeter of the building.

Fallout: Debris found on horizontal or nearly horizontal surfaces.

Other: Miscellaneous materials such as ceiling tiles, wall board and air-conditioner filters.

Inspection and Safety Division's Determination: The results of Inspection and Safety Division's qualitative examination of the data on the ceiling structures.

Non-ACM: Floors where all samples from the ceiling structure were found negative, or may have a single positive result with a low percentage of asbestos. Abatement may not be necessary.

Localized Abatement: Floors where the majority of samples were negative for ACM but had a few samples positive for ACM where spot or partial abatement may be advisable.

Full abatement: Floors on which the number of samples testing positive for ACM are high enough to indicate that spot or partial abatement is not advisable.

PAG001309

HD00044221

TABLE OF CONTENTS

VOLUME I

SURVEY AND BULK SAMPLES

World Trade Center Concourse	1
One World Trade Center Floors	4
One World Trade Center Elevator Shafts	131
One World Trade Center Elevator Pits	173

VOLUME II

SURVEY AND BULK SAMPLES - (CONTINUED....)

Two World Trade Center Floors	192
Two World Trade Center Elevator Shafts	281
Two World Trade Center Elevator Pits	304
Three World Trade Center Floors	323
Four World Trade Center Floors	325
Five World Trade Center Floors	328
Six World Trade Center Floors	335
Northeast World Trade Center Sub-levels	337
Northwest World Trade Center Sub-levels	340
Southeast World Trade Center Sub-levels	347
Southwest World Trade Center Sub-levels	349
World Trade Center River Water Pumping Station	357
Summary	358
Laboratory Procedures	386

PA0001310

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
CONCOURSE

FLOORS WITH NON-ACM CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACM SAMPLES</u>
1	170	170

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
CONCOURSE

FLOOR - 1

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	10	0	0	10	0	0
TOTAL	199	170	0	21	7	1

WORLD TRADE CENTER  
CONCOURSE

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3447	SWTC-03447	CEMENTITIOUS TROVELED ON DUCT INSULATION MATERIAL ABOVE THE GARRAGE BINS BEHIND THE EAT AND DRINK RESTAURANT.	70% CHRYSOTILE ASBESTOS
3448	SWTC-03448	FLUFFY PREFORMED DUCT PADS INSULATION MATERIAL ABOVE THE GARRAGE BINS BEHIND THE EAT AND DRINK RESTAURANT.	60% CHRYSOTILE ASBESTOS
3449	SWTC-03449	FLUFFY TROVELED ON DUCT INSULATION MATERIAL ABOVE THE RAILING OF THE GARRAGE BIN AREA BEHIND THE EAT AND DRINK RESTAURANT.	75% CHRYSOTILE ASBESTOS
3450	SWTC-03450	FLUFFY PREFORMED DUCT PADS INSULATION MATERIAL ABOVE THE RAILING OF THE GARRAGE BIN AREA BEHIND THE EAT AND DRINK RESTAURANT.	60% CHRYSOTILE ASBESTOS
3454	SWTC-03454	FLUFFY FALLOUT MATERIAL ON TOP OF DUCT OVER STORAGE ROOM BEHIND THE EAT AND DRINK RESTAURANT.	15% CHRYSOTILE ASBESTOS
3455	SWTC-03455	CEMENTITIOUS TROVELED ON DUCT INSULATION MATERIAL ABOVE THE STORAGE ROOM BEHIND THE EAT AND DRINK RESTAURANT.	73% CHRYSOTILE ASBESTOS
3456	SWTC-03456	FLUFFY PREFORMED DUCT PADS INSULATION MATERIAL ABOVE THE STORAGE ROOM BEHIND THE EAT AND DRINK RESTAURANT.	30% CHRYSOTILE ASBESTOS
13397	SWTC-13397	CEMENTITIOUS INSULATION MATERIAL FROM A 3" O.D. HEAT TRANSFER PIPE ELBOW LOCATED NEAR COLUMN 188 OF THE CHESS KING STORE.	65% CHRYSOTILE ASBESTOS
13402	SWTC-13402	CEMENTITIOUS INSULATION MATERIAL FROM A 4" O.D. HEAT TRANSFER PIPE COUPLING LOCATED IN THE CENTER OF THE CHESS KING STORE.	65% CHRYSOTILE ASBESTOS
13406	SWTC-13406	CEMENTITIOUS INSULATION MATERIAL FROM A 5" O.D. HEAT TRANSFER PIPE ELBOW LOCATED AT THE WEST WALL OF THE CHESS KING STORE.	60% CHRYSOTILE ASBESTOS

PA0001313

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 ONE WORLD TRADE CENTER

FLOORS WITH NON-ACM CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACM SAMPLES</u>
83	3	3
43	35	33
44	35	35
45	48	48
46	28	28
47	29	29
49	36	36
50	41	41
51	44	44
52	52	52
53	32	32
54	57	37
55	40	40
56	32	32
57	43	43
58	32	32
59	32	32
60	32	32
61	40	40
62	44	44
63	32	32
64	31	31
65	47	47
66	42	42
67	47	47
68	41	41
69	31	31
70	43	43
71	38	38
72	48	44
73	30	30
77	32	32
78	41	41
79	33	33
80	41	41
81	45	45
84	42	42
85	32	32
86	25	25
87	38	38
88	32	32
89	32	32
90	32	32
91	30	30
92	30	30
93	25	25

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOORS WITH NON-ACM CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACM SAMPLES</u>
94	31	31
95	32	32
96	37	37
97	32	32
98	32	32
99	32	32
100	43	43
101	33	33
102	60	56
103	32	32
105	40	40
106	54	54
106	31	31
110	7	7

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 31

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	47	64	0	1	1	1
TOTAL	86	38	0	23	1	4

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 32

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	8	8	0	1	1	0
TOTAL	10	9	0	10	1	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT

FLOOR - 33

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	0	1	0	0
TOTAL	1	0	0	1	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 34

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	0	1	0	0
TOTAL	4	0	0	2	1	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 35

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	11	3	0	8	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH



WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 34

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	42	10	0	8	4	0
TOTAL	187	81	0	99	7	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 1

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	1	0	2	0	0
TOTAL	11	3	0	2	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 2

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	17	17	0	0	0	0
TOTAL	20	20	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 3

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	13	13	0	0	0	0
TOTAL	13	13	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 4

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	10	10	0	0	0	0
TOTAL	12	12	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 5

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	9	9	0	0	0	0
TOTAL	12	12	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 6

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	27	27	0	0	0	0
TOTAL	35	35	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 7

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	37	31	0	4	2	0
TOTAL	84	39	0	43	2	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 9

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	7	6	1	0	0	0
TOTAL	16	16	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 10

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	21	21	0	0	0	0
TOTAL	25	23	0	0	2	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

WORLD TRADE CENTER  
ASBESTOS BGLX SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 11

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	14	14	0	0	0	0
TOTAL	21	21	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 12

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	14	12	1	0	0	1
TOTAL	30	13	1	0	0	4

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 13

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	32	30	1	0	0	0
TOTAL	47	33	11	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 14

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	14	12	2	0	0	0
TOTAL	19	10	1	0	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 15

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	12	12	0	0	0	0
TOTAL	19	10	2	0	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

WORLD TRADE CENTER  
ASBESTOS Bulk SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 16

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	21	21	8	0	0	0
TOTAL	33	28	3	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 17

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	24	24	0	0	0	0
TOTAL	47	33	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 18

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	18	14	1	8	0	1
TOTAL	24	19	1	0	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 19

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	33	33	0	8	0	0
TOTAL	48	34	12	8	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 20

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	8	8	0	0	0	0
TOTAL	21	17	1	8	0	3

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

PA0001320

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 21

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	23	23	0	0	0	0
TOTAL	43	32	1	0	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 22

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	29	29	0	0	0	0
TOTAL	43	36	1	0	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 23

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	14	14	0	0	0	0
TOTAL	21	17	0	0	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 24

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	40	35	1	0	0	0
TOTAL	58	46	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 25

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	32	32	0	0	0	0
TOTAL	42	40	1	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 ONE WORLD TRADE CENTER

FLOOR - 26

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	17	13	0	0	0	2
TOTAL	23	20	1	0	0	2

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 27

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	34	34	0	0	0	0
TOTAL	54	42	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 28

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	21	21	0	0	0	0
TOTAL	27	24	0	0	0	3

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 29

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	8	8	0	0	0	0
TOTAL	12	12	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 30

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	27	27	0	0	0	0
TOTAL	52	40	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

WORLD TRADE CENTER  
ASBESTOS Bulk SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 31

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	32	32	0	0	0	0
TOTAL	55	51	4	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 32

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	29	29	0	0	0	0
TOTAL	147	142	5	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 33

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	13	13	0	0	0	0
TOTAL	44	51	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 34

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	7	7	0	0	0	0
TOTAL	19	10	0	0	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 35

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	24	24	0	0	0	0
TOTAL	47	35	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

PA0001323

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 36

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	27	26	1	0	0	0
TOTAL	27	33	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 37

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	39	39	0	0	0	0
TOTAL	97	84	13	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 38

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	2	0	0	0	0
TOTAL	78	67	9	0	0	2

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT

FLOOR - 39

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	2	0	0	0	0
TOTAL	67	61	6	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT

FLOOR - 40

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	33	33	0	0	0	0
TOTAL	63	53	7	0	0	3

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

PAG001324



WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 41

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	10	3	0	4	1	0
TOTAL	43	30	0	32	2	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT

FLOOR - 43

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	30	35	12	0	3	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 44

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	0	1	0	0
TOTAL	48	35	12	1	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 45

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	49	48	1	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 46

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	30	28	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

PAG0001325

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 47

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	30	29	1	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 48

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	8	8	0	0	0	0
TOTAL	77	74	3	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ASBESTOS

FLOOR - 49

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	38	36	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 50

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	53	41	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 51

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	48	44	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

PA0001326

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 52

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	64	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 53

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 54

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	60	37	3	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 55

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	41	40	1	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 56

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	0	2	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

PAG001327

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 57

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	35	43	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 58

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 59

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 60

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	52	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 61

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	42	40	1	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 62

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	44	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 63

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	47	32	15	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 64

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	31	31	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 65

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	0	2	0	0	0
TOTAL	67	47	20	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 66

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	42	41	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

PA00001329

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 ONE WORLD TRADE CENTER

FLOOR - 67

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	30	47	3	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACN

FLOOR - 68

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	41	41	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACN

FLOOR - 69

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	31	31	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACN

FLOOR - 70

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	43	43	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACN

FLOOR - 71

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	35	38	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACN

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 72

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	4	4	0	0	0	0
TOTAL	48	48	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 73

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	34	30	4	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 74

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	20	20	0	0	0	0
TOTAL	29	29	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

FLOOR - 75

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	18	6	0	10	2	0
TOTAL	90	32	0	41	17	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT

FLOOR - 77

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	0	2	0	0	0
TOTAL	44	32	12	3	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

PA0001331

WORLD TRADE CENTER  
 ASBESTOS RUCK SAMPLING REPORT  
 ONE WORLD TRADE CENTER

FLOOR - 78

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	33	41	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 79

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	45	33	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 80

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	47	41	6	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 81

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	48	45	2	1	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 82

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	18	18	0	0	0	0
TOTAL	96	96	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT



WORLD TRADE CENTER  
 ASBESTOS bulk SAMPLING REPORT  
 ONE WORLD TRADE CENTER

FLOOR - 83

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	3	0	0	0	0
TOTAL	38	36	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT

FLOOR - 84

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	43	42	1	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 85

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	14	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 86

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	23	25	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 87

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	39	38	1	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 88

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/MVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 89

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/MVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 90

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/MVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 91

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/MVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	31	30	1	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 92

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/MVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	32	30	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 93

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	28	25	3	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 94

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	43	31	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 95

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 96

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	33	37	10	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 97

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	0	2	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

PA0001335

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 98

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	63	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 99

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 100

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	57	43	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 101

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	65	33	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 102

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	2	0	0	0	0
TOTAL	60	60	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

FLOOR - 103

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	0	2	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACT

FLOOR - 104

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	16	16	0	0	0	0
TOTAL	63	42	3	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT

FLOOR - 105

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVS	1	0	1	0	0	0
TOTAL	44	40	4	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACT

FLOOR - 106

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	44	34	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACT

FLOOR - 107

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	30	23	3	0	4	0
TOTAL	51	39	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABATEMENT

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 ONE WORLD TRADE CENTER

FLOOR - 108

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/MVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	0	0	3	0	0
TOTAL	93	31	0	15	9	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 110

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/MVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	7	7	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

PA0001338

ONE WORLD TRADE CENTER  
FLOOR: 31

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
848	1WTC-12548	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM ABOVE THE ENTRANCE TO THE ALLIED OFFICES.	10% CHRYSOTILE ASBESTOS 10% TREMOLITE ASBESTOS
850	1WTC-00850	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE FRONT ALLIED OFFICE.	15% CHRYSOTILE ASBESTOS
851	1WTC-00851	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE REAR ALLIED OFFICE.	10% CHRYSOTILE ASBESTOS
852	1WTC-00852	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A DUCT IN THE PLENUM OF THE REAR ALLIED OFFICE.	10% TREMOLITE ASBESTOS
853	1WTC-00853	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE REAR ALLIED OFFICE.	10% CHRYSOTILE ASBESTOS 5% TREMOLITE ASBESTOS
854	1WTC-00854	FLUFFY INSULATION MATERIAL FROM THE CORE OF A SWINGING DOOR AT THE ENTRANCE TO THE ALLIED OFFICES.	20% AMOSITE ASBESTOS 10% CHRYSOTILE ASBESTOS
858	1WTC-00858	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE PLENUM OF THE EAST WALL CORRIDOR.	15% CHRYSOTILE ASBESTOS
857	1WTC-00857	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE PLENUM OF THE EAST WALL CORRIDOR.	20% CHRYSOTILE ASBESTOS
858	1WTC-00858	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM LOCATED IN THE PLENUM OF THE EAST WALL CORRIDOR.	15% CHRYSOTILE ASBESTOS
860	1WTC-00860	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE PLENUM OF THE EAST WALL CORRIDOR.	25% CHRYSOTILE ASBESTOS
861	1WTC-00861	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE PLENUM OF THE EAST WALL CORRIDOR.	25% CHRYSOTILE ASBESTOS
862	1WTC-00862	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE PLENUM OF THE EAST WALL CORRIDOR.	20% CHRYSOTILE ASBESTOS
863	1WTC-00863	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE PLENUM OF THE EAST WALL CORRIDOR.	25% CHRYSOTILE ASBESTOS
12595	1WTC-12595	FLUFFY SPRAYED ON BEAM INSULATION MATERIAL EXPOSED AT THE NORTH-EAST AREA OF THE PUMP ROOM.	30% CHRYSOTILE ASBESTOS
12585	1WTC-12585	FLUFFY SPRAYED ON BEAM INSULATION MATERIAL EXPOSED AT THE SOUTH-EAST AREA OF THE PUMP ROOM.	30% CHRYSOTILE ASBESTOS
12588	1WTC-12588	FLUFFY SPRAYED ON BEAM INSULATION MATERIAL EXPOSED AT THE SOUTH SIDE OF THE PUMP ROOM.	50% CHRYSOTILE ASBESTOS
12605	1WTC-12605	FLUFFY SPRAYED ON BEAM INSULATION MATERIAL EXPOSED IN THE WEST SIDE AREA OF THE PUMP ROOM.	30% CHRYSOTILE ASBESTOS

PAG001339

WORLD TRADE CENTER  
FLOOR: B1

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
12607	1WTC-12607	FLUFFY SPRAYED ON BEAM INSULATION MATERIAL EXPOSED IN THE NORTH WEST CORNER OF PUMP ROOM.	30% CHRYSOTILE ASBESTOS
12609	1WTC-12609	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLenum OF THE MAIN CORRIDOR AT THE STRUCTURAL SHOP ENTRANCE.	30% CHRYSOTILE ASBESTOS
12610	1WTC-12610	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM IN THE PLenum OF THE STRUCTURAL SHOP.	5% CHRYSOTILE ASBESTOS
12612	1WTC-12612	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE WEST WALL OF THE STRUCTURAL SHOP.	30% CHRYSOTILE ASBESTOS
12615	1WTC-12615	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE CENTER OF THE STRUCTURAL SHOP.	30% CHRYSOTILE ASBESTOS
12617	1WTC-12617	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE NORTH WALL OF THE STRUCTURAL SHOP.	40% CHRYSOTILE ASBESTOS
12618	1WTC-12618	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED ON THE NORTH WALL OF THE ELECTRICAL SUB-STATION.	25% CHRYSOTILE ASBESTOS
12619	1WTC-12619	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE NORTH WALL OF THE ELECTRICAL SUB-STATION.	25% CHRYSOTILE ASBESTOS
12620	1WTC-12620	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED ON THE EAST WALL OF THE ELECTRICAL SUB-STATION.	25% CHRYSOTILE ASBESTOS
12621	1WTC-12621	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE SOUTH WALL OF THE ELECTRICAL SUB-STATION.	60% CHRYSOTILE ASBESTOS
12622	1WTC-12622	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE SOUTH WALL OF THE ELECTRICAL SUB-STATION.	60% CHRYSOTILE ASBESTOS
12623	1WTC-12623	FLUFFY FALLOUT MATERIAL ON TOP OF THE ELEVATOR DISTRIBUTION PANEL AT THE NORTH WALL OF THE ELECTRICAL SUB-STATION.	60% CHRYSOTILE ASBESTOS
12624	1WTC-12624	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED ABOVE THE P-3 TRANSFORMED UNIT IN THE ELECTRICAL SUB-STATION.	40% CHRYSOTILE ASBESTOS
12625	1WTC-12625	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED ON THE WEST WALL OF THE ELECTRICAL SUB-STATION.	70% CHRYSOTILE ASBESTOS
12626	1WTC-12626	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED ON THE SOUTH WALL OF THE ELECTRICAL SUB-STATION.	70% CHRYSOTILE ASBESTOS
13030	1WTC-13030	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLenum OF THE SOUTH EAST CORRIDOR AT THE SOUTH WALL.	35% CHRYSOTILE ASBESTOS
13031	1WTC-13031	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED IN THE AIR CONDITIONING FAN ROOM.	30% CHRYSOTILE ASBESTOS

PA0001340



ONE WORLD TRADE CENTER  
FLOOR: B1

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
13053	1WTC-13053	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED IN THE AIR CONDITIONING FAN ROOM.	301 CHRYSOTILE ASBESTOS
13055	1WTC-13055	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED IN THE AIR CONDITIONING FAN ROOM AT COLUMN 454.	301 CHRYSOTILE ASBESTOS
13057	1WTC-13057	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED IN THE SOUTHWEST CORNER OF THE ATTIC STOCKROOM.	301 CHRYSOTILE ASBESTOS
13058	1WTC-13058	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED IN THE ATTIC STOCKROOM.	301 CHRYSOTILE ASBESTOS
13061	1WTC-13061	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED EAST OF COLUMN 1101 IN THE ATTIC STOCKROOM.	301 CHRYSOTILE ASBESTOS
13064	1WTC-13064	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED SOUTH OF COLUMN 1104 IN THE STOCKROOM.	301 CHRYSOTILE ASBESTOS
13065	1WTC-13065	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED SOUTH OF COLUMN 1103 IN THE STOCKROOM.	301 CHRYSOTILE ASBESTOS
13066	1WTC-13066	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	301 CHRYSOTILE ASBESTOS
13067	1WTC-13067	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	50: AMOSITE ASBESTOS 5X CHRYSOTILE ASBESTOS
13092	1WTC-13092	FLUFFY SPRAYED ON INSULATION MATERIAL TAKEN FROM A BEAM IN THE COMPRESSOR ROOM NEAR THE TRUCK DOCK AREA.	401 CHRYSOTILE ASBESTOS
13144	1WTC-13144	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A BEAM IN THE PLENUM NEAR THE WEST END OF THE MAIN CORRIDOR.	401 CHRYSOTILE ASBESTOS
13167	1WTC-13167	CEMENTITIOUS SPRAYED ON INSULATION MATERIAL TAKEN FROM A BEAM IN THE PLENUM IN FRONT OF ELEVATOR CAR 830.	1-31 CHRYSOTILE ASBESTOS
13168	1WTC-13168	FLUFFY SPRAYED ON INSULATION MATERIAL TAKEN FROM A BEAM IN THE PLENUM OF THE SOUTH MAIN CORRIDOR.	301 CHRYSOTILE ASBESTOS

PAG001341

ONE WORLD TRADE CENTER  
FLOOR: 32

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
333	1WTC-00333	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED WITHIN THE FORUM'S LAVATORY.	232 CHRYSOTILE ASBESTOS
699	1WTC-00699	FLUFFY FALLOUT MATERIAL FROM THE GRID DECKING OF THE STEAM RISER SHAFT CLOSET.	102 AMOSITE ASBESTOS
700	1WTC-00700	CEMENTITIOUS INSULATION MATERIAL FROM AN 8" O.D. HEAT TRANSFER PIPE LOCATED WITHIN THE ELECTRICAL ADMINISTRATION OFFICE.	201 AMOSITE ASBESTOS
769	1WTC-00769	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED WITHIN THE MEN'S LAVATORY.	231 CHRYSOTILE ASBESTOS
771	1WTC-00771	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED WITHIN THE MEN'S LAVATORY.	232 CHRYSOTILE ASBESTOS
772	1WTC-00772	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED WITHIN THE LOCKSMITH SHOP.	101 CHRYSOTILE ASBESTOS
773	1WTC-00773	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED WITHIN THE LOCKSMITH SHOP.	101 CHRYSOTILE ASBESTOS
774	1WTC-00774	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED WITHIN THE LOCKSMITH SHOP.	201 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: B3

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
434	1WTC-00434	CEMENTITIOUS INSULATION MATERIAL FROM A MAIN STEAM PIPE IN THE CLOTHING STORAGE AREA IN THE NORTHWEST QUADRANT.	100 AMOSITE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 34

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
432	1WTC-CC451	CEMENTITIOUS INSULATION MATERIAL ON A HIGH STEAM PRESSURE PIPE ON THE EAST WALL OF THE STORAGE AREA IN THE NORTHWEST QUADRANT.	100 AMOSITZ ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR 84

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
120	1WTC-00120	CEMENTITIOUS INSULATION MATERIAL FROM A HEAT TRANSFER PIPE VALVE ON THE STEAM MANIFOLD AT THE EAST WALL.	51 CHRYSOTILE ASBESTOS
121	1WTC-00121	CEMENTITIOUS INSULATION MATERIAL FROM A VERTICAL HEAT TRANSFER PIPE ON THE STEAM MANIFOLD AT THE EAST WALL.	51 CHRYSOTILE ASBESTOS
122	1WTC-00122	CEMENTITIOUS INSULATION MATERIAL FROM A HEAT TRANSFER PIPE VALVE ON THE STEAM MANIFOLD AT THE EAST WALL.	51 CHRYSOTILE ASBESTOS
123	1WTC-00123	CEMENTITIOUS INSULATION MATERIAL FROM A HEAT TRANSFER PIPE VALVE AT THE NORTH WALL.	51 CHRYSOTILE ASBESTOS
141	1WTC-00141	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM WEST OF COLUMN 801.	51 CHRYSOTILE ASBESTOS
142	1WTC-00142	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM WEST OF COLUMN 701.	51 CHRYSOTILE ASBESTOS
143	1WTC-00143	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EAST OF COLUMN 701.	51 CHRYSOTILE ASBESTOS
144	1WTC-00144	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EAST OF COLUMN 701.	51 CHRYSOTILE ASBESTOS
145	1WTC-00145	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM SOUTH OF COLUMN 602.	51 CHRYSOTILE ASBESTOS
1382	1WTC-01382	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE VS-55-6 UNIT.	151 CHRYSOTILE ASBESTOS
1383	1WTC-01383	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE VS-55-6 UNIT.	201 CHRYSOTILE ASBESTOS
1384	1WTC-01384	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS-55-511 UNIT.	101 CHRYSOTILE ASBESTOS
1385	1WTC-01385	FLUFFY CONCRETE SLAB APPLICATION ABOVE ACS-55-511 UNIT.	751 CHRYSOTILE ASBESTOS
1386	1WTC-01386	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS-55-511 UNIT.	101 CHRYSOTILE ASBESTOS
1389	1WTC-01389	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS 55-55 UNIT.	151 CHRYSOTILE ASBESTOS
1390	1WTC-01390	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM ABOVE VS 5-5-5 UNIT.	101 CHRYSOTILE ASBESTOS
1391	1WTC-01391	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE VS 55-4 UNIT.	301 CHRYSOTILE ASBESTOS
1392	1WTC-01392	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE VS 55-4 UNIT.	201 CHRYSOTILE ASBESTOS
1394	1WTC-01394	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE VS-55-3 UNIT.	301 CHRYSOTILE ASBESTOS
1395	1WTC-01395	FLUFFY FALLOUT MATERIAL ON TOP OF UNIT ABOVE ACS 55-1 UNIT.	301 CHRYSOTILE ASBESTOS
1396	1WTC-01396	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS 55-1 UNIT.	201 CHRYSOTILE ASBESTOS
1397	1WTC-01397	FLUFFY INSULATION MATERIAL SPRAYED ON AN ENCAPSULATED BEAM ABOVE ACS 55-4 UNIT.	131 CHRYSOTILE ASBESTOS

PAG001345

ONE WORLD TRADE CENTER

FLOOR: 28

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1398	1WTC-01398	FLUFFY INSULATION MATERIAL SPRAYED ON AN ENCAPSULATED BEAM ABOVE AIR DUCT FROM ACR-35-57 UNIT.	100 CHRYSOTILE ASBESTOS
1399	1WTC-01399	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB ABOVE AIR DUCT FROM ACR-35-51 UNIT.	100 CHRYSOTILE ASBESTOS
1401	1WTC-01401	FLUFFY INSULATION MATERIAL SPRAYED ON AN ENCAPSULATED BEAM ABOVE VS-35-57 UNIT AT COLUMN 837.	100 CHRYSOTILE ASBESTOS
1402	1WTC-01402	FLUFFY INSULATION MATERIAL SPRAYED ON AN ENCAPSULATED BEAM ABOVE AIR DUCT FROM VS-35-7 UNIT.	100 CHRYSOTILE ASBESTOS
1403	1WTC-01403	FLUFFY INSULATION MATERIAL SPRAYED ON AN ENCAPSULATED BEAM ABOVE AIR DUCT FROM VS-35-7 UNIT.	100 CHRYSOTILE ASBESTOS
1404	1WTC-01404	FLUFFY INSULATION MATERIAL SPRAYED ON AN ENCAPSULATED BEAM ABOVE VS 5-5-8 UNIT.	100 CHRYSOTILE ASBESTOS
1405	1WTC-01405	FLUFFY FALLOUT INSULATION MATERIAL TAKEN FROM TOP OF VS 5-5-8 UNIT.	50 CHRYSOTILE ASBESTOS
1406	1WTC-01406	FLUFFY INSULATION MATERIAL SPRAYED ON AN ENCAPSULATED BEAM ABOVE DUCT FROM VS 5-5-8 UNIT.	100 CHRYSOTILE ASBESTOS
1408	1WTC-01408	FLUFFY INSULATION MATERIAL SPRAYED ON AN ENCAPSULATED BEAM ABOVE ROOF OVER PLENUM.	100 CHRYSOTILE ASBESTOS
1409	1WTC-01409	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE DUCT FROM VS-35-9 A, B, C UNIT.	100 CHRYSOTILE ASBESTOS
1410	1WTC-01410	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE VS3-5-9 A, B, C UNIT.	100 CHRYSOTILE ASBESTOS
1412	1WTC-01412	FLUFFY INSULATION MATERIAL SPRAYED ON AN ENCAPSULATED BEAM ABOVE VS 35-10 UNIT.	100 CHRYSOTILE ASBESTOS
1413	1WTC-01413	FLUFFY SPRAYED ON AND ENCAPSULATED BEAM INSULATION ABOVE DUCT FROM VS 35-11.	100 CHRYSOTILE ASBESTOS
1414	1WTC-01414	FLUFFY INSULATION MATERIAL SPRAYED ON AN ENCAPSULATED BEAM ABOVE EXIT OF STAIR E-3.	200 CHRYSOTILE ASBESTOS
1428	1WTC-01428	FLUFFY PRE-MOLDED HEAT TRANSFER PIPE INSULATION FALLOUT ON THE ROOF OF THE AIR TRANSFER PLENUM.	100 AMOSITE ASBESTOS
1429	1WTC-01429	FLUFFY CEMENTITIOUS PRE-MOLDED HEAT TRANSFER PIPE INSULATION FALLOUT ON THE ROOF OF THE AIR TRANSFER PLENUM.	250 AMOSITE ASBESTOS 30 CHRYSOTILE ASBESTOS
1430	1WTC-01430	FLUFFY PRE-MOLDED HEAT TRANSFER PIPE INSULATION FALLOUT ON THE ROOF OF THE AIR TRANSFER PLENUM.	100 AMOSITE ASBESTOS

PA5001346

ONE WORLD TRADE CENTER  
FLOOR: 54

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1063	1WTC-04063	CLOTH GASKET MATERIAL ON HATCH OF ACS-55-3 FAN UNIT.	90% CHRYSOTILE ASBESTOS
1067	1WTC-04067	CLOTH GASKET MATERIAL OF HATCH OF ACS 55-1 FAN UNIT. (17)	90% CHRYSOTILE ASBESTOS
1917	1WTC-04937	FLUFFY PREFORMED PAD INSULATION MATERIAL FROM A 10" O.D. HEAT TRANSFER PIPE AT ACS-55-2 UNIT.	40% AMOSITE ASBESTOS 10% CHRYSOTILE ASBESTOS

PAG0001347

ONE WORLD TRADE CENTER

FLOOR: 1

<u>AREA</u> <u>NO-352</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
964	1WTC-00964	FLUFFY PRE-MOLDED INSULATION MATERIAL FROM A HEAT TRANSFER PIPE LOCATED IN THE SLOP SINK CLOSET.	40% CHRYSOTILE ASBESTOS
965	1WTC-00965	FLUFFY PRE-MOLDED INSULATION MATERIAL FROM A HEAT TRANSFER PIPE LOCATED IN THE SLOP SINK CLOSET.	40% CHRYSOTILE ASBESTOS
4342	1WTC-04342	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM WEST OF THE CATWALK ENTRANCE IN THE CRAWLSPACE UNDER THE FOUNTAIN.	32 CHRYSOTILE ASBESTOS



ONE WORLD TRADE CENTER

FLOOR: 3

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1131	1WTC-01131	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE NORTHWEST CRAWL SPACE OF ACCESS HATCH.	20% CHRYSOTILE ASBESTOS
1134	1WTC-01134	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE NORTHWEST CRAWL SPACE OF THE ACCESS HATCH.	30% CHRYSOTILE ASBESTOS
1435	1WTC-01435	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE SOUTHWEST CRAWL SPACE OF THE ACCESS HATCH.	10% CHRYSOTILE ASBESTOS
1436	1WTC-01436	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB IN THE SOUTHWEST CRAWL SPACE OF ACCESS HATCH.	30% CHRYSOTILE ASBESTOS
1437	1WTC-01437	FLUFFY INSULATION MATERIAL SPRAYED ON THE EXTERIOR COLUMN EXPOSED IN THE SOUTH PLAZA AREA.	10% CHRYSOTILE ASBESTOS
10887	1WTC-10887	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB IN THE PLENUM OF THE WEST CORE CORRIDOR.	30% CHRYSOTILE ASBESTOS
10888	1WTC-10888	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB IN THE PLENUM OF THE WEST CORE CORRIDOR.	25% CHRYSOTILE ASBESTOS
10889	1WTC-10889	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WEST CORE CORRIDOR.	25% CHRYSOTILE ASBESTOS
10870	1WTC-10870	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WEST CORE CORRIDOR.	5% CHRYSOTILE ASBESTOS
10871	1WTC-10871	FLUFFY SPRAYED ON BEAM INSULATION MATERIAL IN THE PLENUM OF WEST CORRIDOR.	40% CHRYSOTILE ASBESTOS
10872	1WTC-10872	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE ELEVATOR LOBBY.	35% CHRYSOTILE ASBESTOS
10873	1WTC-10873	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE ELEVATOR LOBBY.	50% CHRYSOTILE ASBESTOS
10874	1WTC-10874	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE EAST CORE CORRIDOR.	25% CHRYSOTILE ASBESTOS
10875	1WTC-10875	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE ELEVATOR LOBBY.	20% CHRYSOTILE ASBESTOS
10876	1WTC-10876	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE EAST CORE CORRIDOR.	40% CHRYSOTILE ASBESTOS
10877	1WTC-10877	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE EAST STAIR VESTIBULE.	80% CHRYSOTILE ASBESTOS
13243	1WTC-13243	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE STORAGE AND ELECTRICAL CLOSET IN THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS

PAG001349

ONE WORLD TRADE CENTER  
FLOOR: 3

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
10878	1WTC-10878	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF ELEVATOR LOBBY.	30% CHRYSOTILE ASBESTOS
10879	1WTC-10879	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE ELEVATOR LOBBY.	60% CHRYSOTILE ASBESTOS
10880	1WTC-10880	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE EAST CORE CORRIDOR.	60% CHRYSOTILE ASBESTOS
10881	1WTC-10881	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB IN THE PLENUM OF THE MENS LOCKER ROOM.	40% CHRYSOTILE ASBESTOS
10882	1WTC-10882	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE MENS LOCKER ROOM.	30% CHRYSOTILE ASBESTOS
10883	1WTC-10883	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF CORRIDOR AT SINK CLOSET.	40% CHRYSOTILE ASBESTOS
10884	1WTC-10884	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTH CORE CORRIDOR.	35% CHRYSOTILE ASBESTOS
10885	1WTC-10885	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE ELEVATOR LOBBY.	30% CHRYSOTILE ASBESTOS
10886	1WTC-10886	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WEST CORE CORRIDOR.	40% CHRYSOTILE ASBESTOS
10887	1WTC-10887	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WOMENS LOCKER ROOM 2.	40% CHRYSOTILE ASBESTOS
10888	1WTC-10888	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WOMENS LOCKER ROOM 2.	40% CHRYSOTILE ASBESTOS
10889	1WTC-10889	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WOMENS LOCKER ROOM 1.	40% CHRYSOTILE ASBESTOS
10890	1WTC-10890	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WOMENS LOCKER ROOM 2.	35% CHRYSOTILE ASBESTOS
10891	1WTC-10891	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WEST CORE CORRIDOR.	30% CHRYSOTILE ASBESTOS
10892	1WTC-10892	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WOMENS LOCKER ROOM.	40% CHRYSOTILE ASBESTOS

PAG001350

ONE WORLD TRADE CENTER  
FLOOR: 4

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
10893	1WTC-10893	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTH CORE CORRIDOR.	30% CHRYSOTILE ASBESTOS
10894	1WTC-10894	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE ELEVATOR LOBBY.	33% CHRYSOTILE ASBESTOS
10895	1WTC-10895	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WOMEN'S LOCKER ROOM 2.	43% CHRYSOTILE ASBESTOS
10897	1WTC-10897	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WEST CORE CORRIDOR.	25% CHRYSOTILE ASBESTOS
10898	1WTC-10898	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE ELEVATOR LOBBY.	83% CHRYSOTILE ASBESTOS
10899	1WTC-10899	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE STORAGE ROOM.	40% CHRYSOTILE ASBESTOS
10900	1WTC-10900	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE STORAGE ROOM.	25% CHRYSOTILE ASBESTOS
10901	1WTC-10901	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WOMEN'S LOCKER ROOM 1.	33% CHRYSOTILE ASBESTOS
10903	1WTC-10903	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB IN THE PLENUM OF THE EAST CORE CORRIDOR.	30% CHRYSOTILE ASBESTOS
10904	1WTC-10904	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE MEN'S LOCKER ROOM 1.	33% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR 5

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
11:15	1WTC-11:15	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE CENTRAL CORE AREA IN FRONT OF TELEPHONE CLOSET 5.	35% CHRYSOTILE ASBESTOS
11:16	1WTC-11:16	INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST QUADRANT BETWEEN PASSENGER ELEVATORS #32-33.	40% CHRYSOTILE ASBESTOS
11:17	1WTC-11:17	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST QUADRANT BETWEEN PASSENGER ELEVATORS #30-35.	45% CHRYSOTILE ASBESTOS
11:18	1WTC-11:18	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT BETWEEN PASSENGER ELEVATORS #26-27.	30% CHRYSOTILE ASBESTOS
11:19	1WTC-11:19	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE MEN'S ROOM IN THE SOUTHEAST QUADRANT.	50% CHRYSOTILE ASBESTOS
11:20	1WTC-11:20	FLUFFY INSULATION MATERIAL IN THE PLENUM OF ROOF 3 CONSTRUCTION IN THE ELEVATORS AT THE CORE CORRIDOR INTERSECTION.	40% CHRYSOTILE ASBESTOS
11:22	1WTC-11:22	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM IN THE NORTHWEST QUADRANT BETWEEN PASSENGER ELEVATORS #41-46.	30% CHRYSOTILE ASBESTOS
11:23	1WTC-11:23	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM AT THE END OF THE WEST CORE CORRIDOR.	35% CHRYSOTILE ASBESTOS
11:24	1WTC-11:24	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT BETWEEN PASSENGER ELEVATORS #36-39.	20% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 4

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1	1WTC-001CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER NORTHEAST 13	31 CHRYSOTILE ASBESTOS
2	1WTC-002CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER NORTHEAST 14.	31 CHRYSOTILE ASBESTOS
3	1WTC-003CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER NORTHEAST 8.	31 CHRYSOTILE ASBESTOS
4	1WTC-004CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER NORTHEAST 3.	31 CHRYSOTILE ASBESTOS
5	1WTC-005CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER NORTHEAST 1.	31 CHRYSOTILE ASBESTOS
6	1WTC-006CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER NORTHWEST 6.	31 CHRYSOTILE ASBESTOS
7	1WTC-007CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER NORTHWEST 3.	31 CHRYSOTILE ASBESTOS
8	1WTC-008CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER SOUTHWEST 3.	101 CHRYSOTILE ASBESTOS
10	1WTC-010CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER SOUTHWEST 12.	101 CHRYSOTILE ASBESTOS
11	1WTC-011CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER SOUTHWEST 13.	31 CHRYSOTILE ASBESTOS
12	1WTC-012CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER SOUTHEAST 12.	31 CHRYSOTILE ASBESTOS
13	1WTC-013CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER SOUTHEAST 14.	31 CHRYSOTILE ASBESTOS
14	1WTC-014CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER SOUTHEAST 9.	31 CHRYSOTILE ASBESTOS
15	1WTC-015CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER NORTHEAST 10.	101 CHRYSOTILE ASBESTOS
16	1WTC-016CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER NORTHEAST 7.	31 CHRYSOTILE ASBESTOS
17	1WTC-017CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER NORTHWEST 12.	101 CHRYSOTILE ASBESTOS
18	1WTC-018CS	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDELIER NORTHWEST 12.	101 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 6

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
20	1WTC-022005	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDLER SW 7.	5% CHRYSOTILE ASBESTOS
21	1WTC-022105	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDLER SW 10.	10% CHRYSOTILE ASBESTOS
22	1WTC-022205	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDLER SE 3.	5% CHRYSOTILE ASBESTOS
23	1WTC-022305	FLUFFY INSULATION MATERIAL SPRAYED ON CEILING OVER CHANDLER SE 8.	20% CHRYSOTILE ASBESTOS
11402	1WTC-11402	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE CORE CORRIDOR INTERSECTION.	10% CHRYSOTILE ASBESTOS
11406	1WTC-11406	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE STAIR NUMBER 1 VESTIBULE AT THE END OF THE WEST CORE CORRIDOR.	15% CHRYSOTILE ASBESTOS
11408	1WTC-11408	FLUFFY INSULATION MATERIAL SPRAYED ON A PIPE IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
11409	1WTC-11409	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE STAIR NUMBER 1 VESTIBULE AT THE END OF THE EAST CORE CORRIDOR.	15% CHRYSOTILE ASBESTOS
11411	1WTC-11411	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM BETWEEN PASSENGER ELEVATOR NUMBER 32 AND 33 IN THE NORTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
11413	1WTC-11413	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE EASTERN CLOSET ALONG THE NORTH CORE CORRIDOR.	10% CHRYSOTILE ASBESTOS TRACE AMOUNTS ASBESTOS

## ONE WORLD TRADE CENTER

FLOOR: 7

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
349	1WTC-00549	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN IN THE SOUTHWEST RETURN AIR PLENUM.	10% CHRYSOTILE ASBESTOS
350	1WTC-00550	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN IN THE NORTHWEST RETURN AIR PLENUM.	20% CHRYSOTILE ASBESTOS
351	1WTC-00551	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN IN THE NORTHWEST RETURN AIR PLENUM.	20% CHRYSOTILE ASBESTOS
352	1WTC-00552	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN IN THE NORTHWEST RETURN AIR PLENUM.	20% CHRYSOTILE ASBESTOS
361	1WTC-00561	CONDITIONOUS INSULATION MATERIAL SPRAYED ON A WALL IN THE NORTHWEST RETURN AIR PLENUM.	10% CHRYSOTILE ASBESTOS
373	1WTC-00573	CONDITIONOUS INSULATION MATERIAL TROWELED ON A COLUMN IN THE SOUTHWEST RETURN AIR PLENUM.	15% CHRYSOTILE ASBESTOS
374	1WTC-00574	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN IN THE SOUTHWEST RETURN AIR PLENUM.	25% CHRYSOTILE ASBESTOS
375	1WTC-00575	FLUFFY INSULATION MATERIAL TROWELED ON A COLUMN IN THE SOUTHWEST RETURN AIR PLENUM.	1% CHRYSOTILE ASBESTOS
375	1WTC-00576	CONDITIONOUS INSULATION MATERIAL TROWELED ON A COLUMN IN THE SOUTHWEST RETURN AIR PLENUM.	3% CHRYSOTILE ASBESTOS
375	1WTC-00579	FLUFFY INSULATION MATERIAL TROWELED ON A COLUMN IN THE SOUTHWEST RETURN AIR PLENUM NEAR SAMPLE #375.	NOM ASBESTOS
376	1WTC-00576	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN IN THE SOUTHWEST RETURN AIR PLENUM.	15% CHRYSOTILE ASBESTOS
378	1WTC-00578	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.8 UNIT.	20% CHRYSOTILE ASBESTOS
379	1WTC-00579	CONDITIONOUS INSULATION MATERIAL TROWELED ON A BEAM ABOVE THE SOUTH ELECTRICAL SUB-STATION.	15% CHRYSOTILE ASBESTOS
380	1WTC-00580	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE SOUTH ELECTRICAL SUB-STATION.	15% CHRYSOTILE ASBESTOS 1% AMOSITE ASBESTOS
381	1WTC-00581	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE SOUTH ELECTRICAL SUB-STATION.	20% CHRYSOTILE ASBESTOS
382	1WTC-00582	FLUFFY FALLOUT MATERIAL FROM THE TOP OF THE DUCT ABOVE THE ACS 7.8 UNIT.	25% CHRYSOTILE ASBESTOS
390	1WTC-00590	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN IN THE SOUTHEAST CORNER OF THE MECHANICAL EQUIPMENT ROOM.	80% CHRYSOTILE ASBESTOS

PAT001355

ONE WORLD TRADE CENTER  
FLOOR: 7

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
602	1WTC-02602	FLUFFY FALLOUT MATERIAL ON THE FLOOR AT THE E-7-10 UNIT.	30% CHRYSOTILE ASBESTOS
603	1WTC-00603	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE NORTH ELECTRICAL SUB-STATION.	40% CHRYSOTILE ASBESTOS
604	1WTC-00604	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE NORTH ELECTRICAL SUB-STATION.	20% CHRYSOTILE ASBESTOS
605	1WTC-00605	CEMENTITIOUS INSULATION MATERIAL FROM A 12" O.D. HEAT TRANSFER PIPE LOCATED IN THE NORTHEAST RETURN AIR PLENUM.	30% AMOSITE ASBESTOS 10% CHRYSOTILE ASBESTOS
606	1WTC-00606	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN IN THE NORTHEAST RETURN AIR PLENUM.	10% CHRYSOTILE ASBESTOS
607	1WTC-00607	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN IN THE SOUTHEAST RETURN AIR PLENUM.	20% CHRYSOTILE ASBESTOS
609	1WTC-00609	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN IN FRONT OF THE SOUTHEAST FAN IN THE SOUTHEAST AIR PLENUM.	20% CHRYSOTILE ASBESTOS
2398	1WTC-02398	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE NORTHWEST RETURN AIR PLENUM.	40% CHRYSOTILE ASBESTOS
2399	1WTC-02399	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE NORTHWEST RETURN AIR PLENUM.	40% CHRYSOTILE ASBESTOS 13% AMOSITE ASBESTOS
2402	1WTC-02402	CEMENTITIOUS INSULATION MATERIAL FROM A HEAT TRANSFER PIPE COUPLING LOCATED IN THE NORTHWEST RETURN AIR PLENUM.	20% AMOSITE ASBESTOS 5% CHRYSOTILE ASBESTOS
2404	1WTC-02404	CEMENTITIOUS INSULATION MATERIAL FROM A HEAT TRANSFER PIPE ELBOW LOCATED IN THE NORTHWEST RETURN AIR PLENUM.	40% AMOSITE ASBESTOS 10% CHRYSOTILE ASBESTOS
2405	1WTC-02405	CEMENTITIOUS INSULATION MATERIAL FROM A HEAT TRANSFER PIPE ELBOW LOCATED IN THE NORTHWEST RETURN AIR PLENUM.	40% AMOSITE ASBESTOS 40% CHRYSOTILE ASBESTOS
2406	1WTC-02406	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE NORTHWEST RETURN AIR PLENUM.	20% CHRYSOTILE ASBESTOS
2407	1WTC-02407	CEMENTITIOUS INSULATION MATERIAL FLOWED ON A BEAM IN THE NORTHWEST RETURN AIR PLENUM.	10% CHRYSOTILE ASBESTOS
2408	1WTC-02408	FLUFFY INSULATION MATERIAL FROM HEAT TRANSFER PIPE LOCATED IN THE NORTHWEST RETURN AIR PLENUM.	30% AMOSITE ASBESTOS
4329	1WTC-04329	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.11 UNIT.	20% CHRYSOTILE ASBESTOS
4330	1WTC-04330	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.12 UNIT.	20% CHRYSOTILE ASBESTOS
4331	1WTC-04331	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.13 UNIT.	30% CHRYSOTILE ASBESTOS



ONE WORLD TRADE CENTER  
FLOOR: 7

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
4332	1WTC-04332	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS-7-1 UNIT.	10% CHRYSOTILE ASBESTOS
4333	1WTC-04333	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS-7-14 UNIT.	10% CHRYSOTILE ASBESTOS
4335	1WTC-04335	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM THE ABOVE ACS-7-3 UNIT.	10% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 9

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1150	1WTC-01150	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	52 CHRYSOTILE ASBESTOS
1156	1WTC-01156	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT.	52 CHRYSOTILE ASBESTOS
1159	1WTC-01159	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	201 CHRYSOTILE ASBESTOS
1160	1WTC-01160	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	201 CHRYSOTILE ASBESTOS
1161	1WTC-01161	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	52 CHRYSOTILE ASBESTOS
1183	1WTC-01183	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST EXPOSED WITHIN THE PLENUM.	102 CHRYSOTILE ASBESTOS
13658	1WTC-13658	CEMENTITIOUS INSULATION MATERIAL TROVELED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	401 CHRYSOTILE ASBESTOS

PAG001358

ONE WORLD TRADE CENTER  
FLOOR: 10

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
431	1WTC-00431	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
433	1WTC-00433	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
434	1WTC-00434	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
435	1WTC-00435	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	5% CHRYSOTILE ASBESTOS
436	1WTC-00436	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
437	1WTC-00437	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
438	1WTC-00438	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
439	1WTC-00439	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
440	1WTC-00440	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
441	1WTC-00441	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	5% CHRYSOTILE ASBESTOS
442	1WTC-00442	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
443	1WTC-00443	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	5% CHRYSOTILE ASBESTOS
444	1WTC-00444	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
445	1WTC-00445	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	5% CHRYSOTILE ASBESTOS
446	1WTC-00446	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
447	1WTC-00447	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	5% CHRYSOTILE ASBESTOS
448	1WTC-00448	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS

PA0001359

ONE WORLD TRADE CENTER  
FLOOR 10

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
149	1WTC-10419	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
150	1WTC-10430	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
13633	1WTC-11633	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	25% CHRYSOTILE ASBESTOS
13634	1WTC-11634	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	40% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 11

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
431	1WTC-00431	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
433	1WTC-00433	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	31 CHRYSOTILE ASBESTOS
435	1WTC-00435	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM.	20% CHRYSOTILE ASBESTOS
437	1WTC-00437	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	31 CHRYSOTILE ASBESTOS
438	1WTC-00438	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	31 CHRYSOTILE ASBESTOS
439	1WTC-00439	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
440	1WTC-00440	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM.	10% CHRYSOTILE ASBESTOS
441	1WTC-00441	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM.	31 CHRYSOTILE ASBESTOS
442	1WTC-00442	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM.	31 CHRYSOTILE ASBESTOS
444	1WTC-00444	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
447	1WTC-00447	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM.	31 CHRYSOTILE ASBESTOS
448	1WTC-00448	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM.	10% CHRYSOTILE ASBESTOS
449	1WTC-00449	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM.	31 CHRYSOTILE ASBESTOS
15841	1WTC-15841	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE THE NORTHEAST TELEPHONE CLOSET.	33% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 12

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULTS
1160	1WTC-01160	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
1170	1WTC-01170	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
1171	1WTC-01171	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1172	1WTC-01172	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
1174	1WTC-01174	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1175	1WTC-01175	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	5% CHRYSOTILE ASBESTOS
1176	1WTC-01176	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1177	1WTC-01177	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
1178	1WTC-01178	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1179	1WTC-01179	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	5% CHRYSOTILE ASBESTOS
1180	1WTC-01180	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1181	1WTC-01181	FLOOR TILE SAMPLE TAKEN FROM DEMOLISHED AREA OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
1182	1WTC-1182	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	10% CHRYSOTILE ASBESTOS
1183	1WTC-1183	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	10% CHRYSOTILE ASBESTOS

PAG001362

ONE WORLD TRADE CENTER  
FLOOR: 13

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
11314	1WTC-11314	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE CORE AREA CORRIDOR OPPOSITE THE PASSENGER ELEVATOR.	10 CHRYSOPILE ASBESTOS
11316	1WTC-11316	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE CORE CORRIDOR INTERSECTION.	100 CHRYSOPILE ASBESTOS
11317	1WTC-11317	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE CORRIDOR AT THE LADIES ROOM ENTRANCE.	200 CHRYSOPILE ASBESTOS
11318	1WTC-11318	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOPILE ASBESTOS
11319	1WTC-11319	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	200 CHRYSOPILE ASBESTOS
11320	1WTC-11320	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	400 CHRYSOPILE ASBESTOS
11323	1WTC-11323	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	300 CHRYSOPILE ASBESTOS
11324	1WTC-11324	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	200 CHRYSOPILE ASBESTOS
11325	1WTC-11325	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	600 CHRYSOPILE ASBESTOS TRACE AMOSITE ASBESTOS
11326	1WTC-11326	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOPILE ASBESTOS
11327	1WTC-11327	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOPILE ASBESTOS TRACE AMOSITE ASBESTOS
11328	1WTC-11328	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	00 CHRYSOPILE ASBESTOS
11329	1WTC-11329	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOPILE ASBESTOS
11330	1WTC-11330	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOPILE ASBESTOS
11331	1WTC-11331	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	600 CHRYSOPILE ASBESTOS
11332	1WTC-11332	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOPILE ASBESTOS
11334	1WTC-11334	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	600 CHRYSOPILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 13

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
11335	1WTC-11335	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	11% CHRYSOTILE ASBESTOS
11336	1WTC-11336	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
11337	1WTC-11337	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
11338	1WTC-11338	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
11339	1WTC-11339	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	13% CHRYSOTILE ASBESTOS
11340	1WTC-11340	FLUFFY INSULATION MATERIAL SPRAYED ON THE RETAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
11341	1WTC-11341	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	5% CHRYSOTILE ASBESTOS
11342	1WTC-11342	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	1-11% CHRYSOTILE ASBESTOS
11343	1WTC-11343	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	13% CHRYSOTILE ASBESTOS
11344	1WTC-11344	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	50% CHRYSOTILE ASBESTOS
11345	1WTC-11345	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	50% CHRYSOTILE ASBESTOS
11347	1WTC-11347	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE WEST WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	1-31% CHRYSOTILE ASBESTOS
11350	1WTC-11350	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	1% CHRYSOTILE ASBESTOS
11353	1WTC-11353	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	20% CHRYSOTILE ASBESTOS
11354	1WTC-11354	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	22% CHRYSOTILE ASBESTOS

PA0001364



ONE WORLD TRADE CENTER  
FLOOR: 14

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1233	1WTC-01081	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	20: CHRYSOTILE ASBESTOS
1234	1WTC-01086	CONDENSATION INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT.	15: CHRYSOTILE ASBESTOS
1287	1WTC-01087	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	31: CHRYSOTILE ASBESTOS
1288	1WTC-01088	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	15: CHRYSOTILE ASBESTOS
1289	1WTC-01089	FLUFFY FILLOUT MATERIAL IN THE PLENUM OF THE SOUTHEAST QUADRANT.	31: CHRYSOTILE ASBESTOS
1290	1WTC-01090	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	40: CHRYSOTILE ASBESTOS
1291	1WTC-01091	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK OF THE SOUTHEAST QUADRANT.	20: CHRYSOTILE ASBESTOS
1292	1WTC-01092	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	20: CHRYSOTILE ASBESTOS
1293	1WTC-01093	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	15: CHRYSOTILE ASBESTOS
1294	1WTC-01094	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	31: CHRYSOTILE ASBESTOS
1295	1WTC-01095	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	31: CHRYSOTILE ASBESTOS
1296	1WTC-01096	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20: CHRYSOTILE ASBESTOS
1298	1WTC-01098	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	40: CHRYSOTILE ASBESTOS
12631	1WTC-12631	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	30: CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 15

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1070	1WTC-01070	IDENTIFIABLE INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE WEST WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	31 CHRYSOTILE ASBESTOS
1072	1WTC-01072	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM IN THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1073	1WTC-01073	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM IN THE SOUTHWEST QUADRANT.	201 CHRYSOTILE ASBESTOS
1076	1WTC-01076	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM IN THE SOUTHWEST QUADRANT.	201 CHRYSOTILE ASBESTOS
1077	1WTC-01077	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM IN THE SOUTHWEST QUADRANT.	201 CHRYSOTILE ASBESTOS
1078	1WTC-01078	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1080	1WTC-01080	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1081	1WTC-01081	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	201 CHRYSOTILE ASBESTOS
1082	1WTC-01082	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	31 CHRYSOTILE ASBESTOS
1084	1WTC-01084	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1089	1WTC-1089	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	201 CHRYSOTILE ASBESTOS
1090	1WTC-1090	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	131 CHRYSOTILE ASBESTOS

PAG001366

ONE WORLD TRADE CENTER  
FLOOR 14

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
912	1WTC-00912	FLUFFY FALLOUT MATERIAL IN THE PLENUM OF THE SOUTHEAST QUADRANT	10% CHRYSOTILE ASBESTOS
913	1WTC-00913	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
914	1WTC-00914	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS 5% AMOSITE ASBESTOS
915	1WTC-00915	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	5% CHRYSOTILE ASBESTOS
916	1WTC-00916	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
917	1WTC-00917	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
918	1WTC-00918	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
919	1WTC-00919	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
920	1WTC-00920	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
922	1WTC-00922	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
923	1WTC-00923	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
924	1WTC-00924	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
13639	1WTC-13639	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	30% CHRYSOTILE ASBESTOS
13640	1WTC-13640	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	20% CHRYSOTILE ASBESTOS
14900	1WTC-14900	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTH CORE CORRIDOR.	30% CHRYSOTILE ASBESTOS
14913	1WTC-14913	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
14914	1WTC-14914	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS

PAG001367

ONE WORLD TRADE CENTER  
FLOOR: 16

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14917	1WTC-14917	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	33% CHRYSOTILE ASBESTOS
14918	1WTC-14918	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	25% CHRYSOTILE ASBESTOS TRACE AMOSITE ASBESTOS
14919	1WTC-14919	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	33% CHRYSOTILE ASBESTOS
14920	1WTC-14920	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	33% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 17

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
11425	1WTC-11425	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE EAST CORE CORRIDOR OUTSIDE OF THE ELEVATOR LOBBY.	701 CHRYSOTILE ASBESTOS
11427	1WTC-11427	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE CORE CORRIDORS INTERSECTION.	401 CHRYSOTILE ASBESTOS
11430	1WTC-11430	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	401 CHRYSOTILE ASBESTOS
11433	1WTC-11433	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	401 CHRYSOTILE ASBESTOS
11434	1WTC-11434	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	501 CHRYSOTILE ASBESTOS
11435	1WTC-11435	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	301 CHRYSOTILE ASBESTOS
11436	1WTC-11436	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	301 CHRYSOTILE ASBESTOS
11437	1WTC-11437	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	301 CHRYSOTILE ASBESTOS
11441	1WTC-11441	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	501 CHRYSOTILE ASBESTOS
11442	1WTC-11442	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	401 CHRYSOTILE ASBESTOS
11443	1WTC-11443	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	301 CHRYSOTILE ASBESTOS
11444	1WTC-11444	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
11445	1WTC-11445	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	301 CHRYSOTILE ASBESTOS
11446	1WTC-11446	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	301 CHRYSOTILE ASBESTOS
11447	1WTC-11447	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	301 CHRYSOTILE ASBESTOS
11448	1WTC-11448	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	301 CHRYSOTILE ASBESTOS
11449	1WTC-11449	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 17

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
11-30	1WTC-11430	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	35% CHRYSOTILE ASBESTOS
11431	1WTC-11431	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	33% CHRYSOTILE ASBESTOS
11432	1WTC-11432	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
11433	1WTC-11433	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	60% CHRYSOTILE ASBESTOS
11434	1WTC-11434	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	50% CHRYSOTILE ASBESTOS
11437	1WTC-11437	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	43% CHRYSOTILE ASBESTOS
13441	1WTC-13441	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED IN THE NORTHEAST TELEPHONE CLOSET.	23% CHRYSOTILE ASBESTOS

PA0001370

ONE WORLD TRADE CENTER  
FLOOR: 14

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULTS
1030	1WTC-01030	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
1031	1WTC-01031	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
1034	1WTC-01034	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	75% CHRYSOTILE ASBESTOS
1036	1WTC-01036	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1037	1WTC-01037	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
1040	1WTC-01040	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
1042	1WTC-01042	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
1043	1WTC-01043	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1044	1WTC-01044	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
1045	1WTC-01045	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
1046	1WTC-01046	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
1047	1WTC-01047	INTERLOCKING CEILING TILE SAMPLE IN THE SOUTHEAST QUADRANT.	3% CHRYSOTILE ASBESTOS
1048	1WTC-01048	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH-WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	3% CHRYSOTILE ASBESTOS
1049	1WTC-01049	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTH-EAST TELEPHONE CLOSET.	3% CHRYSOTILE ASBESTOS
14921	1WTC-14921	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTH CORE CORRIDOR.	33% CHRYSOTILE ASBESTOS
14922	1WTC-14922	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE EAST CORE CORRIDOR.	33% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 19

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
10917	1WTC-10917	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	33% CHRYSOTILE ASBESTOS
10918	1WTC-10918	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	33% CHRYSOTILE ASBESTOS
10919	1WTC-10919	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT, OFFICE AREA.	1-11% CHRYSOTILE ASBESTOS
10920	1WTC-10920	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	33% CHRYSOTILE ASBESTOS
10921	1WTC-10921	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	43% CHRYSOTILE ASBESTOS
10922	1WTC-10922	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
10923	1WTC-10923	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	25% CHRYSOTILE ASBESTOS
10925	1WTC-10925	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	43% CHRYSOTILE ASBESTOS
10926	1WTC-10926	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
10927	1WTC-10927	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
10928	1WTC-10928	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
10929	1WTC-10929	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	33% CHRYSOTILE ASBESTOS
10930	1WTC-10930	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	23% CHRYSOTILE ASBESTOS
10931	1WTC-10931	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	25% CHRYSOTILE ASBESTOS
10932	1WTC-10932	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
10933	1WTC-10933	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
10934	1WTC-10934	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS



## ONE WORLD TRADE CENTER

FLOOR: 19

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
10935	1WTC-10935	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	35% CHRYSOTILE ASBESTOS
10936	1WTC-10936	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	35% CHRYSOTILE ASBESTOS
10937	1WTC-10937	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
10938	1WTC-10938	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	35% CHRYSOTILE ASBESTOS
10939	1WTC-10939	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
10940	1WTC-10940	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE EAST CORE CORRIDOR NEAR THE CLOSET.	10% CHRYSOTILE ASBESTOS
10941	1WTC-10941	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WEST CORE CORRIDOR NEAR THE CLOSET.	30% CHRYSOTILE ASBESTOS
10942	1WTC-10942	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTH CORE CORRIDOR.	25% CHRYSOTILE ASBESTOS
10943	1WTC-10943	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTH CORE CORRIDOR.	25% CHRYSOTILE ASBESTOS
10944	1WTC-10944	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	45% CHRYSOTILE ASBESTOS
10945	1WTC-10945	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
10946	1WTC-10946	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
10947	1WTC-10947	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	50% CHRYSOTILE ASBESTOS
10948	1WTC-10948	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	45% CHRYSOTILE ASBESTOS
13445	1WTC-13445	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED IN THE NORTHEAST TELEPHONE CLOSET.	20% CHRYSOTILE ASBESTOS
13458	1WTC-13458	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED IN THE NORTHEAST TELEPHONE CLOSET.	25% CHRYSOTILE ASBESTOS

PAGE 001373

ONE WORLD TRADE CENTER  
FLOOR: 20

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1033	1WTC-01033	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
1034	1WTC-01034	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1035	1WTC-01035	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1039	1WTC-01039	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
1040	1WTC-01040	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
1041	1WTC-01041	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
1042	1WTC-01042	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1043	1WTC-01043	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
1049	1WTC-01049	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS

CWE WORLD TRADE CENTER  
FLOOR: 21

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
890	1WTC-30890	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
892	1WTC-30892	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
894	1WTC-30894	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
897	1WTC-30897	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
898	1WTC-30898	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
899	1WTC-30899	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
900	1WTC-00900	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
901	1WTC-00901	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
904	1WTC-00904	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
906	1WTC-00906	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
907	1WTC-00907	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
908	1WTC-00908	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
910	1WTC-00910	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
13847	1WTC-13847	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	101 CHRYSOTILE ASBESTOS
13848	1WTC-13848	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	101 CHRYSOTILE ASBESTOS
14903	1WTC-14903	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
14908	1WTC-14908	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR 2:

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1-907	1WTC-14907	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	33% CHRYSOTILE ASBESTOS
1-908	1WTC-14908	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	33% CHRYSOTILE ASBESTOS
1-909	1WTC-14909	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	25% CHRYSOTILE ASBESTOS
1-910	1WTC-14910	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	23% CHRYSOTILE ASBESTOS
1-911	1WTC-14911	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE EAST CORE CORRIDOR.	23% CHRYSOTILE ASBESTOS
1-912	1WTC-14912	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTH CORE CORRIDOR.	33% CHRYSOTILE ASBESTOS
1-913	1WTC-14913	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WEST CORE CORRIDOR.	33% CHRYSOTILE ASBESTOS
1-914	1WTC-14914	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTH CORE CORRIDOR.	13% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 11

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1100	1WTC-01100	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
1201	1WTC-01201	FLUFFY FALLOUT MATERIAL IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
1204	1WTC-01204	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
1206	1WTC-01206	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
1207	1WTC-01207	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
1208	1WTC-01208	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
1209	1WTC-01209	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
1210	1WTC-01210	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
1211	1WTC-01211	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
1214	1WTC-01214	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
1215	1WTC-01215	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
1464	1WTC-0464	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
1465	1WTC-0465	FLUFFY FALLOUT MATERIAL IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
1467	1WTC-0467	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
1470	1WTC-0470	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
1471	1WTC-0471	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
1472	1WTC-0472	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS

PAG0001377

ONE WORLD TRADE CENTER  
FLOOR: 12

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1474	1WTC-04474	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
1475	1WTC-04475	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
1479	1WTC-04479	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
1480	1WTC-04480	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	80% CHRYSOTILE ASBESTOS
1481	1WTC-04481	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1482	1WTC-04482	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
1483	1WTC-04483	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
1485	1WTC-04485	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
1486	1WTC-04486	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
1487	1WTC-04487	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	32 CHRYSOTILE ASBESTOS 18 AMOSITE ASBESTOS
11449	1WTC-11449	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTHEAST TELEPHONE CLOSET.	40% CHRYSOTILE ASBESTOS
11450	1WTC-11450	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTHEAST TELEPHONE CLOSET.	20% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 23

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1184	1WTC-01184	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
1185	1WTC-01185	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
1187	1WTC-01187	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
1188	1WTC-01188	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1189	1WTC-01189	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	3% CHRYSOTILE ASBESTOS
1191	1WTC-01191	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
1193	1WTC-01193	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1194	1WTC-01194	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
1195	1WTC-01195	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
1196	1WTC-01196	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
1199	1WTC-01199	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
7804	1WTC-07804	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	40% CHRYSOTILE ASBESTOS
7808	1WTC-07808	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB EXPOSED WITHIN THE SOUTHWEST TELEPHONE CLOSET.	70% CHRYSOTILE ASBESTOS
13432	1WTC-13432	CONDENSATION INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	10% CHRYSOTILE ASBESTOS

PAG001379

ONE WORLD TRADE CENTER

FLOOR: 2A

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
7796	1WTC-07796	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	80% CHRYSOTILE ASBESTOS
7799	1WTC-07799	CONVENTIONAL INSULATION MATERIAL REMOVED ON A BEAM EXPOSED WITHIN THE NORTHWEST TELEPHONE CLOSET.	25% CHRYSOTILE ASBESTOS
7800	1WTC-07800	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB EXPOSED WITHIN THE SOUTHWEST TELEPHONE CLOSET.	20% CHRYSOTILE ASBESTOS
12093	1WTC-12093	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	1-1% CHRYSOTILE ASBESTOS
12003	1WTC-12003	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12005	1WTC-12005	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
12007	1WTC-12007	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
12008	1WTC-12008	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
12009	1WTC-12009	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
12011	1WTC-12011	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
12012	1WTC-12012	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12013	1WTC-12013	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12014	1WTC-12014	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
12015	1WTC-12015	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12018	1WTC-12018	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
12017	1WTC-12017	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
12018	1WTC-12018	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS

PAG001380



ONE WORLD TRADE CENTER  
FLOOR: 24

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
12019	1WTC-12019	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
12020	1WTC-12020	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
12021	1WTC-12021	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
12022	1WTC-12022	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
12023	1WTC-12023	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS TRACE AMOSITE ASBESTOS
12024	1WTC-12024	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
12025	1WTC-12025	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	35% CHRYSOTILE ASBESTOS
12026	1WTC-12026	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
12027	1WTC-12027	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	80% CHRYSOTILE ASBESTOS
12028	1WTC-12028	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	25% CHRYSOTILE ASBESTOS
12029	1WTC-12029	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	35% CHRYSOTILE ASBESTOS
12030	1WTC-12030	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	60% CHRYSOTILE ASBESTOS
12031	1WTC-12031	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	45% CHRYSOTILE ASBESTOS
12032	1WTC-12032	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	35% CHRYSOTILE ASBESTOS
12033	1WTC-12033	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTH CORE CORRIDOR.	10% CHRYSOTILE ASBESTOS
12034	1WTC-12034	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB IN THE PLENUM OF THE NORTH CORE CORRIDOR.	10% CHRYSOTILE ASBESTOS
12035	1WTC-12035	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WEST CORE CORRIDOR.	15% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER

FLOOR: 24

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
12037	1WTC-12037	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE SOUTH SIDE OF THE PASSENGER ELEVATOR LOBBY.	36% CHRYSOTILE ASBESTOS
12038	1WTC-12038	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE EAST SIDE OF THE UNUSED PASSENGER ELEVATOR LOBBY.	33% CHRYSOTILE ASBESTOS
12039	1WTC-12039	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE WEST SIDE OF THE UNUSED PASSENGER ELEVATOR LOBBY.	35% CHRYSOTILE ASBESTOS
12040	1WTC-12040	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE EAST SIDE OF THE UNUSED PASSENGER ELEVATOR LOBBY.	40% CHRYSOTILE ASBESTOS
12433	1WTC-12433	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	42% CHRYSOTILE ASBESTOS
12434	1WTC-12434	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	43% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR 13

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1004	1WTC-01004	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1005	1WTC-01005	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1006	1WTC-01006	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1007	1WTC-01007	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1008	1WTC-01008	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1009	1WTC-01009	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1010	1WTC-01010	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1011	1WTC-01011	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1012	1WTC-01012	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1013	1WTC-01013	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1014	1WTC-01014	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
3261	1WTC-03261	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
3262	1WTC-03262	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
3263	1WTC-03263	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
3264	1WTC-03264	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
3265	1WTC-03265	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
3268	1WTC-03268	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS

PA0001383

ONE WORLD TRADE CENTER  
FLOOR 23

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3259	1WTC-03269	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3270	1WTC-03270	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3271	1WTC-03271	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3272	1WTC-03272	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3273	1WTC-03273	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3274	1WTC-03274	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3276	1WTC-03276	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3277	1WTC-03277	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
7788	1WTC-07788	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	100 CHRYSOTILE ASBESTOS
7789	1WTC-07789	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	100 CHRYSOTILE ASBESTOS
7791	1WTC-07791	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHWEST TELEPHONE CLOSET.	100 CHRYSOTILE ASBESTOS
7792	1WTC-07792	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB EXPOSED WITHIN THE SOUTHWEST TELEPHONE CLOSET.	100 CHRYSOTILE ASBESTOS
7793	1WTC-07793	CONDENSATION INSULATION MATERIAL TROWELED ON A BEAM EXPOSED WITHIN THE SOUTHWEST TELEPHONE CLOSET.	1-30 CHRYSOTILE ASBESTOS
13855	1WTC-13855	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	100 CHRYSOTILE ASBESTOS
13856	1WTC-13856	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	100 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 28

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1017	1WTC-01017	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1018	1WTC-01018	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1019	1WTC-01019	CEILING TILE SAMPLE IN THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1020	1WTC-01020	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1021	1WTC-01021	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1022	1WTC-01022	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1023	1WTC-01023	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1024	1WTC-01024	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1026	1WTC-01026	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1027	1WTC-01027	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1028	1WTC-01028	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1030	1WTC-01030	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1031	1WTC-01031	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
7379	1WTC-07379	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	101 CHRYSOTILE ASBESTOS
7380	1WTC-07380	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	101 CHRYSOTILE ASBESTOS
7381	1WTC-07381	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB EXPOSED WITHIN THE SOUTHWEST TELEPHONE CLOSET.	101 CHRYSOTILE ASBESTOS
7382	1WTC-07382	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR. 27

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
7569	1WTC-07569	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	10% CHRYSOTILE ASBESTOS
7570	1WTC-07570	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	15% CHRYSOTILE ASBESTOS
7573	1WTC-07573	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTHWEST TELEPHONE CLOSET.	70% CHRYSOTILE ASBESTOS
7574	1WTC-07574	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTHWEST TELEPHONE CLOSET.	10% CHRYSOTILE ASBESTOS
12053	1WTC-12053	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
12054	1WTC-12054	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12055	1WTC-12055	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
12056	1WTC-12056	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
12057	1WTC-12057	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12058	1WTC-12058	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12059	1WTC-12059	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12060	1WTC-12060	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12061	1WTC-12061	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
12062	1WTC-12062	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
12063	1WTC-12063	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12064	1WTC-12064	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12065	1WTC-12065	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 27

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
12066	1WTC-12066	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
12067	1WTC-12067	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	5% CHRYSOTILE ASBESTOS
12068	1WTC-12068	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
12069	1WTC-12069	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	35% CHRYSOTILE ASBESTOS
12070	1WTC-12070	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	35% CHRYSOTILE ASBESTOS
12071	1WTC-12071	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
12072	1WTC-12072	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
12073	1WTC-12073	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
12075	1WTC-12075	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
12076	1WTC-12076	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTH CORE CORRIDOR.	50% CHRYSOTILE ASBESTOS
12077	1WTC-12077	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTH CORE CORRIDOR.	40% CHRYSOTILE ASBESTOS
12078	1WTC-12078	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE EAST CORE CORRIDOR.	40% CHRYSOTILE ASBESTOS
12079	1WTC-12079	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE WEST CORE CORRIDOR.	60% CHRYSOTILE ASBESTOS
12080	1WTC-12080	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
12081	1WTC-12081	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
12083	1WTC-12083	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL CEILING IN THE PLENUM OF THE NORTHEAST QUADRANT.	25% CHRYSOTILE ASBESTOS
12084	1WTC-12084	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 28

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
983	1WTC-00983	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
986	1WTC-00986	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
987	1WTC-00987	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
988	1WTC-00988	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
989	1WTC-00989	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
991	1WTC-00991	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
992	1WTC-00992	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
993	1WTC-00993	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
997	1WTC-00997	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
998	1WTC-00998	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
999	1WTC-00999	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1000	1WTC-01000	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1001	1WTC-01001	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1003	1WTC-01003	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
7381	1WTC-07381	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB EXPOSED WITHIN THE NORTHWEST TELEPHONE CLOSET.	101 CHRYSOTILE ASBESTOS
7382	1WTC-07382	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHWEST TELEPHONE CLOSET.	101 CHRYSOTILE ASBESTOS
7383	1WTC-07383	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	101 CHRYSOTILE ASBESTOS



ONE WORLD TRADE CENTER  
FLOOR: 19

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
7553	1WTC-07553	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHEAST TELEPHONE CLOSET.	10% CHRYSOTILE ASBESTOS
7555	1WTC-07555	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB EXPOSED WITHIN THE NORTHWEST TELEPHONE CLOSET.	10% CHRYSOTILE ASBESTOS
7556	1WTC-07556	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTHWEST TELEPHONE CLOSET.	10% CHRYSOTILE ASBESTOS
7557	1WTC-07557	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB EXPOSED WITHIN THE SOUTHEAST TELEPHONE CLOSET.	10% CHRYSOTILE ASBESTOS
7559	1WTC-07559	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB EXPOSED WITHIN THE SOUTHWEST TELEPHONE CLOSET.	10% CHRYSOTILE ASBESTOS
14923	1WTC-14923	FLUFFY FALLOUT MATERIAL IN THE PLENUM OF EAST CORE CORRIDOR.	10% CHRYSOTILE ASBESTOS
14926	1WTC-14926	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTH CORE CORRIDOR.	11% CHRYSOTILE ASBESTOS
14927	1WTC-14927	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTH CORE CORRIDOR.	11% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR 30

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
11482	1WTC-11482	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
11483	1WTC-11483	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
11484	1WTC-11484	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTH GENERAL OFFICE AREA NORTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
11485	1WTC-11485	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTH WEST GENERAL OFFICE AREA NORTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
11486	1WTC-11486	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	200 CHRYSOTILE ASBESTOS
11487	1WTC-11487	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	500 CHRYSOTILE ASBESTOS
11493	1WTC-11493	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	400 CHRYSOTILE ASBESTOS
11494	1WTC-11494	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	300 CHRYSOTILE ASBESTOS
11495	1WTC-11495	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	600 CHRYSOTILE ASBESTOS
11496	1WTC-11496	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	200 CHRYSOTILE ASBESTOS
11497	1WTC-11497	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
11498	1WTC-11498	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
11499	1WTC-11499	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	200 CHRYSOTILE ASBESTOS
11500	1WTC-11500	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	400 CHRYSOTILE ASBESTOS
11501	1WTC-11501	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	200 CHRYSOTILE ASBESTOS
11502	1WTC-11502	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	200 CHRYSOTILE ASBESTOS
11503	1WTC-11503	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR 30

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
11304	1WTC-11304	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	401 CHRYSOTILE ASBESTOS
11305	1WTC-11305	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	331 CHRYSOTILE ASBESTOS
11306	1WTC-11306	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	301 CHRYSOTILE ASBESTOS
11307	1WTC-11307	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	301 CHRYSOTILE ASBESTOS
11308	1WTC-11308	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	431 CHRYSOTILE ASBESTOS
11309	1WTC-11309	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	331 CHRYSOTILE ASBESTOS
11310	1WTC-11310	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	201 CHRYSOTILE ASBESTOS
11311	1WTC-11311	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
11312	1WTC-11312	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	301 CHRYSOTILE ASBESTOS
11313	1WTC-11313	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 11

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULTS
5783	1WTC-03783	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	33% CHRYSOTILE ASBESTOS
5784	1WTC-03784	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	35% CHRYSOTILE ASBESTOS
5785	1WTC-03785	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
5787	1WTC-03787	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
5849	1WTC-03849	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
5871	1WTC-03871	CONDENSITIOUS INSULATION MATERIAL TROWELED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	3% CHRYSOTILE ASBESTOS
5872	1WTC-03872	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
5873	1WTC-03873	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
5874	1WTC-03874	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
5875	1WTC-03875	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
5876	1WTC-03876	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
5878	1WTC-03878	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
5879	1WTC-03879	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	31% CHRYSOTILE ASBESTOS
5880	1WTC-03880	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
5881	1WTC-03881	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
5882	1WTC-03882	CONDENSITIOUS INSULATION MATERIAL TROWELED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
5883	1WTC-03883	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	13% CHRYSOTILE ASBESTOS

PA0001393

ONE WORLD TRADE CENTER  
FLOOR: 11

<u>SAMPLE NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
5883	1WTC-05883	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
5884	1WTC-05884	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
5887	1WTC-05887	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
5885	1WTC-05888	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
5888	1WTC-05889	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
5890	1WTC-05890	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
5891	1WTC-05891	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
5893	1WTC-05893	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
5894	1WTC-05894	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
5895	1WTC-05895	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
5898	1WTC-05896	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
5898	1WTC-05898	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
5901	1WTC-05901	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
5902	1WTC-05902	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
5903	1WTC-05903	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 12

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
3646	1WTC-03646	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	3% CHRYSOTILE ASBESTOS
3646	1WTC-09003	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #3646.	10% CHRYSOTILE ASBESTOS
3646	1WTC-09004	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #3646.	NON ASBESTOS
3646	1WTC-09005	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #3646.	40% CHRYSOTILE ASBESTOS
3646	1WTC-09006	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #3646.	40% CHRYSOTILE ASBESTOS
3660	1WTC-03660	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	3% CHRYSOTILE ASBESTOS
3660	1WTC-04993	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #3660.	1-12 CHRYSOTILE ASBESTOS
3660	1WTC-08996	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #3660.	1-12 CHRYSOTILE ASBESTOS
3660	1WTC-04997	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #3660.	41% CHRYSOTILE ASBESTOS
3660	1WTC-04998	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #3660.	20% CHRYSOTILE ASBESTOS
3661	1WTC-03661	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	1% CHRYSOTILE ASBESTOS
3661	1WTC-08999	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #3661.	2-12 CHRYSOTILE ASBESTOS
3661	1WTC-09000	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT BY SAMPLE #3661.	20% CHRYSOTILE ASBESTOS
3661	1WTC-09001	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #3661.	NON ASBESTOS
3661	1WTC-09002	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #3661.	12% CHRYSOTILE ASBESTOS
3798	1WTC-03798	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
3798	1WTC-13377	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT NEAR SAMPLE #3798.	40% CHRYSOTILE ASBESTOS

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 384.

ONE WORLD TRADE CENTER  
FLOOR: 32

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
3798	1WTC-13378	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT NEAR SAMPLE 3798.	100 CHRYSOTILE ASBESTOS
3798	1WTC-13379	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT NEAR SAMPLE # 3798.	100 CHRYSOTILE ASBESTOS
3798	1WTC-13380	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT NEAR SAMPLE 3798.	100 CHRYSOTILE ASBESTOS
13391	1WTC-13391	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
13391	1WTC-13391	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
14390	1WTC-14390	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
14391	1WTC-14391	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	1-10 CHRYSOTILE ASBESTOS
14397	1WTC-14397	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
14401	1WTC-14401	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
14402	1WTC-14402	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	1-10 CHRYSOTILE ASBESTOS
14403	1WTC-14403	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
14404	1WTC-14404	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
14406	1WTC-14406	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
14408	1WTC-14408	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	1-10 CHRYSOTILE ASBESTOS
14451	1WTC-14451	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS

## ONE WORLD TRADE CENTER

FLOOR: 33

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
10961	1WTC-10961	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10962	1WTC-10962	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10963	1WTC-10963	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10964	1WTC-10964	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10965	1WTC-10965	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10966	1WTC-10966	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10967	1WTC-10967	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10968	1WTC-10968	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10969	1WTC-10969	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10970	1WTC-10970	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10971	1WTC-10971	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10972	1WTC-10972	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10973	1WTC-10973	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
10974	1WTC-10974	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS



ONE WORLD TRADE CENTER  
FLOOR: 1A

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
973	1WTC-00973	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
974	1WTC-00974	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	200 CHRYSOTILE ASBESTOS
975	1WTC-00975	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	300 CHRYSOTILE ASBESTOS
976	1WTC-00976	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	200 CHRYSOTILE ASBESTOS
979	1WTC-00979	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
980	1WTC-00980	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
982	1WTC-00982	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 13

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
11321	1WTC-11321	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	43% CHRYSOTILE ASBESTOS
11322	1WTC-11322	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTH CENTRAL OFFICE AREA BY THE NORTHEAST TELEPHONE CLOSET.	40% CHRYSOTILE ASBESTOS
11323	1WTC-11323	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	25% CHRYSOTILE ASBESTOS
11324	1WTC-11324	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
11325	1WTC-11325	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
11326	1WTC-11326	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
11327	1WTC-11327	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
11328	1WTC-11328	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	25% CHRYSOTILE ASBESTOS
11329	1WTC-11329	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	33% CHRYSOTILE ASBESTOS
11330	1WTC-11330	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
11331	1WTC-11331	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	60% CHRYSOTILE ASBESTOS
11332	1WTC-11332	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	25% CHRYSOTILE ASBESTOS
11333	1WTC-11333	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	25% CHRYSOTILE ASBESTOS
11334	1WTC-11334	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
11335	1WTC-11335	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS
11336	1WTC-11336	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
11337	1WTC-11337	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	33% CHRYSOTILE ASBESTOS
11338	1WTC-11338	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	25% CHRYSOTILE ASBESTOS

## ONE WORLD TRADE CENTER

FLOOR: 13

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
11340	1WTC-11340	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
11341	1WTC-11341	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	400 CHRYSOTILE ASBESTOS
11342	1WTC-11342	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	400 CHRYSOTILE ASBESTOS
11343	1WTC-11343	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	500 CHRYSOTILE ASBESTOS
11344	1WTC-11344	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	300 CHRYSOTILE ASBESTOS
11345	1WTC-11345	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	400 CHRYSOTILE ASBESTOS
11346	1WTC-11346	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	250 CHRYSOTILE ASBESTOS
11347	1WTC-11347	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	300 CHRYSOTILE ASBESTOS
11348	1WTC-11348	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	400 CHRYSOTILE ASBESTOS

## ONE WORLD TRADE CENTER

FLOOR: 16

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
10822	1WTC-10822	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	402 CHRYSOTILE ASBESTOS
10823	1WTC-10823	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	502 CHRYSOTILE ASBESTOS
10824	1WTC-10824	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	351 CHRYSOTILE ASBESTOS
10825	1WTC-10825	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	452 CHRYSOTILE ASBESTOS
10826	1WTC-10826	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	502 CHRYSOTILE ASBESTOS
10828	1WTC-10828	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	351 CHRYSOTILE ASBESTOS
10829	1WTC-10829	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	452 CHRYSOTILE ASBESTOS
10830	1WTC-10830	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	452 CHRYSOTILE ASBESTOS
10831	1WTC-10831	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	402 CHRYSOTILE ASBESTOS
10832	1WTC-10832	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	452 CHRYSOTILE ASBESTOS
10833	1WTC-10833	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	301 CHRYSOTILE ASBESTOS
10834	1WTC-10834	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	351 CHRYSOTILE ASBESTOS
10835	1WTC-10835	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	402 CHRYSOTILE ASBESTOS
10836	1WTC-10836	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	402 CHRYSOTILE ASBESTOS
10837	1WTC-10837	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	402 CHRYSOTILE ASBESTOS
10838	1WTC-10838	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	402 CHRYSOTILE ASBESTOS
10839	1WTC-10839	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	402 CHRYSOTILE ASBESTOS

PAC001401

ONE WORLD TRADE CENTER  
FLOOR: 36

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
10840	1WTC-10840	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
10841	1WTC-10841	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
10842	1WTC-10842	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
10844	1WTC-10844	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
10845	1WTC-10845	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
10846	1WTC-10846	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
10847	1WTC-10847	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
10848	1WTC-10848	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
10849	1WTC-10849	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	25% CHRYSOTILE ASBESTOS
10850	1WTC-10850	CONDENSATION INSULATION MATERIAL TROWELED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT OF THE SOUTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS

PA0001402

ONE WORLD TRADE CENTER  
FLOOR: 37

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULTS
3391	1WTC-03391	FLUFFY FALLOUT INSULATION MATERIAL IN THE PLENUM BY NORTHEAST TELEPHONE CLOSET OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3392	1WTC-03392	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3393	1WTC-03393	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3394	1WTC-03394	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3395	1WTC-03395	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3396	1WTC-03396	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3397	1WTC-03397	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3398	1WTC-03398	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3901	1WTC-03901	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3902	1WTC-03902	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3903	1WTC-03903	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3904	1WTC-03904	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3905	1WTC-03905	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3906	1WTC-03906	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3907	1WTC-03907	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3908	1WTC-03908	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
3909	1WTC-03909	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 37

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
16764	1WTC-16764	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	75% CHRYSOTILE ASBESTOS
16765	1WTC-16765	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
16765	1WTC-16765	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	33% CHRYSOTILE ASBESTOS
16766	1WTC-16766	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
16767	1WTC-16767	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	33% CHRYSOTILE ASBESTOS
16768	1WTC-16768	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
16769	1WTC-16769	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
16770	1WTC-16770	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
16771	1WTC-16771	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
16772	1WTC-16772	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
16773	1WTC-16773	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	20% CHRYSOTILE ASBESTOS
16774	1WTC-16774	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	25% CHRYSOTILE ASBESTOS
16775	1WTC-16775	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
16782	1WTC-16782	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	33% CHRYSOTILE ASBESTOS
16783	1WTC-16783	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	45% CHRYSOTILE ASBESTOS
16784	1WTC-16784	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	45% CHRYSOTILE ASBESTOS
16785	1WTC-16785	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	33% CHRYSOTILE ASBESTOS

PAG001404

ONE WORLD TRADE CENTER  
FLOOR: 37

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1-787	1WTC-1-787	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	43% CHRYSOTILE ASBESTOS
1-790	1WTC-1-790	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	60% CHRYSOTILE ASBESTOS
1-791	1WTC-1-791	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	43% CHRYSOTILE ASBESTOS
1-792	1WTC-1-792	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	43% CHRYSOTILE ASBESTOS
1-793	1WTC-1-793	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	43% CHRYSOTILE ASBESTOS



ONE WORLD TRADE CENTER  
FLOOR: 11

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
2461	147C-02461	FLUFFY INSULATION MATERIAL SPRAYED ON A METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	11 CHRYSOTILE ASBESTOS
2461	147C-10458	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE #2461.	TRACE CHRYSOTILE ASBESTOS
2461	147C-10459	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE #2461.	1-11 CHRYSOTILE ASBESTOS
2461	147C-10460	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT 2 FEET NORTH OF SAMPLE #2461.	NON ASBESTOS
2461	147C-10461	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT 2 FEET EAST OF SAMPLE #2461.	TRACE CHRYSOTILE ASBESTOS
2461	147C-10462	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT 2 FEET WEST OF SAMPLE #2461.	1-11 CHRYSOTILE ASBESTOS
2461	147C-10463	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT 2 FEET SOUTH OF SAMPLE #2461.	NON ASBESTOS

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 184.

ONE WORLD TRADE CENTER  
FLOOR: 39

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
2642	1WTC-02642	FIBREGLASS INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE EAST CORE CORRIDOR.	10% CHRYSOTILE ASBESTOS
14655	1WTC-14655	FIBREGLASS INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE EAST CORE CORRIDOR.	10% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 40

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
2436	1WTC-02436	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
2437	1WTC-02437	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	201 CHRYSOTILE ASBESTOS
2438	1WTC-02438	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	301 CHRYSOTILE ASBESTOS
2439	1WTC-02439	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	401 CHRYSOTILE ASBESTOS
2440	1WTC-02440	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	151 CHRYSOTILE ASBESTOS
2441	1WTC-02441	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	151 CHRYSOTILE ASBESTOS
2442	1WTC-02442	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	153 CHRYSOTILE ASBESTOS
2443	1WTC-02443	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	151 CHRYSOTILE ASBESTOS
2444	1WTC-02444	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	151 CHRYSOTILE ASBESTOS
3003	1WTC-03003	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	151 CHRYSOTILE ASBESTOS
3004	1WTC-03004	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	151 CHRYSOTILE ASBESTOS
3005	1WTC-03005	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	151 CHRYSOTILE ASBESTOS
3006	1WTC-03006	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
3007	1WTC-03007	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	151 CHRYSOTILE ASBESTOS
3009	1WTC-03009	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	301 CHRYSOTILE ASBESTOS
3010	1WTC-03010	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS

PA0001408

ONE WORLD TRADE CENTER  
FLOOR: 40

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
3011	1WTC-03011	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
3012	1WTC-03012	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
3013	1WTC-03013	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	100 CHRYSOTILE ASBESTOS
3015	1WTC-03015	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3016	1WTC-03016	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3017	1WTC-03017	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3018	1WTC-03018	FLUFFY FALLOUT MATERIAL IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3019	1WTC-03019	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3021	1WTC-03021	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3022	1WTC-03022	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3023	1WTC-03023	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3024	1WTC-03024	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
3026	1WTC-03026	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
15143	1WTC-15143	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE WEST CORE CORRIDOR OUTSIDE MEN'S ROOM.	1-10 CHRYSOTILE ASBESTOS
15143	1WTC-15143	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTH CORE CORRIDOR.	1-10 CHRYSOTILE ASBESTOS
15150	1WTC-15150	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS
15151	1WTC-15151	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	100 CHRYSOTILE ASBESTOS

PA0001409

ONE WORLD TRADE CENTER  
FLOOR: 40

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
13152	1WTC-13152	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLEIGH OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR 41

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
704	1WTC-00704	CONDENSITIVE INSULATION MATERIAL FROM A HEAT TRANSFER PIPE LOCATED SOUTH OF THE ACS-41-8 UNIT.	23% CHRYSOTILE ASBESTOS
713	1WTC-00713	CONDENSITIVE INSULATION MATERIAL FROM A HEAT TRANSFER PIPE COUPLING NEAR THE SW-03 UNIT IN THE NORTHWEST QUADRANT.	25% CHRYSOTILE ASBESTOS
738	1WTC-00738	CONDENSITIVE INSULATION MATERIAL FROM A HEAT TRANSFER PIPE COVER LOCATED WEST OF THE ACS-41-2 UNIT.	10% CHRYSOTILE ASBESTOS
736	1WTC-00736	FLUFFY FALLOUT MATERIAL ON FLOOR LOCATED NEAR THE ACS-41-8 UNIT.	15% CHRYSOTILE ASBESTOS
748	1WTC-00748	CONDENSITIVE INSULATION MATERIAL FROM A HEAT TRANSFER PIPE ELBOW LOCATED WEST OF THE ACS-41-7 UNIT.	5% CHRYSOTILE ASBESTOS
4071	1WTC-04071	FLUFFY PRE-MOLDED INSULATION MATERIAL FROM A HEAT TRANSFER PIPE LOCATED 3 FEET EAST OF THE PRV 41-4 UNIT OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
4079	1WTC-04079	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK LOCATED SOUTHWEST OF COLUMN 807.	40% CHRYSOTILE ASBESTOS
4080	1WTC-04080	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK LOCATED NORTHEAST OF THE ACS 41-16 UNIT.	40% CHRYSOTILE ASBESTOS
4081	1WTC-04081	CONDENSITIVE INSULATION MATERIAL TROWELED ON A BEAM LOCATED SOUTH OF COLUMN 807.	3% TROVILITE ASBESTOS
4090	1WTC-04090	CONDENSITIVE INSULATION MATERIAL FROM A DUCT LOCATED ABOVE THE ACS 41-13 UNIT.	15% AMOYITE ASBESTOS 5% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR, 11

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
7917	1WTC-07917	FLUTTY PAD INSULATION MATERIAL ON A DUCT IN THE PLENUM OF THE SOUTHWEST QUADRANT.	100 AMCSITE ASBESTOS 1-33 CHRYSOCTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 48

<u>SEA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
147	1WTC-04147	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	32 CHRYSOTILE ASBESTOS
147	1WTC-03320	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #147.	132 CHRYSOTILE ASBESTOS
4147	1WTC-03321	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #147.	TRACE CHRYSOTILE ASBESTOS
4150	1WTC-04150	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	102 CHRYSOTILE ASBESTOS
4150	1WTC-03318	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	152 CHRYSOTILE ASBESTOS
4150	1WTC-03319	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE #150.	152 CHRYSOTILE ASBESTOS
4150	1WTC-14070	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED ONE FOOT EAST OF SAMPLE #150.	412 CHRYSOTILE ASBESTOS
4150	1WTC-14071	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED TWO FEET EAST OF SAMPLE #150.	NOW ASBESTOS
3319	1WTC-14072	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED FOUR FEET OF SAMPLE #3319.	102 CHRYSOTILE ASBESTOS
3319	1WTC-14073	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED 2 FEET EAST OF SAMPLE NO. 3319.	NOW ASBESTOS
1081	1WTC-14081	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	1-32 CHRYSOTILE ASBESTOS
1084	1WTC-14084	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	102 CHRYSOTILE ASBESTOS

\* NOTE: Bon Asbestos Containing Material as per USEPA - see note on page 384.



ONE WORLD TRADE CENTER  
FLOOR: 56

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
9884	1WTC-09884	CONDITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT.	1-11 CHRYSOTILE ASBESTOS
9891	1WTC-09891	CONDITIOUS INSULATION MATERIAL SPRAYED ON A BEAM WITHIN THE SOUTH WALL CONVECTOR UNIT.	1-17 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 37

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
10074	1WTC-10074	CONVENTIONAL INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	31 CEMENTITE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 63

CSA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
3102	1WTC-04302	CONDITITIOUS INSULATION MATERIAL TROVELED ON BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE IN THE NORTHEAST QUADRANT.	31 CHRYSOOTILE ASBESTOS
3102	1WTC-04316	CONDITITIOUS INSULATION MATERIAL TROVELED ON BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT 2' NORTH OF SAMPLE NUMBER 3102.	31 CHRYSOOTILE ASBESTOS
3102	1WTC-04327	CONDITITIOUS INSULATION MATERIAL TROVELED ON BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT 2'-6" NORTH OF SAMPLE NUMBER 3102.	NON ASBESTOS
3102	1WTC-04328	CONDITITIOUS INSULATION MATERIAL TROVELED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT APPROXIMATELY 13'-0" SOUTH OF SAMPLE NUMBER 3102.	12 CHRYSOOTILE ASBESTOS
3102	1WTC-04029	CONDITITIOUS INSULATION MATERIAL TROVELED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT APPROXIMATELY 10'-0" NORTH OF SAMPLE NUMBER 3102.	NON ASBESTOS
3102	1WTC-10463	CONDITITIOUS INSULATION MATERIAL TROVELED ON BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT NEAR SAMPLE NUMBER 3102.	TRACE CHRYSOOTILE ASBESTOS
3102	1WTC-10466	CONDITITIOUS INSULATION MATERIAL TROVELED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT 2' SOUTH OF SAMPLE NUMBER 3102.	NON ASBESTOS
3102	1WTC-10487	CONDITITIOUS INSULATION MATERIAL TROVELED ON BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT 2' NORTH OF SAMPLE NUMBER 3102.	TRACE CHRYSOOTILE ASBESTOS
3102	1WTC-10488	CONDITITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT CLOSE TO SAMPLE NUMBER 4026.	NON ASBESTOS
3102	1WTC-10489	CONDITITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT 1' SOUTH OF SAMPLE NUMBER 4026.	TRACE CHRYSOOTILE ASBESTOS
3102	1WTC-13490	CONDITITIOUS INSULATION MATERIAL TROVELED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT 2' NORTH OF SAMPLE NUMBER 4026.	12 CHRYSOOTILE ASBESTOS

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 188.

ONE WORLD TRADE CENTER  
FLOOR 72

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3364	1WTC-03364	CERAMITIC INSULATION MATERIAL REMOVED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	31 CHRYSOTILE ASBESTOS
3364	1WTC-03889	CERAMITIC INSULATION MATERIAL REMOVED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED THREE FEET WEST OF SAMPLE 3364.	11 CHRYSOTILE ASBESTOS *
3364	1WTC-03890	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT NEAR SAMPLE 3364.	31 CHRYSOTILE ASBESTOS
3364	1WTC-03891	CERAMITIC INSULATION MATERIAL REMOVED ON A BEAM IN THE PLENUM OF THE WEST QUADRANT LOCATED TWO FEET WEST OF SAMPLE 3364.	NON ASBESTOS
3364	1WTC-03892	CERAMITIC INSULATION MATERIAL REMOVED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED THREE FEET EAST OF SAMPLE 3364.	11 CHRYSOTILE ASBESTOS *
3364	1WTC-03893	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED THREE FEET EAST OF SAMPLE 3364.	31 CHRYSOTILE ASBESTOS
3364	1WTC-10411	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT NEAR SAMPLE 3364.	TRACE CHRYSOTILE ASBESTOS *
3364	1WTC-10412	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT NEAR SAMPLE 3364.	NON ASBESTOS
3364	1WTC-10413	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET EAST OF SAMPLE 3364.	NON ASBESTOS
3364	1WTC-10414	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET EAST OF SAMPLE 3364.	NON ASBESTOS
3364	1WTC-10417	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET WEST OF SAMPLE 3364.	<11 CHRYSOTILE ASBESTOS *
3364	1WTC-10418	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET WEST OF SAMPLE 3364.	NON ASBESTOS
3364	1WTC-10419	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT CLOSE TO SAMPLE 33890.	<11 CHRYSOTILE ASBESTOS *
3364	1WTC-10420	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT CLOSE TO SAMPLE 33890.	<11 CHRYSOTILE ASBESTOS *
3364	1WTC-10421	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT 2' EAST OF SAMPLE 33890.	<11 CHRYSOTILE ASBESTOS *
3364	1WTC-10422	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT 2' WEST OF SAMPLE 33890.	<11 CHRYSOTILE ASBESTOS *
3364	1WTC-10423	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT 2' SOUTH OF SAMPLE 33890.	NON ASBESTOS

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 188.

ONE WORLD TRADE CENTER  
FLOOR 72

<u>REA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3364	1WTC-10424	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT 2' SOUTH OF SAMPLE 1890.	NON ASBESTOS
3364	1WTC-10425	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT NEAR SAMPLE 1893.	TRACE CHRYCOTILE ASBESTOS
3364	1WTC-10426	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT NEAR SAMPLE 1893.	1-3% CHRYCOTILE ASBESTOS
3364	1WTC-10427	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET EAST OF SAMPLE 1891.	NON ASBESTOS
3364	1WTC-10428	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET WEST OF SAMPLE 1881.	TRACE CHRYCOTILE ASBESTOS
3364	1WTC-10429	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET SOUTH OF SAMPLE 1893.	4% CHRYCOTILE ASBESTOS
3364	1WTC-10430	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET SOUTH OF SAMPLE 1893.	4% CHRYCOTILE ASBESTOS

\* NOTE: Non Asbestos Containing Material as per OSHA - see note on page 126.

ONE WORLD TRADE CENTER  
FLOOR: 73

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
3939	1WTC-03939	CONDENSATION INSULATION MATERIAL TROWELLED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	1-3% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR 74

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
2881	1WTC-02881	FLUFFY INSULATION MATERIAL SPRAYED ON BEAM IN THE FLENUM OF THE NORTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
2882	1WTC-02882	FLUFFY INSULATION MATERIAL SPRAYED ON BEAM IN THE FLENUM OF THE NORTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
2883	1WTC-02883	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM OF THE NORTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
2885	1WTC-02885	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM OF THE NORTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
2888	1WTC-02888	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM OF THE NORTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
2887	1WTC-02887	CONDITIONOUS INSULATION MATERIAL TRAVELED ON A BEAM IN THE FLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
2888	1WTC-02888	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
2889	1WTC-02889	FLUFFY INSULATION MATERIAL SPRAYED ON BEAM IN THE FLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
2871	1WTC-02891	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
2892	1WTC-02892	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
2893	1WTC-02893	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
2894	1WTC-02894	FLUFFY INSULATION MATERIAL SPRAYED ON BEAM IN THE FLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
2895	1WTC-02895	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM OF THE SOUTHWEST QUADRANT.	15% CHRYSOTILE ASBESTOS
2898	1WTC-02898	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM OF THE SOUTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
2897	1WTC-02897	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM OF THE SOUTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
2899	1WTC-02899	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM OF THE SOUTHEAST QUADRANT.	15% CHRYSOTILE ASBESTOS
2127	1WTC-1127	FLUFFY INSULATION MATERIAL SPRAYED ON BEAM IN THE FLENUM OF THE NORTHEAST QUADRANT.	5% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 74

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
11928	1WTC-11928	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
11929	1WTC-11929	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	251 CHRYSOTILE ASBESTOS
11930	1WTC-11930	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS

PA0001421



ONE WORLD TRADE CENTER  
FLOOR: 73

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1751	1WTC-01751	CONDENSATION MATERIAL ON THERMOSTAT ON FRONT OF THE ACS-75-3 UNIT.	85% CHRYSOTILE ASBESTOS
1868	1WTC-01868	FIBROUS INSULATION MATERIAL FROM A 24" DIAMETER HEAT TRANSFER PIPE AT THE PRV 75-2 IN THE NORTHEAST QUADRANT.	90% CHRYSOTILE ASBESTOS
1868	1WTC-05186	FLUFFY INSULATION MATERIAL FROM A 24" O.D. HEAT TRANSFER PIPE LOCATED AT THE PRV 75-2 UNIT IN THE NORTHEAST QUADRANT.	60% CHRYSOTILE ASBESTOS
1868	1WTC-05187	FLUFFY INSULATION MATERIAL FROM A 24" DIAMETER HEAT TRANSFER PIPE LOCATED AT THE PRV 75-2 NEAR SAMPLE 1868.	60% CHRYSOTILE ASBESTOS
1870	1WTC-01870	FLUFFY INSULATION MATERIAL FROM A 24" O.D. HEAT TRANSFER PIPE LOCATED AT THE PRV 75-3 UNIT OF THE NORTHEAST QUADRANT.	20% AMOSITE ASBESTOS
1885	1WTC-01885	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 75-1 UNIT.	65% CHRYSOTILE ASBESTOS
1902	1WTC-01902	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE NORTH ELECTRICAL SUB-STATION.	3% CHRYSOTILE ASBESTOS
1904	1WTC-01904	FALLOUT MATERIAL ON TOP OF THE DOCK ABOVE THE E-75-21 UNIT.	20% CHRYSOTILE ASBESTOS
1905	1WTC-01905	FIBROUS INSULATION MATERIAL FROM A HEAT TRANSFER PIPE ABOVE THE E.E.S. E-75-21 UNIT.	15% AMOSITE ASBESTOS 10% CHRYSOTILE ASBESTOS
1910	1WTC-01910	FALLOUT MATERIAL FROM THE FLOOR OF THE NORTHWEST RETURN AIR PLenum.	3% CHRYSOTILE ASBESTOS
1915	1WTC-01915	CONDENSATION INSULATION MATERIAL FROM A HEAT TRANSFER PIPE VALVE ABOVE PUMP P-75-2.	3% CHRYSOTILE ASBESTOS
1915	1WTC-05186	CONDENSATION INSULATION MATERIAL FROM A HEAT TRANSFER PIPE VALVE ON PUMP P-75-2 NEAR SAMPLE 1915.	3% CHRYSOTILE ASBESTOS
1915	1WTC-05185	CONDENSATION INSULATION MATERIAL FROM A HEAT TRANSFER PIPE VALVE ON PUMP P-75-2 NEAR SAMPLE 1915.	3% CHRYSOTILE ASBESTOS
1925	1WTC-01925	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE SOUTH ELECTRICAL SUB-STATION.	3% CHRYSOTILE ASBESTOS
1925	1WTC-05188	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE SOUTH ELECTRICAL SUB-STATION NEAR SAMPLE 1925.	10% CHRYSOTILE ASBESTOS
1925	1WTC-05189	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE SOUTH ELECTRICAL SUB-STATION NEAR SAMPLE 1925.	10% CHRYSOTILE ASBESTOS
1925	1WTC-05190	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE SOUTH ELECTRICAL SUB-STATION NEAR SAMPLE 1925.	20% CHRYSOTILE ASBESTOS
1928	1WTC-01928	BAFD PAPER LIKE MATERIAL FROM PIPE SUPPORT ABOVE THE SOUTH ELECTRICAL SUB-STATION.	60% AMOSITE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 77

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
8174	1WTC-08174	CEMENTITIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE WEST WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	1-3% CHRYSOTILE ASBESTOS
8175	1WTC-08175	CEMENTITIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	5% CHRYSOTILE ASBESTOS

PAG001423

ONE WORLD TRADE CENTER  
FLOOR: 19

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1002	1470-1002	CONVENTIONAL INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	1-32 CHERYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 82

<u>AREA</u> <u>UNIT</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1919	1WTC-10385	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE NORTHWEST QUADRANT LOCATED TWO FEET SOUTH OF SAMPLE 1919.	<1% CHRYSOTILE ASBESTOS
1919	1WTC-10386	FLUFFY SPRAYED ON JOIST INSULATION IN FLENUM AT NORTH OFFICE AREA ABOUT 2 FEET EAST OF SAMPLE 1919	<1% CHRYSOTILE ASBESTOS
1919	1WTC-10387	FLUFFY SPRAYED ON DUELLING INSULATION IN FLENUM AT NORTH OFFICE AREA ABOUT 2 FEET WEST OF SAMPLE 1919	1-3% CHRYSOTILE ASBESTOS
4919	1WTC-10388	FLUFFY SPRAYED ON JOIST INSULATION IN FLENUM AT NORTH OFFICE AREA ABOUT 2 FEET SOUTH OF SAMPLE 1919	<1% CHRYSOTILE ASBESTOS
4187	1WTC-14187	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT.	5% CHRYSOTILE ASBESTOS
4188	1WTC-14188	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT.	5% CHRYSOTILE ASBESTOS
4189	1WTC-14189	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE FLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
4193	1WTC-14193	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT.	1-3% CHRYSOTILE ASBESTOS
4213	1WTC-14213	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
4214	1WTC-14214	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE NORTHWEST QUADRANT.	1-1% CHRYSOTILE ASBESTOS

\* NOTE: See Asbestos Containing Material as per OSHA - see note on page 188.

ONE WORLD TRADE CENTER  
FLOOR: 83

SEA	SAMPLE	LOCATION	RESULT
NUMBER	NUMBER		
1177	1WTC-03177	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	32 CHERYSOTILE ASBESTOS
1177	1WTC-03880	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED SIX INCHES NORTH OF SAMPLE 3177.	NON ASBESTOS
1177	1WTC-03881	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT ABOVE SAMPLE 3177.	12 CHERYSOTILE ASBESTOS *
1177	1WTC-03882	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED SIX FEET SOUTHEAST OF SAMPLE 3177.	32 CHERYSOTILE ASBESTOS
1177	1WTC-03883	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT ABOVE SAMPLE 3882.	32 CHERYSOTILE ASBESTOS
1177	1WTC-03884	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED 8 FEET WEST OF SAMPLE 3177.	32 CHERYSOTILE ASBESTOS
1177	1WTC-10385	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE 3884.	<12 CHERYSOTILE ASBESTOS *
1177	1WTC-10386	FLUFFY SPRAYED ON JOIST INSULATION IN PLENUM IN SOUTH EAST OFFICE AREA NEXT TO SAMPLE 03884.	1-32 CHERYSOTILE ASBESTOS
1177	1WTC-10387	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED TWO FEET EAST OF SAMPLE 3884.	<12 CHERYSOTILE ASBESTOS *
1177	1WTC-10388	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET WEST OF SAMPLE 3884.	TRACE CHERYSOTILE ASBESTOS *
1177	1WTC-10389	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED TWO FEET SOUTH OF SAMPLE 3884.	<12 CHERYSOTILE ASBESTOS *
1177	1WTC-10370	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED TWO FEET NORTH OF SAMPLE 3884.	TRACE CHERYSOTILE ASBESTOS *
1177	1WTC-10371	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE 3177.	<12 CHERYSOTILE ASBESTOS *
1177	1WTC-10372	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE 3177.	<12 CHERYSOTILE ASBESTOS *
1177	1WTC-10373	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED TWO FEET EAST OF SAMPLE 3177.	<12 CHERYSOTILE ASBESTOS *
1177	1WTC-10374	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED TWO FEET WEST OF SAMPLE 3177.	<12 CHERYSOTILE ASBESTOS *
1177	1WTC-10375	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED 2 FEET SOUTH OF SAMPLE 3177.	<12 CHERYSOTILE ASBESTOS *

\* NOTE: See Asbestos Containing Material as per OSHA - see note on page 388.

ONE WORLD TRADE CENTER  
FLOOR: 83

SEA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
3177	1WTC-10376	FLUTTY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT LOCATED TWO FEET NORTH OF SAMPLE 3177.	<1% CHRYSOTILE ASBESTOS -
3177	1WTC-10377	FLUTTY SPRAYED ON JOIST INSULATION IN PLENUM IN SOUTH EAST OFFICE AREA NEXT TO SAMPLE #3882.	NON ASBESTOS
3177	1WTC-10378	FLUTTY SPRAYED ON JOIST INSULATION IN PLENUM IN SOUTH EAST OFFICE AREA NEXT TO SAMPLE #3882.	TRACE CHRYSOTILE ASBESTOS -
3177	1WTC-10379	FLUTTY SPRAYED ON JOIST INSULATION IN PLENUM IN SOUTH EAST OFFICE AREA 2' EAST OF SAMPLE #3882.	<1% CHRYSOTILE ASBESTOS -
3177	1WTC-10380	FLUTTY SPRAYED ON JOIST INSULATION IN PLENUM IN SOUTH EAST OFFICE AREA 2' WEST OF SAMPLE #3882.	<1% CHRYSOTILE ASBESTOS -
3177	1WTC-10381	FLUTTY SPRAYED ON JOIST INSULATION IN PLENUM IN SOUTH EAST OFFICE AREA 2' SOUTH OF SAMPLE #3882.	TRACE CHRYSOTILE ASBESTOS -
3177	1WTC-10382	FLUTTY SPRAYED ON JOIST INSULATION IN PLENUM IN SOUTH EAST OFFICE AREA 2' NORTH OF SAMPLE # 3882.	<1% CHRYSOTILE ASBESTOS -
3177	1WTC-10382	FLUTTY SPRAYED ON INSULATION MATERIAL TAKEN FROM A JOIST INSIDE THE PLENUM NEXT TO SAMPLE NO. 3882.	TRACE CHRYSOTILE ASBESTOS -

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 188.

ONE WORLD TRADE CENTER  
FLOOR: 88

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
9024	OWTC-09024	CEMENTITIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT.	1-11 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 97

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
9475	1WTC-09475	CONDITIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT.	401 CHRYSOLOTE ASBESTOS
9479	1WTC-09479	CONDITIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT.	1-31 CHRYSOLOTE ASBESTOS



ONE WORLD TRADE CENTER  
FLOOR: 101

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
V291	1WTC-09291	CONDENSATES SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE EAST WALL CONVERTER UNIT.	1-3% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 102

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
4773	1WTC-04773	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST EXPOSED IN THE SOUTHWEST TELEPHONE CLOSET.	21 CHRYSOTILE ASBESTOS
4773	1WTC-10328	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED IN THE SOUTHWEST TELEPHONE CLOSET NEAR SAMPLE 4773.	NON ASBESTOS
4773	1WTC-10337	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE SOUTHWEST TELEPHONE CLOSET NEAR SAMPLE 4773.	NON ASBESTOS
4773	1WTC-10338	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE SOUTHWEST TELEPHONE CLOSET NEAR SAMPLE 4773.	NON ASBESTOS
4773	1WTC-10339	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE SOUTHWEST TELEPHONE CLOSET NEAR SAMPLE 4773.	NON ASBESTOS
4773	1WTC-10330	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB IN THE SOUTHWEST TELEPHONE CLOSET LOCATED TWO FEET SOUTH OF SAMPLE 4773.	<32 CHRYSOTILE ASBESTOS
4773	1WTC-10331	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB IN THE SOUTHWEST TELEPHONE CLOSET LOCATED TWO FEET NORTH OF SAMPLE 4773.	1-32 CHRYSOTILE ASBESTOS

\* NOTE: See Asbestos Containing Material as per USEPA - see note on page 186.

ONE WORLD TRADE CENTER  
FLOOR, 103

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
8943	1WTC-08943	CONDITIOINS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT.	70% CHRYSOTILE ASBESTOS
8944	1WTC-08944	CONDITIOINS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT.	30% CHRYSOTILE ASBESTOS

1A7001483

ONE WORLD TRADE CENTER  
FLOOR: 104

<u>SEA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
4761	1WTC-04761	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT.	31 CHRYSOTILE ASBESTOS
4761	1WTC-10320	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHWEST QUADRANT NEAR SAMPLE 4761.	NON ASBESTOS
4761	1WTC-10321	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHWEST QUADRANT NEAR SAMPLE 4761.	TRACE CHRYSOTILE ASBESTOS
4761	1WTC-10322	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET NORTH OF SAMPLE 4761.	1-31 CHRYSOTILE ASBESTOS
4761	1WTC-10323	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET EAST OF SAMPLE 4761.	1-31 CHRYSOTILE ASBESTOS
4761	1WTC-10324	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET WEST SAMPLE 4761.	<15 CHRYSOTILE ASBESTOS
4761	1WTC-10325	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHWEST QUADRANT LOCATED TWO FEET SOUTH OF SAMPLE 4761.	1-31 CHRYSOTILE ASBESTOS
4762	1WTC-04762	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT.	31 CHRYSOTILE ASBESTOS
4762	1WTC-10302	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE 4762.	155 CHRYSOTILE ASBESTOS
4762	1WTC-10303	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE 4762.	105 CHRYSOTILE ASBESTOS
4762	1WTC-10304	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT LOCATED TWO FEET NORTH OF SAMPLE 4762.	105 CHRYSOTILE ASBESTOS
4762	1WTC-10305	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT LOCATED TWO FEET EAST OF SAMPLE 4762.	155 CHRYSOTILE ASBESTOS
4765	1WTC-10306	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT LOCATED TWO FEET WEST OF SAMPLE 4762.	<15 CHRYSOTILE ASBESTOS
4762	1WTC-10307	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE FLENUM OF THE SOUTHEAST QUADRANT LOCATED TWO FEET SOUTH OF SAMPLE 4762.	105 CHRYSOTILE ASBESTOS
3461	1WTC-03461	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE FLENUM OF THE SOUTHEAST QUADRANT.	1-35 CHRYSOTILE ASBESTOS
3461	1WTC-10290	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE 3461.	NON ASBESTOS
3461	1WTC-10291	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE 3461.	1-31 CHRYSOTILE ASBESTOS

\* NOTE: Non Asbestos Containing Material as per USEPA - see memo on page 100.

ONE WORLD TRADE CENTER  
FLOOR: 104

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3441	1WTC-10292	FLUFFY SPRAYED ON JOIST INSULATION IN PLENUM AT SOUTH-EAST OFFICE AREA ABOUT 2 FEET NORTH OF SAMPLE #3441	NON ASBESTOS
3441	1WTC-10293	FLUFFY SPRAYED ON JOIST INSULATION IN PLENUM AT SOUTH-EAST OFFICE AREA ABOUT 2 FEET EAST OF SAMPLE #3441	NON ASBESTOS
3441	1WTC-10294	FLUFFY SPRAYED ON JOIST INSULATION IN PLENUM AT SOUTH-EAST OFFICE AREA ABOUT 2 FEET WEST OF SAMPLE #3441	101 CHRYSOTILE ASBESTOS
3441	1WTC-10295	FLUFFY SPRAYED ON DECKING INSULATION IN PLENUM AT SOUTH-EAST OFFICE AREA ABOUT 2 FEET SOUTH OF SAMPLE #3441	101 CHRYSOTILE ASBESTOS
13072	1WTC-13072	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	51 CHRYSOTILE ASBESTOS
13073	1WTC-13073	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	51 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 103

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3739	1WTC-03739	CONDOTTIONS TRAVELED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT.	70% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
FLOOR: 106

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
9204	1WTC-09204	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT.	1-18 CHRYSOPILE ASBESTOS

## ONE WORLD TRADE CENTER

FLOOR: 137

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
9243	1WTC-09243	CERENTIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT.	20% CHRYSOTILE ASBESTOS
9244	1WTC-09244	CERENTIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT.	1-31 CHRYSOTILE ASBESTOS
9247	1WTC-09247	CERENTIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT.	1-31 CHRYSOTILE ASBESTOS
9248	1WTC-09248	CERENTIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT.	1-32 CHRYSOTILE ASBESTOS
9249	1WTC-09249	CERENTIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT.	31 CHRYSOTILE ASBESTOS
9258	1WTC-09258	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	102 CHRYSOTILE ASBESTOS
9260	1WTC-09260	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	102 CHRYSOTILE ASBESTOS
9261	1WTC-09261	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	31 CHRYSOTILE ASBESTOS
9263	1WTC-09263	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST DINING AREA.	102 CHRYSOTILE ASBESTOS
9264	1WTC-09264	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST DINING AREA.	102 CHRYSOTILE ASBESTOS
9268	1WTC-09268	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST DINING AREA.	131 CHRYSOTILE ASBESTOS
9267	1WTC-09267	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST DINING AREA.	102 CHRYSOTILE ASBESTOS
9268	1WTC-09268	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST DINING AREA.	201 CHRYSOTILE ASBESTOS
9269	1WTC-09269	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	402 CHRYSOTILE ASBESTOS
9270	1WTC-09270	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST DINING AREA.	102 CHRYSOTILE ASBESTOS
9271	1WTC-09271	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	102 CHRYSOTILE ASBESTOS
9272	1WTC-09272	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	102 CHRYSOTILE ASBESTOS



ONE WORLD TRADE CENTER  
FLOOR: 107

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
9273	1WTC-09273	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	51 CHRYSOTILE ASBESTOS
9274	1WTC-09274	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	51 CHRYSOTILE ASBESTOS
9275	1WTC-09275	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	100 CHRYSOTILE ASBESTOS
9276	1WTC-09276	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	132 CHRYSOTILE ASBESTOS
9277	1WTC-09277	FLUFFY INSULATION MATERIAL SPRAYED ON BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	101 CHRYSOTILE ASBESTOS
9278	1WTC-09278	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	101 CHRYSOTILE ASBESTOS
9279	1WTC-09279	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	80X CHRYSOTILE ASBESTOS
9280	1WTC-09280	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	401 CHRYSOTILE ASBESTOS
9281	1WTC-09281	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST DINING AREA.	501 CHRYSOTILE ASBESTOS
13498	1WTC-13498	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE KITCHEN AREA IN THE NORTHWEST QUADRANT.	133 CHRYSOTILE ASBESTOS
13499	1WTC-13499	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE KITCHEN AREA IN THE NORTHWEST QUADRANT.	151 CHRYSOTILE ASBESTOS
13500	1WTC-13500	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE KITCHEN AREA IN THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
13501	1WTC-13501	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE KITCHEN AREA IN THE NORTHWEST QUADRANT.	152 CHRYSOTILE ASBESTOS

PAG001439

ONE WORLD TRADE CENTER  
FLOOR: 108

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
13668	1WTC-13668	CHRYTITIOUS INSULATION MATERIAL FROM A 6" O.D. HEAT TRANSFER PIPE ELBOW ABOVE ACS-108-2.	31 CHRYTITIOUS ASBESTOS
13668	1WTC-13668	CHRYTITIOUS INSULATION MATERIAL FROM AN 8" O.D. HEAT TRANSFER PIPE COUPLING LOCATED SOUTH OF ACS 108-11 UNIT.	31 CHRYTITIOUS ASBESTOS
13669	1WTC-13669	CHRYTITIOUS INSULATION MATERIAL FROM A 6" O.D. HEAT TRANSFER PIPE ELBOW LOCATED WEST OF ACS-108-6 UNIT.	1-31 CHRYTITIOUS ASBESTOS

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 ONE WORLD TRADE CENTER

ELEVATOR SHAFT - 01

	<u>SAMPLES</u>
POSITIVE	8
TOTAL	8

ELEVATOR SHAFT - 02

	<u>SAMPLES</u>
POSITIVE	18
TOTAL	18

ELEVATOR SHAFT - 04

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	10

ELEVATOR SHAFT - 05

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	13

ELEVATOR SHAFT - 07

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	24

ELEVATOR SHAFT - 08

	<u>SAMPLES</u>
POSITIVE	26
TOTAL	28

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

ELEVATOR SHAFT - 09

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

ELEVATOR SHAFT - 10

	<u>SAMPLES</u>
POSITIVE	13
TOTAL	13

ELEVATOR SHAFT - 11

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

ELEVATOR SHAFT - 12

	<u>SAMPLES</u>
POSITIVE	13
TOTAL	19

ELEVATOR SHAFT - 13

	<u>SAMPLES</u>
POSITIVE	7
TOTAL	19

ELEVATOR SHAFT - 14

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	17

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

ELEVATOR SHAFT - 18

	<u>SAMPLES</u>
POSITIVE	6
TOTAL	17

ELEVATOR SHAFT - 20

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	15

ELEVATOR SHAFT - 23

	<u>SAMPLES</u>
POSITIVE	14
TOTAL	14

ELEVATOR SHAFT - 25

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

ELEVATOR SHAFT - 26

	<u>SAMPLES</u>
POSITIVE	17
TOTAL	15

ELEVATOR SHAFT - 29

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

PA0001443

WORLD TRADE CENTER  
 ASBESTOS SOLE SAMPLING REPORT  
 ONE WORLD TRADE CENTER

ELEVATOR SHAFT - 31

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

ELEVATOR SHAFT - 15

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

ELEVATOR SHAFT - 17

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	3

ELEVATOR SHAFT - 39

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	3

ELEVATOR SHAFT - 43

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

ELEVATOR SHAFT - 47

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

PAG0001444

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

ELEVATOR SHAFT - 48

	<u>SAMPLES</u>
POSITIVE	7
TOTAL	7

ELEVATOR SHAFT - 49

	<u>SAMPLES</u>
POSITIVE	11
TOTAL	11

ELEVATOR SHAFT - 52

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR SHAFT - 53

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR SHAFT - 57

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

ELEVATOR SHAFT - 61

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

PA0001445

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

ELEVATOR SHAFT - 63

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	4

ELEVATOR SHAFT - 66

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	5

ELEVATOR SHAFT - 70

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	3

ELEVATOR SHAFT - 71

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	5

ELEVATOR SHAFT - 74

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	2

ELEVATOR SHAFT - 79

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	1

FA0001446



ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 03

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
193	1WTC-00393	FLUFFY FALLOUT INSULATION MATERIAL ON TOP OF ELEVATOR CAR #3.	131 CHRYSOTILE ASBESTOS
193	1WTC-00393	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 40TH FLOOR.	32 CHRYSOTILE ASBESTOS
196	1WTC-00396	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 14TH FLOOR.	101 CHRYSOTILE ASBESTOS
198	1WTC-00398	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 14TH FLOOR.	32 CHRYSOTILE ASBESTOS
199	1WTC-00399	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 12ND FLOOR.	32 CHRYSOTILE ASBESTOS
400	1WTC-00400	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 29TH FLOOR.	32 CHRYSOTILE ASBESTOS
401	1WTC-00401	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 28TH FLOOR.	101 CHRYSOTILE ASBESTOS
402	1WTC-00402	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 24TH FLOOR.	131 CHRYSOTILE ASBESTOS
403	1WTC-00403	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 20TH FLOOR.	101 CHRYSOTILE ASBESTOS
404	1WTC-00404	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 14TH FLOOR.	101 CHRYSOTILE ASBESTOS
405	1WTC-00405	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 10TH FLOOR.	32 CHRYSOTILE ASBESTOS
406	1WTC-00406	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 10TH FLOOR.	101 CHRYSOTILE ASBESTOS
407	1WTC-00407	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 7TH FLOOR.	101 CHRYSOTILE ASBESTOS
408	1WTC-00408	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 8TH FLOOR.	101 CHRYSOTILE ASBESTOS
409	1WTC-00409	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 3RD FLOOR.	131 CHRYSOTILE ASBESTOS
410	1WTC-00410	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 3RD FLOOR.	131 CHRYSOTILE ASBESTOS

PAG001450

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 04

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
15117	15117C-15117	CERAMITIC INSULATION MATERIAL EXPOSED ON A COLUMN LOCATED ON THE WEST WALL AT THE 2ND FLOOR.	80% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 03

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14870	1WTC-14870	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 11TH FLOOR.	25% CHRYSOTILE ASBESTOS
14872	1WTC-14872	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 8TH FLOOR.	13% CHRYSOTILE ASBESTOS
14874	1WTC-14874	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE NORTH WALL AT THE 12TH FLOOR.	13% CHRYSOTILE ASBESTOS
14876	1WTC-14876	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 18TH FLOOR.	40% CHRYSOTILE ASBESTOS

PAG0001452

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 07

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14858	1WTC-14858	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL BELOW THE 6TH FLOOR.	25% CHRYSOTILE ASBESTOS
14859	1WTC-14859	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL BELOW THE 12TH FLOOR.	10% CHRYSOTILE ASBESTOS
14854	1WTC-14854	CORRUGATED INSULATION MATERIAL TROWELED ON A BEAM LOCATED ON THE WEST WALL BELOW THE 20TH FLOOR.	1-11 CHRYSOTILE ASBESTOS

PAG001453

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 08

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
376	1WTC-00376	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 44TH FLOOR.	10% CHRYSOTILE ASBESTOS
377	1WTC-00377	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 42ND FLOOR.	10% CHRYSOTILE ASBESTOS
378	1WTC-00378	FLUFFY FALLOUT INSULATION MATERIAL ON TOP OF ELEVATOR CAR #8.	10% CHRYSOTILE ASBESTOS
379	1WTC-00379	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 40TH FLOOR.	10% CHRYSOTILE ASBESTOS
380	1WTC-00380	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 37TH FLOOR.	10% CHRYSOTILE ASBESTOS
381	1WTC-00381	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 35TH FLOOR.	10% CHRYSOTILE ASBESTOS
384	1WTC-00384	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 31ST FLOOR.	10% CHRYSOTILE ASBESTOS
386	1WTC-00386	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 27TH FLOOR.	5% CHRYSOTILE ASBESTOS
387	1WTC-00387	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 27TH FLOOR.	20% CHRYSOTILE ASBESTOS
388	1WTC-00388	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 21ST FLOOR.	10% CHRYSOTILE ASBESTOS
389	1WTC-00389	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 18TH FLOOR.	20% CHRYSOTILE ASBESTOS
390	1WTC-00390	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 12TH FLOOR.	30% CHRYSOTILE ASBESTOS
391	1WTC-00391	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 7TH FLOOR.	10% CHRYSOTILE ASBESTOS
392	1WTC-00392	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 3RD FLOOR.	15% CHRYSOTILE ASBESTOS
12714	1WTC-12714	FLUFFY FALLOUT INSULATION MATERIAL TAKEN FROM THE BEAM BETWEEN SHAFTS 8 AND 9	10% CHRYSOTILE ASBESTOS
12715	1WTC-12715	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE NORTHEAST WALL ABOVE CONCOURSE LEVEL.	30% CHRYSOTILE ASBESTOS
12716	1WTC-12716	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE CONCOURSE LEVEL.	20% CHRYSOTILE ASBESTOS
12717	1WTC-12717	FLUFFY FALLOUT INSULATION MATERIAL ON TOP OF ELEVATOR CAR #8.	5% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 08

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
13118	1WTC-13118	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE CONCOURSE LEVEL.	13% CHRYSOTILE ASBESTOS
13118	1WTC-13118	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 2ND FLOOR.	60% CHRYSOTILE ASBESTOS
13119	1WTC-13119	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 9TH FLOOR.	30% CHRYSOTILE ASBESTOS
13120	1WTC-13120	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 19TH FLOOR.	30% CHRYSOTILE ASBESTOS
13121	1WTC-13121	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 27TH FLOOR.	40% CHRYSOTILE ASBESTOS
13122	1WTC-13122	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 34TH FLOOR.	3% CHRYSOTILE ASBESTOS
13123	1WTC-13123	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 41ST FLOOR.	3% CHRYSOTILE ASBESTOS
13124	1WTC-13124	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 44TH FLOOR.	3% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 09

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
12710	1WTC-12710	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE SOUTHWALL ABOVE THE CONCOURSE LEVEL.	10% CHRYSOTILE ASBESTOS
12711	1WTC-12711	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL ABOVE THE CONCOURSE LEVEL.	15% CHRYSOTILE ASBESTOS
12712	1WTC-12712	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL ABOVE THE CONCOURSE LEVEL.	25% CHRYSOTILE ASBESTOS
12713	1WTC-12713	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE NORTHWEST CORNER ABOVE THE CONCOURSE LEVEL.	60% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT. 10

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
12703	1WTC-12703	FLUFFY FALLOUT MATERIAL ON A BEAM LOCATED ABOVE THE CONCOURSE LEVEL.	20% CHRYSOTILE ASBESTOS
12704	1WTC-12704	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED IN THE NORTHEAST CORNER ABOVE THE CONCOURSE LEVEL.	60% CHRYSOTILE ASBESTOS
12707	1WTC-12707	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE CONCOURSE LEVEL.	20% CHRYSOTILE ASBESTOS
12708	1WTC-12708	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE CONCOURSE LEVEL.	20% CHRYSOTILE ASBESTOS
12709	1WTC-12709	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE CONCOURSE LEVEL.	30% CHRYSOTILE ASBESTOS
13133	1WTC-13133	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 18TH FLOOR.	30% CHRYSOTILE ASBESTOS
13134	1WTC-13134	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 8TH FLOOR.	60% CHRYSOTILE ASBESTOS
13135	1WTC-13135	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 13TH FLOOR.	40% CHRYSOTILE ASBESTOS
13136	1WTC-13136	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 20TH FLOOR.	80% CHRYSOTILE ASBESTOS
13137	1WTC-13137	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 27TH FLOOR.	5% CHRYSOTILE ASBESTOS
13138	1WTC-13138	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 14TH FLOOR.	5% CHRYSOTILE ASBESTOS
13139	1WTC-13139	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 19TH FLOOR.	13% CHRYSOTILE ASBESTOS
13140	1WTC-13140	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 44TH FLOOR.	10% CHRYSOTILE ASBESTOS



ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 11

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
12701	1WTC-12701	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED IN THE NORTHWEST CORNER ABOVE THE CONCOURSE.	30% CHRYSOTILE ASBESTOS
12702	1WTC-12702	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL ABOVE THE CONCOURSE.	40% CHRYSOTILE ASBESTOS
12703	1WTC-12703	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL ABOVE THE CONCOURSE.	73% CHRYSOTILE ASBESTOS
12704	1WTC-12704	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE CORNER ABOVE THE CONCOURSE.	40% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 13

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
13153	1WTC-13153	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WALL AT THE 78TH FLOOR.	10% CHRYSOTILE ASBESTOS
13155	1WTC-13155	FLUFFY FALLOUT INSULATION MATERIAL ON TOP OF ELEVATOR CAR 813.	20% CHRYSOTILE ASBESTOS
13156	1WTC-13156	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WALL ABOVE THE 73RD FLOOR.	10% CHRYSOTILE ASBESTOS
13157	1WTC-13157	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WALL ABOVE THE 67TH FLOOR.	15% CHRYSOTILE ASBESTOS
13158	1WTC-13158	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WALL ABOVE THE 63RD FLOOR.	3% CHRYSOTILE ASBESTOS
13159	1WTC-13159	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WALL ABOVE THE 57TH FLOOR.	3% CHRYSOTILE ASBESTOS
13164	1WTC-13164	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WALL ABOVE THE 40TH FLOOR.	10% CHRYSOTILE ASBESTOS
13165	1WTC-13165	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WALL ABOVE THE 35TH FLOOR.	10% CHRYSOTILE ASBESTOS
13167	1WTC-13167	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WALL ABOVE THE 25TH FLOOR.	15% CHRYSOTILE ASBESTOS
13168	1WTC-13168	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WALL ABOVE THE 19TH FLOOR.	45% CHRYSOTILE ASBESTOS
13169	1WTC-13169	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WALL ABOVE THE 14TH FLOOR.	20% CHRYSOTILE ASBESTOS
13170	1WTC-13170	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WALL ABOVE THE 8TH FLOOR.	25% CHRYSOTILE ASBESTOS
13171	1WTC-13171	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WALL ABOVE THE 3RD FLOOR.	60% CHRYSOTILE ASBESTOS TRACE AMOSITE ASBESTOS

PA0001459

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 13

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
13220	1WTC-13220	FLUFFY FALLOUT INSULATION MATERIAL ON TOP OF ELEVATOR CAR #13.	10% CHRYSOTILE ASBESTOS
13221	1WTC-13221	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE EAST WALL AT THE 25TH FLOOR.	1-3% CHRYSOTILE ASBESTOS
13222	1WTC-13222	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 25TH FLOOR.	23% CHRYSOTILE ASBESTOS
13223	1WTC-13223	FLUFFY INSULATION MATERIAL TROWELED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 19TH FLOOR.	25% CHRYSOTILE ASBESTOS
13224	1WTC-13224	FLUFFY INSULATION MATERIAL TROWELED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 13TH FLOOR.	5% CHRYSOTILE ASBESTOS
13225	1WTC-13225	FLUFFY INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 7TH FLOOR.	23% CHRYSOTILE ASBESTOS
13226	1WTC-13226	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 2ND FLOOR.	23% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT, 16

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
15192	1WTC-15192	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 2ND FLOOR.	5% CHRYSOTILE ASBESTOS
15193	1WTC-15193	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 2ND FLOOR.	10% CHRYSOTILE ASBESTOS
15194	1WTC-15194	FLUFFY INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 19TH FLOOR.	10% CHRYSOTILE ASBESTOS
15197	1WTC-15197	FLUFFY INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 24TH FLOOR.	13% CHRYSOTILE ASBESTOS
15198	1WTC-15198	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 24TH FLOOR.	10% CHRYSOTILE ASBESTOS

PAG001461

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 18

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
13262	1WTC-13262	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 2ND FLOOR.	58 CHRYSOTILE ASBESTOS
13263	1WTC-13263	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 2ND FLOOR.	151 CHRYSOTILE ASBESTOS
13265	1WTC-13265	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 12TH FLOOR.	101 CHRYSOTILE ASBESTOS
13266	1WTC-13266	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 18TH FLOOR.	101 CHRYSOTILE ASBESTOS
13267	1WTC-13267	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 24TH FLOOR.	101 CHRYSOTILE ASBESTOS
13268	1WTC-13268	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 24TH FLOOR.	151 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT, 20

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
13233	1WTC-13233	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 20TH FLOOR.	1-15 CHRYSOTILE ASBESTOS
13234	1WTC-13234	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 21ST FLOOR.	401 CHRYSOTILE ASBESTOS
13237	1WTC-13237	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 15TH FLOOR.	231 CHRYSOTILE ASBESTOS
13238	1WTC-13238	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL ABOVE THE 16TH FLOOR.	351 CHRYSOTILE ASBESTOS
13240	1WTC-13240	FLUFFY FALLOUT INSULATION MATERIAL ON TOP OF ELEVATOR CAR #20.	152 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 23

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
15172	1WTC-15172	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL AT THE 73RD FLOOR.	52 CHRYSOTILE ASBESTOS
15173	1WTC-15173	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 73RD FLOOR.	101 CHRYSOTILE ASBESTOS
15174	1WTC-15174	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 87TH FLOOR.	152 CHRYSOTILE ASBESTOS
15175	1WTC-15175	FLUFFY FALLOUT MATERIAL ON TOP OF ELEVATOR CAR #23.	52 CHRYSOTILE ASBESTOS
15176	1WTC-15176	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 80TH FLOOR.	102 CHRYSOTILE ASBESTOS
15177	1WTC-15177	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 53RD FLOOR.	101 CHRYSOTILE ASBESTOS
15178	1WTC-15178	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 45TH FLOOR.	152 CHRYSOTILE ASBESTOS
15179	1WTC-15179	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 19TH FLOOR.	102 CHRYSOTILE ASBESTOS
15180	1WTC-15180	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 33RD FLOOR.	102 CHRYSOTILE ASBESTOS
15181	1WTC-15181	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 16TH FLOOR.	102 CHRYSOTILE ASBESTOS
15182	1WTC-15182	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 18TH FLOOR.	502 CHRYSOTILE ASBESTOS
15183	1WTC-15183	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 13TH FLOOR.	101 CHRYSOTILE ASBESTOS
15184	1WTC-15184	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 2ND FLOOR.	432 CHRYSOTILE ASBESTOS
15185	1WTC-15185	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 8TH FLOOR.	452 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 25

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14431	1WTC-14431	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 2ND FLOOR.	70% CHRYSOTILE ASBESTOS
14432	1WTC-14432	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 4TH FLOOR.	40% CHRYSOTILE ASBESTOS
14433	1WTC-14433	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 10TH FLOOR.	15% CHRYSOTILE ASBESTOS
14404	1WTC-14404	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 15TH FLOOR.	60% CHRYSOTILE ASBESTOS

PA0001465



ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 28

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
411	1WTC-00411	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 16TH FLOOR.	15% CHRYSOTILE ASBESTOS
412	1WTC-00412	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 14TH FLOOR.	10% CHRYSOTILE ASBESTOS
413	1WTC-00413	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 12TH FLOOR.	10% CHRYSOTILE ASBESTOS
414	1WTC-00414	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 10TH FLOOR.	25% CHRYSOTILE ASBESTOS
415	1WTC-00415	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 7TH FLOOR.	5% CHRYSOTILE ASBESTOS
416	1WTC-00416	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 5TH FLOOR.	10% CHRYSOTILE ASBESTOS
417	1WTC-00417	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 3TH FLOOR.	35% CHRYSOTILE ASBESTOS
418	1WTC-00418	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 3RD FLOOR.	15% CHRYSOTILE ASBESTOS
421	1WTC-00421	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 24TH FLOOR.	10% CHRYSOTILE ASBESTOS
422	1WTC-00422	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 23RD FLOOR.	20% CHRYSOTILE ASBESTOS
423	1WTC-00423	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 21ST FLOOR.	20% CHRYSOTILE ASBESTOS
424	1WTC-00424	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 17TH FLOOR.	60% CHRYSOTILE ASBESTOS
425	1WTC-00425	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT 13TH FLOOR.	10% CHRYSOTILE ASBESTOS
427	1WTC-00427	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 9TH FLOOR.	10% CHRYSOTILE ASBESTOS
428	1WTC-00428	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 9TH FLOOR.	10% CHRYSOTILE ASBESTOS
429	1WTC-00429	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 8TH FLOOR.	25% CHRYSOTILE ASBESTOS
430	1WTC-00430	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 4TH FLOOR.	20% CHRYSOTILE ASBESTOS

PAG001466

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 29

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1-405	1WTC-14405	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 14TH FLOOR.	30% CHRYSOTILE ASBESTOS
1-406	1WTC-14406	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 14TH FLOOR.	40% CHRYSOTILE ASBESTOS
1-407	1WTC-14407	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 9TH FLOOR.	33% CHRYSOTILE ASBESTOS
1-408	1WTC-14408	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 2ND FLOOR.	30% CHRYSOTILE ASBESTOS

PA0001467

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 11

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14409	1WTC-14409	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 2ND FLOOR.	15% CHRYSOTILE ASBESTOS
14410	1WTC-14410	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 7TH FLOOR.	33% CHRYSOTILE ASBESTOS
14411	1WTC-14411	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 11TH FLOOR.	40% CHRYSOTILE ASBESTOS
14412	1WTC-14412	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 15TH FLOOR.	50% CHRYSOTILE ASBESTOS
14413	1WTC-14413	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 22ND FLOOR.	50% CHRYSOTILE ASBESTOS
14414	1WTC-14414	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 24TH FLOOR.	20% CHRYSOTILE ASBESTOS

PA0001468

CNY WORLD TRADE CENTER  
ELEVATOR SHAFT: 15

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14413	14WC-14413	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 7TH FLOOR.	10% CHRYSOTILE ASBESTOS
14414	14WC-14414	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 11TH FLOOR.	10% CHRYSOTILE ASBESTOS
14417	14WC-14417	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 18TH FLOOR.	70% CHRYSOTILE ASBESTOS
14418	14WC-14418	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 22ND FLOOR.	10% CHRYSOTILE ASBESTOS
14419	14WC-14419	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 24TH FLOOR.	10% CHRYSOTILE ASBESTOS
14420	14WC-14420	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 2ND FLOOR.	1-1% CHRYSOTILE ASBESTOS

PA0001469

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 37

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
14442	1WTC-14442	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 1RD FLOOR.	702 CHRYSOTILE ASBESTOS
14443	1WTC-14443	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 8TH FLOOR.	701 CHRYSOTILE ASBESTOS
14444	1WTC-14444	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 14TH FLOOR.	701 CHRYSOTILE ASBESTOS
14445	1WTC-14445	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 24TH FLOOR.	702 CHRYSOTILE ASBESTOS
14446	1WTC-14446	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 30TH FLOOR.	402 CHRYSOTILE ASBESTOS

PA0001470

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT, 19

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
10037	1WTC-10037	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 12TH FLOOR.	100 CHRYSOTILE ASBESTOS
10038	1WTC-10038	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 17TH FLOOR.	100 CHRYSOTILE ASBESTOS
10039	1WTC-10039	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 23RD FLOOR.	700 CHRYSOTILE ASBESTOS
10040	1WTC-10040	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 29TH FLOOR.	100 CHRYSOTILE ASBESTOS
10041	1WTC-10041	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 4TH FLOOR.	100 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT, 43

<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14421	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 40TH FLOOR.	10% CHRYSOTILE ASBESTOS
14422	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 35TH FLOOR.	20% CHRYSOTILE ASBESTOS
14423	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 32ND FLOOR.	3% CHRYSOTILE ASBESTOS
14424	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 25TH FLOOR.	40% CHRYSOTILE ASBESTOS
14425	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 19TH FLOOR.	90% CHRYSOTILE ASBESTOS
14426	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 14TH FLOOR.	30% CHRYSOTILE ASBESTOS
14427	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 4TH FLOOR.	40% CHRYSOTILE ASBESTOS
14428	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 1ST FLOOR.	60% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 67

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1429	1WTC-14429	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 40TH FLOOR.	50% CHRYSOTILE ASBESTOS
1430	1WTC-14430	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 16TH FLOOR.	31 CHRYSOTILE ASBESTOS
1431	1WTC-14431	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE WEST WALL AT THE 118TH FLOOR.	60% CHRYSOTILE ASBESTOS
1432	1WTC-14432	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 18TH FLOOR.	60% CHRYSOTILE ASBESTOS
1433	1WTC-14433	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 24TH FLOOR.	60% CHRYSOTILE ASBESTOS
1434	1WTC-14434	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE WEST WALL AT THE 14TH FLOOR.	60% CHRYSOTILE ASBESTOS
1435	1WTC-14435	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 10TH FLOOR.	70% CHRYSOTILE ASBESTOS
1436	1WTC-14436	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE B1 SUBLEVEL.	60% CHRYSOTILE ASBESTOS



ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 48

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
15291	1WTC-15291	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 31 SUBLEVEL.	15% CHRYSOTILE ASBESTOS
15292	1WTC-15292	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL ABOVE THE 37TH FLOOR.	13% CHRYSOTILE ASBESTOS
15293	1WTC-15293	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL ABOVE THE 14TH FLOOR.	13% CHRYSOTILE ASBESTOS
15294	1WTC-15294	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 29TH FLOOR.	13% CHRYSOTILE ASBESTOS
15295	1WTC-15295	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 29TH FLOOR.	16% CHRYSOTILE ASBESTOS
15296	1WTC-15296	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL ABOVE THE 15TH FLOOR.	16% CHRYSOTILE ASBESTOS
15297	1WTC-15297	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE SOUTH WALL ABOVE THE 40TH FLOOR.	20% CHRYSOTILE ASBESTOS

PAG001474

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 49

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
15278	1WTC-15278	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 3RD FLOOR.	10% CHRYSOTILE ASBESTOS
15278	1WTC-15279	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE NORTH WALL ABOVE THE 9TH FLOOR.	23% CHRYSOTILE ASBESTOS
15280	1WTC-15280	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 15TH FLOOR.	10% CHRYSOTILE ASBESTOS
15282	1WTC-15282	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 24TH FLOOR.	15% CHRYSOTILE ASBESTOS
15283	1WTC-15283	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 22ND FLOOR.	10% CHRYSOTILE ASBESTOS
15284	1WTC-15284	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 39TH FLOOR.	15% CHRYSOTILE ASBESTOS
15288	1WTC-15286	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 49TH FLOOR.	15% CHRYSOTILE ASBESTOS
15287	1WTC-15287	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 58TH FLOOR.	20% CHRYSOTILE ASBESTOS
15288	1WTC-15288	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 63RD FLOOR.	20% CHRYSOTILE ASBESTOS
15289	1WTC-15289	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE WEST WALL ABOVE THE 69TH FLOOR.	10% CHRYSOTILE ASBESTOS
15290	1WTC-15290	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE EAST WALL ABOVE THE 74TH FLOOR.	20% CHRYSOTILE ASBESTOS

PA0001475

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 52

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14447	1WTC-14447	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 14TH FLOOR.	10% CHRYSOTILE ASBESTOS
14448	1WTC-14448	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 14TH FLOOR.	25% CHRYSOTILE ASBESTOS
14449	1WTC-14449	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 14TH FLOOR.	60% CHRYSOTILE ASBESTOS

8/1/80 1476

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT, 33

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14450	1WTC-14450	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 44TH FLOOR.	50% CHRYSOTILE ASBESTOS
14451	1WTC-14451	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 50TH FLOOR.	20% CHRYSOTILE ASBESTOS
14452	1WTC-14452	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 51ST FLOOR.	40% CHRYSOTILE ASBESTOS

PA0001477

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT, 37

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
14453	1WTC-14453	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 47TH FLOOR.	60% CHRYSOTILE ASBESTOS
14454	1WTC-14454	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 54TH FLOOR.	70% CHRYSOTILE ASBESTOS
14455	1WTC-14455	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 57TH FLOOR.	20% CHRYSOTILE ASBESTOS
14456	1WTC-14456	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 61ST FLOOR.	20% CHRYSOTILE ASBESTOS

PAG001478

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 61

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
16437	1WTC-16437	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 43TH FLOOR.	101 CHRYSOTILE ASBESTOS
16438	1WTC-16438	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 50TH FLOOR.	101 CHRYSOTILE ASBESTOS
16439	1WTC-16439	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 55TH FLOOR.	101 CHRYSOTILE ASBESTOS
16440	1WTC-16440	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 59TH FLOOR.	101 CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 43

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
10076	1WTC-10076	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 45TH FLOOR.	100% CHERYSOTILE ASBESTOS
10077	1WTC-10077	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 46TH FLOOR.	80% CHERYSOTILE ASBESTOS
10078	1WTC-10078	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 47TH FLOOR.	60% CHERYSOTILE ASBESTOS
10079	1WTC-10079	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 48TH FLOOR.	40% CHERYSOTILE ASBESTOS
10080	1WTC-10080	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL AT THE 49TH FLOOR.	30% CHERYSOTILE ASBESTOS

PAC0001430

ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 66

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14471	1WTC-14471	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 67TH FLOOR.	30% CHRYSOTILE ASBESTOS
14472	1WTC-14472	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 63RD FLOOR.	20% CHRYSOTILE ASBESTOS
14473	1WTC-14473	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 50TH FLOOR.	10% CHRYSOTILE ASBESTOS
14474	1WTC-14474	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 46TH FLOOR.	5% CHRYSOTILE ASBESTOS



ONE WORLD TRADE CENTER  
ELEVATOR SHAFT: 73

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
14461	1WTC-14461	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 74TH FLOOR.	13% CHRYSOTILE ASBESTOS
14462	1WTC-14462	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 67TH FLOOR.	10% CHRYSOTILE ASBESTOS
14463	1WTC-14463	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 61ST FLOOR.	15% CHRYSOTILE ASBESTOS
14464	1WTC-14464	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 53RD FLOOR.	1-3% CHRYSOTILE ASBESTOS
14465	1WTC-14465	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE WEST WALL AT THE 47TH FLOOR.	20% CHRYSOTILE ASBESTOS

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 ONE WORLD TRADE CENTER

ELEVATOR PIT# - 03-04

	<u>SAMPLES</u>
POSITIVE	2
TOTAL	2

ELEVATOR PIT# - 08-09

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT# - 10-11

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT# - 11-13

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	3

ELEVATOR PIT# - 14-15

	<u>SAMPLES</u>
POSITIVE	20
TOTAL	28

ELEVATOR PIT# - 20-21

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	2

PA0001483

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

ELEVATOR PIT - 24

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT - 25-26

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT - 29

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT - 30

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT - 33-34

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT - 35

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

PA0001484

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
ONE WORLD TRADE CENTER

ELEVATOR PITS - 37-38

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	2

ELEVATOR PITS - 39-40

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	2

ELEVATOR PITS - 42-44

	<u>SAMPLES</u>
POSITIVE	2
TOTAL	2

ELEVATOR PITS - 45-46

	<u>SAMPLES</u>
POSITIVE	2
TOTAL	2

PA0001485

ONE WORLD TRADE CENTER  
ELEVATOR FITS: 03-04

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
336	1UTC-00336	INSULATION MATERIAL LOCATED ON THE SOUTH WALL.	30% CHRYSOTILE ASBESTOS
337	1UTC-00337	FALLOUT MATERIAL IN THE ELEVATOR PIT.	30% CHRYSOTILE ASBESTOS

FAF001426

ONE WORLD TRADE CENTER  
ELEVATOR PITTS: 12-13

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
339	1WTC-00139	INSULATION MATERIAL FROM A COLUMN IN THE ELEVATOR PIT.	40% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR PIT: 08-09

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
114	1WTC-00134	INSULATION MATERIAL LOCATED ON THE SOUTH WALL OF THE ELEVATOR PIT.	25% CHRYSOTILE ASBESTOS

FA0001468

ONE WORLD TRADE CENTER  
ELEVATOR PITS: 10-11

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
335	OWTC-00335	INSULATION MATERIAL FROM THE SOUTH WALL IN THE ELEVATOR PIT.	10% CHRYSOTILE ASBESTOS

PAG0001489



ONE WORLD TRADE CENTER  
ELEVATOR PIT: 14-13

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3401	1WTC-03401	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3402	1WTC-03402	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3403	1WTC-03403	FLUFFY INSULATION MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3404	1WTC-03404	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3406	1WTC-03406	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3407	1WTC-03407	CONVENTIONAL FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3408	1WTC-03408	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3409	1WTC-03409	CONVENTIONAL FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3411	1WTC-03411	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3412	1WTC-03412	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3413	1WTC-03413	FLUFFY MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3414	1WTC-03414	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3415	1WTC-03415	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3417	1WTC-03417	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3418	1WTC-03418	CONVENTIONAL FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3419	1WTC-03419	FLUFFY MATERIAL IN THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3420	1WTC-03420	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3421	1WTC-03421	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3422	1WTC-03422	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS
3423	1WTC-03423	FLUFFY FALLOUT MATERIAL FROM THE ELEVATOR PIT.	100 CHRYSOTILE ASBESTOS

PA0001400

ONE WORLD TRADE CENTER  
ELEVATOR PITTS: 20-21

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
341	1WTC-00361	INSULATION MATERIAL ON A COLUMN FROM ELEVATOR PIT.	10% CHRYSOTILE ASBESTOS

PAG0001491

ONE WORLD TRADE CENTER  
ELEVATOR PIT: 2A

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
346	1WTC-00346	INSULATION MATERIAL FROM THE ELEVATOR PIT.	25% CHRYSOTILE ASBESTOS

PA0001492

ONE WORLD TRADE CENTER  
ELEVATOR FITS: 23-24

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
147	1WTC-00347	INSULATION MATERIAL FROM THE ELEVATOR FIT.	3% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR PIT: 29

<u>AREA</u> <u>SUBJECT</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
343	1WTC-00343	INSULATION MATERIAL FROM THE ELEVATOR PIT.	20% CHRYSOTILE ASBESTOS

PA0001494

ONE WORLD TRADE CENTER  
ELEVATOR PIT: 30

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3-3	LV22-00143	INSULATION MATERIAL FROM THE ELEVATOR PIT.	10% CHRYSOTILE ASBESTOS

ONE WORLD TRADE CENTER  
ELEVATOR PIT: 33-34

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
348	1WTC-03348	INSULATION MATERIAL FROM THE ELEVATOR PIT.	SI CHRYSOTILE ASBESTOS

PA0001496

ONE WORLD TRADE CENTER  
ELEVATOR PIT: 15

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
344	1WTC-00344	INSULATION MATERIAL FROM THE ELEVATOR PIT.	15% CHRYSOTILE ASBESTOS TRACE AMOSITE ASBESTOS



ONE WORLD TRADE CENTER  
ELEVATOR FITS: 17-18

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
133	1WTC-00355	INSULATION MATERIAL ON A COLUMN FROM THE ELEVATOR PIT.	20% CHRYSOTILE ASBESTOS

71-001498

ONE WORLD TRADE CENTER  
ELEVATOR FITS: 39-40

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
334	1WTC-00334	INSULATION MATERIAL ON A COLUMN FROM ELEVATOR FITS 39 AND 40.	100 PERCENTURE ASBESTOS

PA0001499

ONE WORLD TRADE CENTER  
ELEVATOR PIT: 42-44

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
349	1WTC-00349	OUTER LAYER OF INSULATION MATERIAL FROM THE ELEVATOR PIT.	20% CHRYSOTILE ASBESTOS
350	1WTC-00350	INNER LAYER OF INSULATION MATERIAL FROM THE ELEVATOR PIT.	10% CHRYSOTILE ASBESTOS

PA0001500

ONE WORLD TRADE CENTER  
ELEVATOR FITS: 43-44

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
131	1WTC-00351	FALLOUT MATERIAL ON THE FLOOR IN THE ELEVATOR FIT.	100 CHRYSOOTILE ASBESTOS
132	1WTC-00352	INSULATION MATERIAL FROM A BEAM IN ELEVATOR FIT.	230 CHRYSOOTILE ASBESTOS

PA0001501

ASBESTOS INVESTIGATION AND ANALYSIS REPORT  
WORLD TRADE CENTER  
VOLUME II OF II

ENVIRONMENTAL MANAGEMENT DIVISION  
MARCH 21, 1988

PA0002562

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 TWO WORLD TRADE CENTER

FLOORS WITH NON-ACM CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACM SAMPLES</u>
81	77	77
82	1	1
84	1	1
86	26	25
2	9	9
3	33	33
4	36	26
5	18	18
9	38	36
14	40	40
15	40	40
16	38	38
17	50	50
18	39	39
19	42	39
20	89	87
21	42	42
22	52	53
23	40	40
24	40	40
25	41	41
27	42	42
28	73	73
39	40	40
30	78	78
31	38	38
34	42	42
35	40	40
36	83	60
37	40	40
38	40	40
39	41	41
44	43	43
45	33	33
46	43	43
47	50	50
48	49	49
49	45	45
50	40	40
51	33	33
52	36	36
53	34	34
54	25	23
55	50	50
56	52	52
57	40	40

PA0002564

WORLD TRADE CENTER  
 ASBESTOS Bulk SAMPLING REPORT  
 TWO WORLD TRADE CENTER

FLOORS WITH NON-ACH CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACH SAMPLES</u>
38	32	32
39	32	32
40	30	30
41	36	36
42	36	36
43	33	33
44	41	41
45	42	42
46	41	41
47	32	33
48	37	37
49	48	48
70	30	30
71	36	36
72	32	32
73	36	36
77	33	33
78	33	33
79	32	32
80	32	32
91	32	32
92	31	31
93	32	32
94	36	36
95	31	31
96	33	32
97	31	31
98	30	30
99	30	30
100	32	32
101	30	30
102	40	40
103	40	40
104	33	33
105	32	33
106	32	33

PA0002565

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - B1

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	81	27	0	15	1	2

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - B2

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	1	0	1	0	0
TOTAL	18	8	0	11	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABANDONMENT

FLOOR - B3

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	3	1	0	2	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - B4

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	8	0	0	0	0	0
TOTAL	21	1	0	20	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - B5

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	1	0	0	2	2
TOTAL	66	28	0	18	2	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM



WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 1

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RYAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	3	0	0	0	0
TOTAL	12	12	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT

FLOOR - 2

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RYAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	9	9	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOX

FLOOR - 3

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RYAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	11	11	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOX

FLOOR - 4

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RYAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	10	10	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOX

FLOOR - 5

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RYAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	1	0
TOTAL	11	10	0	0	2	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOX

WORLD TRADE CENTER  
ASBESTOS Bulk SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 6

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	18	18	0	0	0	0
TOTAL	22	22	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABANDON

FLOOR - 7

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	73	43	0	7	1	0
TOTAL	182	127	0	27	8	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABANDON

FLOOR - 8

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	0	2	0	0	0
TOTAL	74	36	18	0	9	2

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AON

FLOOR - 10

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	26	26	0	0	0	0
TOTAL	31	30	0	0	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABANDON

FLOOR - 11

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	12	12	0	0	0	1
TOTAL	31	30	0	0	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABANDON

WORLD TRADE CENTER  
ASBESTOS Bulk Sampling Report  
Two World Trade Center

FLOOR - 12

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	10	16	0	0	0	0
TOTAL	33	32	1	0	0	2

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT

FLOOR - 13

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	11	11	0	0	0	0
TOTAL	37	66	11	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT

FLOOR - 14

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	32	10	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOM

FLOOR - 15

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	3	0
TOTAL	32	10	12	0	3	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOM

FLOOR - 16

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	3
TOTAL	30	30	12	0	0	3

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOM

WORLD TRADE CENTER  
ASBESTOS WILK SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 17

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	3	0	0	0
TOTAL	42	30	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOI

FLOOR - 18

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	32	39	12	1	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOI

FLOOR - 19

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	3	0	0	0	3
TOTAL	58	42	14	1	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOI

FLOOR - 20

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	2	0	0	0	0
TOTAL	82	89	3	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOI

FLOOR - 21

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	33	42	13	3	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOI

PA0002570

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 22

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	48	32	16	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 23

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	32	40	12	6	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 24

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	3
TOTAL	33	40	13	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 25

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	6	0	0	0	0	0
TOTAL	32	41	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 26

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	9	9	0	0	0	0
TOTAL	73	41	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABATEMENT

WORLD TRADE CENTER  
ASBESTOS Bulk Sampling Report  
TWO WORLD TRADE CENTER

FLOOR - 27

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALL-OUT</u>	<u>OTHER</u>
POSITIVE	0	3	0	0	0	0
TOTAL	34	42	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACB

FLOOR - 28

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALL-OUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	81	73	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACB

FLOOR - 29

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALL-OUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	31	40	11	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACB

FLOOR - 30

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALL-OUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	90	78	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACB

FLOOR - 31

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALL-OUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	30	16	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACB

WORLD TRADE CENTER  
 ASBESTOS Bulk SAMPLING REPORT  
 TWO WORLD TRADE CENTER

FLOOR - 32

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALL-OUT</u>	<u>OTHER</u>
POSITIVE	2	2	0	0	0	0
TOTAL	57	43	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABANDONMENT

FLOOR - 33

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALL-OUT</u>	<u>OTHER</u>
POSITIVE	5	5	0	0	0	0
TOTAL	188	171	18	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABANDONMENT

FLOOR - 34

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALL-OUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	42	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACR

FLOOR - 35

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALL-OUT</u>	<u>OTHER</u>
POSITIVE	0	0	8	0	8	0
TOTAL	32	40	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACR

FLOOR - 36

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALL-OUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	72	40	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACR

WORLD TRADE CENTER  
ASBESTOS FIBER SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 37

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	32	40	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 38

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	32	40	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 39

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	33	41	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

FLOOR - 40

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	22	22	0	0	0	0
TOTAL	33	42	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABANDON

FLOOR - 41

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	33	31	0	1	3	0
TOTAL	133	99	0	22	14	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABANDON



WORLD TRADE CENTER  
ASSISTED BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 43

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/STAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	11	4	0	3	0	0
TOTAL	90	72		6	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: LOCALIZED ABANDONMENT

FLOOR - 44

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/STAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	33	43	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOM

FLOOR - 45

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/STAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	51	33	28	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOM

FLOOR - 46

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/STAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	5	0	5	0	0	0
TOTAL	43	42	21	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOM

FLOOR - 47

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/STAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	3	2	0	0	0
TOTAL	53	30	13	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOM

WORLD TRADE CENTER  
 ASBESTOS SOIL SAMPLING REPORT  
 TWO WORLD TRADE CENTER

FLOOR - 18

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	74	49	23	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 19

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	57	48	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 30

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	32	10	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 31

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	44	15	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 32

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	64	34	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 33

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	66	34	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 34

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	35	23	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 35

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	62	30	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 36

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	64	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 37

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	72	60	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

WORLD TRADE CENTER  
 ASBESTOS Bulk SAMPLING REPORT  
 TWO WORLD TRADE CENTER

FLOOR - 38

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 39

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	108	92	18	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 40

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	42	30	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 41

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	48	36	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 42

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	8	0	0	0
TOTAL	48	36	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

PAG002578

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
FOR WORLD TRADE CENTER

FLOOR - 63

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	63	33	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 64

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	36	41	13	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 65

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	37	42	15	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 66

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	4	6	4	0	0	0
TOTAL	36	41	13	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 67

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	7	0	7	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 66

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	5	0	5	0	8	0
TOTAL	69	37	12	0	8	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACB

FLOOR - 69

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	8	0	0
TOTAL	61	18	13	8	0	8

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACB

FLOOR - 70

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	0	3	0	0	0
TOTAL	92	30	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACB

FLOOR - 71

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	5	2	1	0	0	0
TOTAL	51	16	13	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACB

FLOOR - 72

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	0	2	0	6	0
TOTAL	44	12	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACB

WORLD TRADE CENTER  
ASBESTOS FIBER SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 73

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	2	0	2	3	0	0
TOTAL	46	34	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACR

FLOOR - 74

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	82	82	0	0	0	0
TOTAL	181	167	13	0	0	1

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABANDONMENT

FLOOR - 75

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	13	9	0	2	2	0
TOTAL	143	48	0	121	16	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: FULL ABANDONMENT

FLOOR - 77

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	47	33	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACR

FLOOR - 78

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	0	3	0	0	0
TOTAL	67	33	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACR

WORLD TRADE CENTER  
 ASSISTANT BULK SAMPLING REPORT  
 TWO WORLD TRADE CENTER

FLOOR - 79

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	11	33	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACN

FLOOR - 80

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	11	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACN

FLOOR - 81

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	0	2	0	0	0
TOTAL	11	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACN

FLOOR - 82

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	31	31	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACN

FLOOR - 83

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	11	32	12	0	3	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACN

PA0002582



WORLD TRADE CENTER  
ASBESTOS Bulk SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 84

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	44	34	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOH

FLOOR - 85

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	32	31	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOH

FLOOR - 86

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOH

FLOOR - 87

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	83	31	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOH

FLOOR - 88

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	32	30	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-AOH

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 89

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	8	0	0	0	0	0
TOTAL	32	30	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 90

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	8	0	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 91

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	0	0	0	0	0
TOTAL	32	30	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 92

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	37	35	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 93

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	3	1	0	0	0
TOTAL	47	15	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 TWO WORLD TRADE CENTER

FLOOR - 94

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	46	42	4	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 95

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	47	43	4	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 96

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	0	3	0	0	0
TOTAL	33	14	9	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 97

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	6	0	0	0	0	0
TOTAL	34	32	4	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 98

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	69	57	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 99

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	43	33	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 100

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	47	33	12	1	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 101

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	30	30	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 102

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	31	19	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 103

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	31	19	2	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

FLOOR - 104

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	43	33	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 105

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 106

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	44	32	12	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 107

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	34	34	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

FLOOR - 108

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/RVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	3	0	1	0	0
TOTAL	112	70	0	23	11	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACM

PAG0002567

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 TWO WORLD TRADE CENTER

FLOOR - 110

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	10	10	0	0	0	0

INSPECTION AND SAFETY DIVISION'S CLASSIFICATION: NON-ACH

TWO WORLD TRADE CENTER  
FLOOR: 82

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
13073	2VTC-13073	FLUTTY FALLOUT MATERIAL FROM THE FLOOR LOCATED WITHIN THE STEAM SHAFT CLOSET.	70% CHRYSOLOTE ASBESTOS
13078	2VTC-13078	FLUTTY FIBROGLASS INSULATION MATERIAL FROM A 24" O.D. HEAT TRANSFER PIPE LOCATED WITHIN THE STEAM SHAFT CLOSET.	40% CHRYSOLOTE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 84

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1174	2WTC-01174	CONDITITIOES TRAVELED ON BEAM INSULATION ABOVE ACS 13.7.	SI TRANSLITE ASBESTOS



TWO WORLD TRADE CENTER  
FLOOR, 1

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
8498	2WTC-08498	FLETTY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM ABOVE A LIGHT PICTURE LOCATED IN THE EAST SIDE OF THE MEZANINE OPPOSITE ELEVATOR NUMBER 1.	100 CHRYSOTILE ASBESTOS
8498	2WTC-08498	CONVENTIONAL INSULATION MATERIAL TROWELED ON A BEAM IN THE FLENUM ABOVE A LIGHT PICTURE LOCATED AT THE NORTH ELEVATOR BACK WALL IN THE MEZANINE.	100 CHRYSOTILE ASBESTOS
8499	2WTC-08499	FLETTY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLENUM ABOVE A LIGHT PICTURE LOCATED AT THE NORTH ELEVATOR BACK WALL IN THE MEZANINE.	100 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 6

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
92	2WTC-092CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SW 4 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
94	2WTC-094CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SE 1 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
95	2WTC-095CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SE 11 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
96	2WTC-096CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SE 14 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
97	2WTC-097CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SE 16 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
98	2WTC-098CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SE 13 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
99	2WTC-099CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SE 16 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
100	2WTC-100CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SW 16 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
101	2WTC-101CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SW 13 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
102	2WTC-102CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SW 9 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
103	2WTC-103CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SW 7 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
104	2WTC-104CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SW 12 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
105	2WTC-105CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SW 9 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
106	2WTC-106CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SE 4 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
107	2WTC-107CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SE 7 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
108	2WTC-108CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SE 10 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS
109	2WTC-109CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANDLER UNIT SE 3 IN THE CATWALK AREA.	10% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 8

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
113	2WTC-118CS	FLUFFY INSULATION MATERIAL SPRAYED ON OVER CHANGELIER UNIT # 6 IN THE CATWALK AREA.	31 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 7

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1107	2WTC-01137	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE 11800 VOLT ROOM.	52 CHRYSOTILE ASBESTOS
1108	2WTC-01138	FLUFFY INSULATION MATERIAL SPRAYED ON A TRUSS ABOVE THE 11800 VOLT ROOM.	55 CHRYSOTILE ASBESTOS
1109	2WTC-01139	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE EXHAUST FAN E 7.21 UNIT.	51 CHRYSOTILE ASBESTOS
1142	2WTC-01142	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN ABOVE EXHAUST FAN E 7.21 UNIT.	51 CHRYSOTILE ASBESTOS
1143	2WTC-01143	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE EXHAUST FAN E 7.21 UNIT.	51 CHRYSOTILE ASBESTOS
1144	2WTC-01144	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE EXHAUST FAN E 7.21 UNIT.	105 CHRYSOTILE ASBESTOS
1218	2WTC-12182	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE E 7.21 UNIT.	205 CHRYSOTILE ASBESTOS
1216	2WTC-12187	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE E 7.21 UNIT.	11 CHRYSOTILE ASBESTOS
1217	2WTC-12172	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A JOIST ABOVE E 7.21 UNIT.	201 CHRYSOTILE ASBESTOS
1217	2WTC-12171	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A JOIST ABOVE THE E 7.21 UNIT.	15 CHRYSOTILE ASBESTOS
1215	2WTC-12182	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE E 7.21 UNIT.	205 CHRYSOTILE ASBESTOS
1218	2WTC-12181	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE COLD WATER PIPE AT THE E 7.21 UNIT.	12 CHRYSOTILE ASBESTOS
1219	2WTC-12192	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE E 7.21 UNIT.	805 CHRYSOTILE ASBESTOS
1219	2WTC-12191	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE E 7.21 UNIT.	12 CHRYSOTILE ASBESTOS
1220	2WTC-12202	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE AIR DUCT OF THE E 7.21 UNIT.	101 CHRYSOTILE ASBESTOS
1220	2WTC-12201	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE AIR DUCT OF THE ACS 7.21 UNIT.	11 CHRYSOTILE ASBESTOS
1221	2WTC-12212	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE AIR DUCT OF THE E 7.21 UNIT.	135 CHRYSOTILE ASBESTOS

\* NOTE: See Asbestos Containing Material as per USEPA - see note on page 184.

TWO WORLD TRADE CENTER  
FLOOR: 7

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1221	2WTC-1221E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE AIR DUCT OF THE 7.21 UNIT.	1% CHRYSOTILE ASBESTOS
1222	2WTC-1222E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE AIR DUCT OF THE 7.21 UNIT.	40% CHRYSOTILE ASBESTOS
1222	2WTC-1222I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE AIR DUCT OF THE 7.21 UNIT.	3% CHRYSOTILE ASBESTOS
1224	2WTC-01224	FLUFFY FALLOUT MATERIAL ON TOP OF DUCT ABOVE THE E 7.21 UNIT.	30% CHRYSOTILE ASBESTOS
1224	2WTC-01224	FLUFFY FALLOUT MATERIAL ON TOP OF THE DUCT ABOVE THE E 7.21 UNIT.	30% CHRYSOTILE ASBESTOS
1227	2WTC-01227	FLUFFY FALLOUT MATERIAL ON TOP OF DUCT ABOVE THE S 7.21 UNIT.	30% CHRYSOTILE ASBESTOS
1229	2WTC-1229E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE SOUTHEAST ACS 7.8 UNIT.	30% CHRYSOTILE ASBESTOS
1229	2WTC-1229I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE SOUTHEAST ACS 7.8 UNIT.	1% CHRYSOTILE ASBESTOS
1230	2WTC-1230E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.8 UNIT.	30% CHRYSOTILE ASBESTOS
1230	2WTC-1230I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.8 UNIT.	NON ASBESTOS
1231	2WTC-1231E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A JOIST ABOVE THE ACS 7.11 UNIT.	30% CHRYSOTILE ASBESTOS
1231	2WTC-1231I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A JOIST ABOVE THE ACS 7.11 UNIT.	10% CHRYSOTILE ASBESTOS
1231	2WTC-1231E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.11 UNIT.	40% CHRYSOTILE ASBESTOS
1232	2WTC-1232I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.11 UNIT.	3% CHRYSOTILE ASBESTOS
1233	2WTC-1233E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.11 UNIT.	15% CHRYSOTILE ASBESTOS
1233	2WTC-1233I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.11 UNIT.	15% CHRYSOTILE ASBESTOS
1234	2WTC-1234E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.10 UNIT.	60% CHRYSOTILE ASBESTOS
1234	2WTC-1234I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.10 UNIT.	1% CHRYSOTILE ASBESTOS

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 186.

TWO WORLD TRADE CENTER  
FLOOR: 7

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1235	2WTC-1235E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.10 UNIT.	10% CHRYSOTILE ASBESTOS
1235	2WTC-1235I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.10 UNIT.	1% CHRYSOTILE ASBESTOS
1236	2WTC-01236	CONVENTIONAL PRE-MOLDED INSULATION MATERIAL FROM A HEAT TRANSFER PIPE ABOVE THE ACS 7.10 UNIT.	10% ANOSITE ASBESTOS
1237	2WTC-1237E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.10 UNIT.	30% CHRYSOTILE ASBESTOS
1237	2WTC-1237I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.10 UNIT.	NON ASBESTOS
1238	2WTC-1238E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM IN THE SOUTHEAST RETURN AIR FLENUM.	40% CHRYSOTILE ASBESTOS
1238	2WTC-1238I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM IN THE SOUTHEAST RETURN AIR FLENUM.	1% CHRYSOTILE ASBESTOS
1239	2WTC-1239E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM IN THE SOUTHEAST RETURN AIR FLENUM.	30% CHRYSOTILE ASBESTOS
1239	2WTC-1239I	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE ACS 7 S.E. ROOM.	10% CHRYSOTILE ASBESTOS
1242	2WTC-1242E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.12 UNIT.	60% CHRYSOTILE ASBESTOS
1242	2WTC-1242I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.12 UNIT.	10% CHRYSOTILE ASBESTOS
1243	2WTC-1243E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.12 UNIT.	50% CHRYSOTILE ASBESTOS
1243	2WTC-1243I	FLUFFY INSULATION MATERIAL ON THE METAL DECK ABOVE ACS 7.12 S.	1% CHRYSOTILE ASBESTOS
1243	2WTC-1243E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.12 UNIT.	60% CHRYSOTILE ASBESTOS
1243	2WTC-1243I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.12 UNIT.	1% CHRYSOTILE ASBESTOS
1247	2WTC-1247E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.12 UNIT.	13% CHRYSOTILE ASBESTOS
1247	2WTC-1247I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.12 UNIT.	NON ASBESTOS

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 355.

TWO WORLD TRADE CENTER  
FLOOR: 7

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1231	2WTC-1231E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A JOIST ABOVE THE ACS 7.9 UNIT.	30% CHRYSOTILE ASBESTOS
1231	2WTC-1231I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A JOIST ABOVE THE ACS 7.9 UNIT.	NON ASBESTOS
1232	2WTC-1232E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.3 UNIT.	43% CHRYSOTILE ASBESTOS
1232	2WTC-1232I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.3 UNIT.	3% CHRYSOTILE ASBESTOS
1233	2WTC-1233E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.9 UNIT.	40% CHRYSOTILE ASBESTOS TRACE AMOSITE ASBESTOS
1233	2WTC-1233I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.9 UNIT.	1% CHRYSOTILE ASBESTOS
1234	2WTC-01234	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.9 UNIT.	20% CHRYSOTILE ASBESTOS
1262	2WTC-1262E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.9 UNIT.	20% CHRYSOTILE ASBESTOS
1263	2WTC-1263E	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.3 UNIT.	1% CHRYSOTILE ASBESTOS
1263	2WTC-02164	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM IN THE SOUTHWEST RETURN AIR PLENUM.	3% CHRYSOTILE ASBESTOS
1263	2WTC-02113	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM IN THE SOUTHWEST RETURN AIR PLENUM.	20% CHRYSOTILE ASBESTOS
1263	2WTC-02116	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE SOUTHWEST RETURN AIR PLENUM.	10% CHRYSOTILE ASBESTOS
1263	2WTC-1383E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE SOUTHWEST RETURN AIR PLENUM.	10% CHRYSOTILE ASBESTOS
1263	2WTC-1383I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE SOUTHWEST RETURN AIR PLENUM.	40% CHRYSOTILE ASBESTOS
1284	2WTC-01284	FLUFFY INSULATION MATERIAL FROM A STEAM PIPE AT THE ACS 7.3 UNIT.	40% AMOSITE ASBESTOS 1% CHRYSOTILE ASBESTOS
1284	2WTC-02189	FLUFFY INSULATION MATERIAL FROM A 8" O.D. HEAT TRANSFER PIPE INSIDE ACS 7.1 AND 2 RISERS.	30% CHRYSOTILE ASBESTOS 30% AMOSITE ASBESTOS
1284	2WTC-02190	CEMENTITIOUS INSULATION MATERIAL FROM A 8" O.D. HEAT TRANSFER PIPE ELBOW INSIDE THE ACS 7.1 AND 2 RISERS.	30% CHRYSOTILE ASBESTOS 30% AMOSITE ASBESTOS

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 126.

TWO WORLD TRADE CENTER  
FLOOR: 7

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1264	2WTC-02411	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE COUPLING LOCATED INSIDE ACB 7 1-2 NORTH AND SOUTH RISERS.	80% ASBESTOS
1264	2WTC-02412	FLUFFY CONDITIONS HEAT TRANSFER PIPE INSULATION ON ELBOW OF 8" PIPE EXPOSED INSIDE ACB 7 1-2 NORTH AND SOUTH RISERS	40% CHRYSOTILE ASBESTOS 40% AMOSITE ASBESTOS
1264	2WTC-02412	FLUFFY INSULATION MATERIAL FROM A 8" O.D. HEAT TRANSFER PIPE LOCATED ACB 7 1-2 NORTH AND SOUTH STEAM RISERS.	30% CHRYSOTILE ASBESTOS 30% AMOSITE ASBESTOS
1262	2WTC-1252E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM IN THE ACB 7.9 UNIT.	30% CHRYSOTILE ASBESTOS
1263	2WTC-1253E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM IN THE ACB 7.9 UNIT.	11% CHRYSOTILE ASBESTOS *
1266	2WTC-01254	CONDENSATION INSULATION MATERIAL THROWN ON A BEAM AT THE ACB 7.3 UNIT.	32% CHRYSOTILE ASBESTOS
1267	2WTC-01267	AIR-CELL INSULATION MATERIAL ON A STEAM PIPE IN THE ACB 7.3 UNIT.	30% CHRYSOTILE ASBESTOS
1269	2WTC-1269E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACB 7.14 UNIT.	60% CHRYSOTILE ASBESTOS
1269	2WTC-1269E	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACB 7.14 UNIT.	31% CHRYSOTILE ASBESTOS
1270	2WTC-1270E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACB 7.14 DUCT UNIT.	30% CHRYSOTILE ASBESTOS
1270	2WTC-1270E	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACB 7.14 DUCT UNIT.	20% CHRYSOTILE ASBESTOS
1271	2WTC-1271E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACB 7.14 DUCT UNIT.	13% CHRYSOTILE ASBESTOS
1271	2WTC-1271E	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACB 7.14 DUCT UNIT.	11% CHRYSOTILE ASBESTOS *
1272	2WTC-1272E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACB 7.14 DUCT UNIT.	30% CHRYSOTILE ASBESTOS
1272	2WTC-1272E	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACB 7.14 DUCT UNIT.	12% CHRYSOTILE ASBESTOS *
1273	2WTC-1273E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACB 7.12 DUCT UNIT.	13% CHRYSOTILE ASBESTOS
1273	2WTC-1273E	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACB 7.12 DUCT UNIT.	11% CHRYSOTILE ASBESTOS *

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 386.



TWO WORLD TRADE CENTER  
FLOOR: 7

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1274	2WTC-1274E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.12 DUCT UNIT.	10% CHRYSOTILE ASBESTOS
1274	2WTC-1274I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.12 DUCT UNIT.	1% CHRYSOTILE ASBESTOS
1273	2WTC-1273E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.12 UNIT.	40% CHRYSOTILE ASBESTOS
1273	2WTC-1273I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.12 UNIT.	3% CHRYSOTILE ASBESTOS
1276	2WTC-1276E	FLUFFY EXTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.12 UNIT.	10% CHRYSOTILE ASBESTOS
1276	2WTC-1276I	FLUFFY INTERIOR LAYER OF INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.12 UNIT.	1% CHRYSOTILE ASBESTOS
3191	2WTC-03191	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM IN THE SOUTHWEST RETURN AIR FLENUM.	30% CHRYSOTILE ASBESTOS
3193	2WTC-03193	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.9 UNIT.	20% CHRYSOTILE ASBESTOS
3194	2WTC-03194	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 7.9 UNIT.	20% CHRYSOTILE ASBESTOS
3195	2WTC-03195	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE ACS 7.9 UNIT.	30% CHRYSOTILE ASBESTOS

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 366.

TWO WORLD TRADE CENTER  
FLOOR: 9

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
7383	2WTC-07383	CEMENTITIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT.	1-32 CHRYSOTILE ASBESTOS
7383	2WTC-10434	CEMENTITIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED IN THE NORTH WALL CONVECTOR UNIT AT SAMPLE #7383	1-32 CHRYSOTILE ASBESTOS
7383	2WTC-10435	CEMENTITIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED IN THE NORTH WALL CONVECTOR UNIT APPROXIMATELY TWO FEET EAST OF SAMPLE #7383	<1% CHRYSOTILE ASBESTOS *
7383	2WTC-10436	CEMENTITIOUS SPRAYED ON BEAM INSULATION MATERIAL EXPOSED IN THE NORTH WALL CONVECTOR UNIT APPROXIMATELY TWO FEET WEST OF SAMPLE #7383	<1% CHRYSOTILE ASBESTOS *

\* NOTE: Non Asbestos Containing Material as per USEPA - see data on page 386.

TWO WORLD TRADE CENTER  
FLOOR: 10

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1616	2WTC-01616	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	51 CHRYSOTILE ASBESTOS
1619	2WTC-01619	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	51 CHRYSOTILE ASBESTOS
1620	2WTC-01620	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	51 CHRYSOTILE ASBESTOS
1624	2WTC-01624	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	51 CHRYSOTILE ASBESTOS
1628	2WTC-01628	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	801 CHRYSOTILE ASBESTOS
1626	2WTC-01626	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	201 CHRYSOTILE ASBESTOS
1629	2WTC-01629	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
9311	2WTC-09311	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	701 CHRYSOTILE ASBESTOS
9312	2WTC-09312	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
9313	2WTC-09313	CEMENTITIOUS SPRAYED ON CONCRETE ENCASED BEAM INSULATION MATERIAL IN THE SOUTHWEST QUADRANT.	1-33 CHRYSOTILE ASBESTOS
9314	2WTC-09314	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	701 CHRYSOTILE ASBESTOS
9315	2WTC-09315	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	601 CHRYSOTILE ASBESTOS
9316	2WTC-09316	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	701 CHRYSOTILE ASBESTOS
9318	2WTC-09318	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	601 CHRYSOTILE ASBESTOS
9319	2WTC-09319	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
9320	2WTC-09320	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	701 CHRYSOTILE ASBESTOS
9321	2WTC-09321	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	701 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 10

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
9322	2WTC-09322	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
9323	2WTC-09323	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
9324	2WTC-09324	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	80% CHRYSOTILE ASBESTOS
9325	2WTC-09325	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	80% CHRYSOTILE ASBESTOS
9326	2WTC-09326	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DUCK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	70% CHRYSOTILE ASBESTOS
9327	2WTC-09327	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	70% CHRYSOTILE ASBESTOS
9328	2WTC-09328	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	70% CHRYSOTILE ASBESTOS
9329	2WTC-09329	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	80% CHRYSOTILE ASBESTOS
9330	2WTC-09330	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 12

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
2287	2WTC-02287	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF SOUTHEAST QUADRANT.	201 CHRYSOTILE ASBESTOS
2288	2WTC-02288	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	201 CHRYSOTILE ASBESTOS
2289	2WTC-02289	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	201 CHRYSOTILE ASBESTOS
2290	2WTC-02290	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	201 CHRYSOTILE ASBESTOS
2292	2WTC-02292	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	201 CHRYSOTILE ASBESTOS
2294	2WTC-02294	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	201 CHRYSOTILE ASBESTOS
2295	2WTC-02295	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
2296	2WTC-02296	FLUFFY INSULATION MATERIAL TROVELED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
2297	2WTC-02297	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
2298	2WTC-02298	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
2299	2WTC-02299	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
2300	2WTC-02300	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
2301	2WTC-02301	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	401 CHRYSOTILE ASBESTOS
2302	2WTC-02302	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	401 CHRYSOTILE ASBESTOS
2303	2WTC-02303	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	351 CHRYSOTILE ASBESTOS
2304	2WTC-02304	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	401 CHRYSOTILE ASBESTOS
2305	2WTC-02305	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	401 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 11

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
2306	2WTC-02306	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
2307	2WTC-02307	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
9299	2WTC-09299	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	80% CHRYSOTILE ASBESTOS
9300	2WTC-09300	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	80% CHRYSOTILE ASBESTOS
9301	2WTC-09301	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	70% CHRYSOTILE ASBESTOS
9302	2WTC-09302	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	70% CHRYSOTILE ASBESTOS
9305	2WTC-09305	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	90% CHRYSOTILE ASBESTOS
9304	2WTC-09304	CONDENSATION INSULATION MATERIAL TROWELED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	90% CHRYSOTILE ASBESTOS
9303	2WTC-09303	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	80% CHRYSOTILE ASBESTOS
9308	2WTC-09308	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHWEST QUADRANT.	70% CHRYSOTILE ASBESTOS
9307	2WTC-09307	FLUFFY FALLOUT MATERIAL IN THE PLENUM OF THE SOUTHWEST QUADRANT.	70% CHRYSOTILE ASBESTOS
9308	2WTC-09308	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	80% CHRYSOTILE ASBESTOS
9309	2WTC-09309	FLUFFY SPRAYED ON CONCRETE ENCASED BEAM INSULATION MATERIAL IN THE PLENUM OF THE SOUTHWEST QUADRANT.	60% CHRYSOTILE ASBESTOS
9310	2WTC-09310	CONDENSATION INSULATION MATERIAL TROWELED ON THE METAL DECK IN THE PLENUM IN THE SOUTHWEST QUADRANT.	90% CHRYSOTILE ASBESTOS
12944	2WTC-12944	CONDENSATION INSULATION MATERIAL TROWELED ON A BEAM LOCATED ON THE WEST WALL OF THE SOUTHWEST TELEPHONE CLOSET IN THE SOUTHWEST QUADRANT.	3% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 12

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1633	2WTC-01633	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	52 CHRYSOTILE ASBESTOS
1634	2WTC-01634	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	51 CHRYSOTILE ASBESTOS
1637	2WTC-01637	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	103 CHRYSOTILE ASBESTOS
1640	2WTC-01640	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	51 CHRYSOTILE ASBESTOS
1641	2WTC-01641	FLUFFY ENCAPSULATED BEAM INSULATION MATERIAL IN THE PLENUM OF THE NORTHEAST QUADRANT.	408 CHRYSOTILE ASBESTOS
1642	2WTC-01642	FLUFFY ENCAPSULATED BEAM INSULATION MATERIAL IN THE PLENUM OF THE NORTHEAST QUADRANT.	51 CHRYSOTILE ASBESTOS
1644	2WTC-01644	FLUFFY ENCAPSULATED METAL DECK INSULATION MATERIAL IN THE PLENUM OF THE SOUTHEAST QUADRANT.	401 CHRYSOTILE ASBESTOS
1645	2WTC-01645	FLUFFY ENCAPSULATED JOIST INSULATION MATERIAL IN THE PLENUM OF THE SOUTHEAST QUADRANT.	51 CHRYSOTILE ASBESTOS
1646	2WTC-01646	FLUFFY ENCAPSULATED BEAM INSULATION MATERIAL IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
1647	2WTC-01647	FLUFFY ENCAPSULATED JOIST INSULATION MATERIAL IN THE PLENUM OF THE SOUTHEAST QUADRANT.	401 CHRYSOTILE ASBESTOS
1648	2WTC-01648	FLUFFY ENCAPSULATED JOIST INSULATION MATERIAL IN THE PLENUM OF THE SOUTHWEST QUADRANT.	103 CHRYSOTILE ASBESTOS
1650	2WTC-01650	FLUFFY ENCAPSULATED BEAM INSULATION MATERIAL IN THE PLENUM OF THE SOUTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
1651	2WTC-01651	FLUFFY ENCAPSULATED BEAM INSULATION MATERIAL IN THE PLENUM OF THE SOUTHWEST QUADRANT.	102 CHRYSOTILE ASBESTOS
1653	2WTC-01653	FLUFFY ENCAPSULATED BEAM INSULATION MATERIAL IN THE PLENUM OF THE SOUTHWEST QUADRANT.	103 CHRYSOTILE ASBESTOS
1654	2WTC-01654	FLUFFY ENCAPSULATED METAL DECK INSULATION MATERIAL IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
1655	2WTC-01655	FLUFFY ENCAPSULATED BEAM INSULATION MATERIAL IN THE PLENUM OF THE NORTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS

## TWO WORLD TRADE CENTER

FLOOR: 12

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
4899	ZWTC-04899	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
4899	ZWTC-07310	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 4899.	1-12 CHRYSOTILE ASBESTOS
4899	ZWTC-07311	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 4899.	<1% CHRYSOTILE ASBESTOS
4899	ZWTC-07312	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL CEILING IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 4899.	NON ASBESTOS
4899	ZWTC-07313	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 4899.	1-33 CHRYSOTILE ASBESTOS
4899	ZWTC-14219	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM 3 FEET NORTH OF SAMPLES 4899, 7310, AND 7313.	TRACE CHRYSOTILE ASBESTOS
4899	ZWTC-14220	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM 3 FEET SOUTH OF SAMPLES 4899, 7310 AND 7313.	<1% CHRYSOTILE ASBESTOS
4899	ZWTC-14221	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM 2 FEET EAST OF SAMPLES 4899, 7310, AND 7313.	<1% CHRYSOTILE ASBESTOS
4899	ZWTC-14222	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM 3 FEET WEST SAMPLES 4899, 7310, 7313.	1-12 CHRYSOTILE ASBESTOS
7318	ZWTC-07318	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
7318	ZWTC-14231	FLUFFY INSULATION MATERIAL SPRAYED ON METAL DECK IN THE PLENUM 3 FEET NORTH OF SAMPLE 7318.	10% CHRYSOTILE ASBESTOS
7318	ZWTC-14232	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK 3 FEET SOUTH OF SAMPLE 7318.	10% CHRYSOTILE ASBESTOS
7318	ZWTC-14233	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM 3 FEET EAST OF SAMPLE 7318.	10% CHRYSOTILE ASBESTOS
7318	ZWTC-14234	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM 3 FEET WEST OF SAMPLE 7318.	20% CHRYSOTILE ASBESTOS
14223	ZWTC-14223	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	1-12 CHRYSOTILE ASBESTOS
14226	ZWTC-14226	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM 1 FOOT NORTH OF SAMPLE 7318.	10% CHRYSOTILE ASBESTOS

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 374.



TWO WORLD TRADE CENTER  
FLOOR: 14

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
7128	2WTC-07128	CONDITITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	1-3% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 19

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1229	2WTC-01228	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED IN THE PLENUM OF THE SERVICE ELEVATOR LOBBY IN THE NORTHEAST QUADRANT.	31 CHRYSOTILE ASBESTOS
1228	2WTC-09732	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SERVICE ELEVATOR LOBBY IN THE NORTHEAST QUADRANT NEAR SAMPLE 1228.	1-32 CHRYSOTILE ASBESTOS
1228	2WTC-09733	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SERVICE ELEVATOR LOBBY IN THE NORTHEAST QUADRANT NEAR SAMPLE 1228.	1-32 CHRYSOTILE ASBESTOS
1228	2WTC-09734	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SERVICE ELEVATOR LOBBY IN THE NORTHEAST QUADRANT NEAR SAMPLE 1228.	<11 CHRYSOTILE ASBESTOS *
1228	2WTC-09735	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SERVICE ELEVATOR LOBBY IN THE NORTHEAST QUADRANT NEAR SAMPLE 1228.	<11 CHRYSOTILE ASBESTOS *

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 188.

TWO WORLD TRADE CENTER  
FLOOR: 20

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1784	2WTC-01784	FLUTTY INSULATION MATERIAL SPRAYED ON A SEAM IN THE FLENUM OF THE NORTHEAST QUADRANT.	3X CHRYSOTILE ASBESTOS
1784	2WTC-09720	FLUTTY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 1784.	<12 CHRYSOTILE ASBESTOS
1784	2WTC-09721	FLUTTY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE FLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 1784.	1-33 CHRYSOTILE ASBESTOS
1784	2WTC-09722	FLUTTY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 1784.	NON ASBESTOS
1784	2WTC-09723	FLUTTY INSULATION MATERIAL SPRAYED ON A JOIST IN THE FLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 1784.	NON ASBESTOS

\* NOTE: Non Asbestos Containing Material as per USEPA - see note on page 188.

TWO WORLD TRADE CENTER  
FLOOR: 12

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1161	2WTC-04461	CERAMITIC INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	31 CERAMITIC ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 23

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1878	2WTC-07878	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	1-31 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 24

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
7871	2WTC-87871	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM EXPOSED WITHIN THE WEST WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	1-11 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 28

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3148	2WTC-03148	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHERTSOTILE ASBESTOS
3148	2WTC-07359	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE 3148.	10% CHERTSOTILE ASBESTOS
3148	2WTC-07360	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE 3148.	5% CHERTSOTILE ASBESTOS
3148	2WTC-07361	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE 3148.	10% CHERTSOTILE ASBESTOS
3148	2WTC-07362	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT NEAR SAMPLE 3148.	10% CHERTSOTILE ASBESTOS
14670	2WTC-14670	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHERTSOTILE ASBESTOS
14671	2WTC-14671	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHERTSOTILE ASBESTOS
14672	2WTC-14672	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	1-1% CHERTSOTILE ASBESTOS
14686	2WTC-14686	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHEAST QUADRANT.	40% CHERTSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 32

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
7037	ZWTC-07037	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT.	1-31 CHRYSOTILE ASBESTOS
14446	ZWTC-14446	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT.	1-31 CHRYSOTILE ASBESTOS

PA00002614



TWO WORLD TRADE CENTER  
FLOOR: 33

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
4114	2WTC-04114	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST APPROXIMATELY 13 FEET OUT FROM COLUMN #103 IN THE SOUTHWEST QUADRANT.	15 CHRYSOTILE ASBESTOS -
4114	2WTC-03239	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	TRACE CHRYSOTILE ASBESTOS -
4114	2WTC-03240	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTH SIDE OFFICE IN THE SOUTHWEST QUADRANT.	TRACE CHRYSOTILE ASBESTOS -
4114	2WTC-08802	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM NEAR SAMPLE #4114.	TRACE CHRYSOTILE ASBESTOS -
4114	2WTC-08833	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM NEAR SAMPLE #4114.	1-31 CHRYSOTILE ASBESTOS
4119	2WTC-04116	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST APPROXIMATELY 20 FEET OUT FROM COLUMN #147 IN THE NORTHWEST QUADRANT.	11 CHRYSOTILE ASBESTOS -
4119	2WTC-03248	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	80% ASBESTOS
4119	2WTC-03246	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	1-32 CHRYSOTILE ASBESTOS
4114	2WTC-08794	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT NEAR SAMPLE #4119.	TRACE CHRYSOTILE ASBESTOS
4119	2WTC-04797	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT NEAR SAMPLE #4119.	1-31 CHRYSOTILE ASBESTOS
4792	2WTC-08792	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	1-31 CHRYSOTILE ASBESTOS
9744	2WTC-09744	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	1-31 CHRYSOTILE ASBESTOS

\* NOTE: 80% Asbestos Containing Material as per USEPA - see note on page 186.

TWO WORLD TRADE CENTER  
FLOOR: 19

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
0021	1WTC-04421	CONDITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE WEST WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	81 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 40

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
4131	ZWTC-04131	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
4139	ZWTC-04139	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	13% CHRYSOTILE ASBESTOS
4141	ZWTC-04141	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	5% CHRYSOTILE ASBESTOS
4142	ZWTC-04142	FLUFFY INSULATION MATERIAL SPRAYED OVER CEMENTITIOUS TRAVELER ON BEAM INSULATION MATERIAL IN THE PLENUM OF THE NORTHWEST QUADRANT.	13% CHRYSOTILE ASBESTOS
4143	ZWTC-04143	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
4144	ZWTC-04144	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	5% CHRYSOTILE ASBESTOS
4145	ZWTC-04145	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	13% CHRYSOTILE ASBESTOS
4146	ZWTC-04146	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
4147	ZWTC-04147	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	5% CHRYSOTILE ASBESTOS
4148	ZWTC-04148	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	5% CHRYSOTILE ASBESTOS
4173	ZWTC-04173	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	13% CHRYSOTILE ASBESTOS
4475	ZWTC-04475	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	13% CHRYSOTILE ASBESTOS
4476	ZWTC-04476	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	13% CHRYSOTILE ASBESTOS
4477	ZWTC-04477	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
4478	ZWTC-04478	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
4479	ZWTC-04479	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
4483	ZWTC-04483	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	5% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 40

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
13038	2WTC-13038	FLUTTY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	3% CHRYSOTILE ASBESTOS
13039	2WTC-13039	FLUTTY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	25% CHRYSOTILE ASBESTOS
13044	2WTC-13044	FLUTTY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	1-3% CHRYSOTILE ASBESTOS
13046	2WTC-13046	FLUTTY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHWEST QUADRANT.	13% CHRYSOTILE ASBESTOS
13047	2WTC-13047	FLUTTY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 41

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
938	2WTC-00938	CEMENTITIOUS INSULATION MATERIAL FROM A PIPE ELBOW ON THE SOUTH SIDE OF THE ACS 41.11 UNIT.	31 CHRYSOTILE ASBESTOS
937	2WTC-00937	FLUFFY FALLOUT MATERIAL FOUND ON THE FLOOR ON THE SOUTHSIDE OF THE ACS 41.14 UNIT.	31 CHRYSOTILE ASBESTOS
940	2WTC-00940	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS 41.14 UNIT.	41 CHRYSOTILE ASBESTOS
1283	2WTC-01283	FLUFFY FALLOUT MATERIAL ON POUND TOP ON DOCK AT ACS 41.14 UNIT.	101 CHRYSOTILE ASBESTOS
1285	2WTC-01285	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE ACS 41.7 UNIT.	302 CHRYSOTILE ASBESTOS
1286	2WTC-01286	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE ACS 41.7 UNIT.	203 CHRYSOTILE ASBESTOS
1287	2WTC-01287	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS 41.7 UNIT.	202 CHRYSOTILE ASBESTOS
1293	2WTC-01293	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE EAST ELECTRICAL SUB-STATION.	102 CHRYSOTILE ASBESTOS
1294	2WTC-01294	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE EAST ELECTRICAL SUB-STATION.	112 CHRYSOTILE ASBESTOS
1326	2WTC-01326	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE WEST ELECTRIC SUB-STATION.	31 CHRYSOTILE ASBESTOS
1320	2WTC-01320	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE MOTOR GENERATOR ROOM.	31 CHRYSOTILE ASBESTOS
1205	2WTC-05205	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE EX 41.1 UNIT.	203 CHRYSOTILE ASBESTOS
1206	2WTC-05206	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE EX 41.3 UNIT.	202 CHRYSOTILE ASBESTOS
3207	2WTC-05207	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE WEST ELECTRICAL SUB-STATION.	202 CHRYSOTILE ASBESTOS
3208	2WTC-05208	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE WEST ELECTRICAL SUB-STATION.	203 CHRYSOTILE ASBESTOS
1209	2WTC-05209	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE DOCK OF ACS 41.4 UNIT.	202 CHRYSOTILE ASBESTOS
3210	2WTC-05210	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ON THE DUCT OF THE ACS 41.4 UNIT.	202 CHRYSOTILE ASBESTOS
1211	2WTC-05211	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST ABOVE THE DOCK OF THE ACS 41.4 UNIT.	202 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 41

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULTS
3212	2WTC-05212	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST ABOVE THE DOCT OF THE ACS 41.4 UNIT.	20% CHRYSOTILE ASBESTOS
3213	2WTC-05213	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE DOCT OF THE ACS 41.4 UNIT.	20% CHRYSOTILE ASBESTOS
3214	2WTC-05214	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE DOCT OF THE ACS 41.4 UNIT.	20% CHRYSOTILE ASBESTOS
3215	2WTC-05215	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE WEST ELECTRICAL SUB-STATION.	20% CHRYSOTILE ASBESTOS
3216	2WTC-05216	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK ABOVE THE WEST ELECTRICAL SUB-STATION.	20% CHRYSOTILE ASBESTOS
3217	2WTC-05217	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST ABOVE THE EAST ELECTRICAL SUB-STATION	20% CHRYSOTILE ASBESTOS
3218	2WTC-05218	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST ABOVE THE EAST ELECTRICAL SUB-STATION.	20% CHRYSOTILE ASBESTOS
9184	2WTC-09184	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 41.13 UNIT.	30% CHRYSOTILE ASBESTOS
9187	2WTC-09187	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 41.13 UNIT.	30% CHRYSOTILE ASBESTOS
9188	2WTC-09188	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE THE ACS 41.1 UNIT.	30% CHRYSOTILE ASBESTOS
9189	2WTC-09189	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS 41-1 UNIT.	80% CHRYSOTILE ASBESTOS
9190	2WTC-09190	FLUFFY FALLOUT MATERIAL FOUND ON TOP OF ACS 41-10 UNIT.	10% CHRYSOTILE ASBESTOS
9192	2WTC-09192	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS 41-18 UNIT.	15% CHRYSOTILE ASBESTOS
9193	2WTC-09193	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS 41-14 UNIT.	20% CHRYSOTILE ASBESTOS
9194	2WTC-09194	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS 41-14 UNIT.	20% CHRYSOTILE ASBESTOS
9195	2WTC-09195	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS 41-14 UNIT.	10% CHRYSOTILE ASBESTOS
9196	2WTC-09196	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM ABOVE ACS 41-16 UNIT.	30% CHRYSOTILE ASBESTOS

## TWO WORLD TRADE CENTER

FLOOR: 43

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
4933	2WTC-04933	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM AT THE BOTTOM OF THE ESCALATOR IN THE SOUTHWEST QUADRANT.	1-18 CHRYSOTILE ASBESTOS
4933	2WTC-03220	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	TRACE CHRYSOTILE ASBESTOS
4933	2WTC-03221	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	31 CHRYSOTILE ASBESTOS
4933	2WTC-03222	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	31 CHRYSOTILE ASBESTOS
4987	2WTC-04987	CLOTH MATERIAL CONNECTING FAN AND DUCT WORK IN FAN ROOM IN THE NORTH SIDE.	953 CHRYSOTILE ASBESTOS
4987	2WTC-03218	WOVEN BLANKET FAN DUCT WORK NORTH SIDE.	901 CHRYSOTILE ASBESTOS
4987	2WTC-03219	WOVEN BLANKET FAN DUCT WORK IN THE NORTHEAST QUADRANT.	908 CHRYSOTILE ASBESTOS
12099	2WTC-12099	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF SOUTH WALL OFFICE.	1-38 CHRYSOTILE ASBESTOS
12100	2WTC-12100	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM AT ESCALATOR LANDING IN THE SOUTHWEST QUADRANT.	31 CHRYSOTILE ASBESTOS
12101	2WTC-12101	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	1-31 CHRYSOTILE ASBESTOS
12938	2WTC-12938	FLUFFY SPRAYED ON INSULATION MATERIAL TAKEN FROM A BEAM EXPOSED IN THE SOUTH WEST TELEPHONE CLOSET.	1-38 CHRYSOTILE ASBESTOS
14007	2WTC-14007	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	108 CHRYSOTILE ASBESTOS

\* NOTE: Non Asbestos Containing Material as per ULIFA - see note on page 388.

TWO WORLD TRADE CENTER  
FLOOR: 44

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
4193	2WTC-04193	CIMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	1-12 CHRYSOTILE ASBESTOS
4194	2WTC-04194	CIMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	1-11 CHRYSOTILE ASBESTOS
4199	2WTC-04199	CIMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	1-11 CHRYSOTILE ASBESTOS
4204	2WTC-04204	CIMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM EXPOSED WITHIN THE WEST WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	1-12 CHRYSOTILE ASBESTOS
4213	2WTC-04213	CIMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	1-12 CHRYSOTILE ASBESTOS



TWO WORLD TRADE CENTER  
FLOOR: 47

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
6220	2WTC-04220	CERAMITIC INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS
6222	2WTC-04222	CERAMITIC INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	40% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR, 46

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
6242	2WTC-06242	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE WEST WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	201 CHRYSOTILE ASBESTOS
6249	2WTC-06249	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	202 CHRYSOTILE ASBESTOS
6249	2WTC-14247	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON FROM THE OUTER LAYER OF MATERIAL WITHIN CONVECTOR AT SAMPLE 6249.	251 CHRYSOTILE ASBESTOS
6249	2WTC-14246	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON FROM THE INNER LAYER OF MATERIAL WITHIN CONVECTOR AT SAMPLE 6249.	412 CHRYSOTILE ASBESTOS *

\* NOTE: Ben Asbestos Containing Material as per OSHA - see note on page 186.

TWO WORLD TRADE CENTER

FLOOR: 31

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
4428	2WTC-04428	CEMENTITIOUS INSULATION MATERIAL SPREAD ON A BEAM EXPOSED WITHIN THE WEST WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	SI CHERYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 33

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
6711	INTC-66711	CEMENTITIOUS INSULATION MATERIAL TRAPPED ON A BEAM EXPOSED WITHIN THE WEST WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	13% CHRYSOOTILE ASBESTOS

PAG002626

TWO WORLD TRADE CENTER  
FLOOR: 57

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
4461	ZWIC-06461	CONDENSITIVE INSULATION MATERIAL PROCELED ON A BEAM EXPOSED WITHIN THE WEST WALL CONVECTION UNIT IN THE SOUTHWEST QUADRANT.	1-31 CROTSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 58

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
5875	2WTC-45875	CERAMITICUS TROVELED ON INSULATION MATERIAL AT THE NORTH WALL CONVECTOR.	1-3% CHERSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 63

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
6438	2WTC-06408	CONDITIIONS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	5% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 48

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
5384	2WTC-03384	CONDITITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT.	1-32 CHRYSOTILE ASBESTOS
6419	2WTC-04419	CONDITITIOUS INSULATION MATERIAL TROWELED ON A BEAM EXPOSED WITHIN THE WEST WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	1-32 CHRYSOTILE ASBESTOS
6424	2WTC-04424	CONDITITIOUS INSULATION MATERIAL TROWELED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	1-32 CHRYSOTILE ASBESTOS
6425	2WTC-04425	CONDITITIOUS INSULATION MATERIAL TROWELED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT.	1-32 CHRYSOTILE ASBESTOS



TWO WORLD TRADE CENTER  
FLOOR: 47

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
6336	ZWTC-06336	CINDERITIOUS INSULATION MATERIAL TRAVELED ON A BEAM EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT.	1-32 CHERYSOTILE ASBESTOS
6337	ZWTC-06337	CINDERITIOUS INSULATION MATERIAL TRAVELED ON A BEAM EXPOSED WITHIN THE NORTH WALL CONVECTOR UNIT.	1-32 CHERYSOTILE ASBESTOS
6339	ZWTC-06339	CINDERITIOUS INSULATION MATERIAL TRAVELED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT.	1-32 CHERYSOTILE ASBESTOS
6341	ZWTC-06341	CINDERITIOUS INSULATION MATERIAL TRAVELED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR UNIT.	1-32 CHERYSOTILE ASBESTOS
6342	ZWTC-06342	CINDERITIOUS INSULATION MATERIAL TRAVELED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT.	1-32 CHERYSOTILE ASBESTOS
6344	ZWTC-06344	CINDERITIOUS INSULATION MATERIAL TRAVELED ON A BEAM EXPOSED WITHIN THE SOUTH WALL CONVECTOR UNIT.	1-32 CHERYSOTILE ASBESTOS
6345	ZWTC-06345	CINDERITIOUS INSULATION MATERIAL TRAVELED ON A BEAM EXPOSED WITHIN THE WEST WALL CONVECTOR UNIT.	1-32 CHERYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 48

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
6073	2WTC-06073	CEMENTITIOUS INSULATION MATERIAL TROWELED ON WITHIN THE SOUTH WALL CONVECTOR.	1-3% CHRYSOTILE ASBESTOS
6074	2WTC-06074	CEMENTITIOUS INSULATION MATERIAL TROWELED ON WITHIN THE EAST WALL CONVECTOR.	1-3% CHRYSOTILE ASBESTOS
6077	2WTC-06077	CEMENTITIOUS INSULATION MATERIAL TROWELED ON WITHIN THE NORTH WALL CONVECTOR.	1-3% CHRYSOTILE ASBESTOS
6079	2WTC-06079	CEMENTITIOUS INSULATION MATERIAL TROWELED ON WITHIN THE NORTH WALL CONVECTOR.	1-3% CHRYSOTILE ASBESTOS
6084	2WTC-06084	CEMENTITIOUS INSULATION MATERIAL TROWELED ON WITHIN THE SOUTH WALL CONVECTOR.	1-3% CHRYSOTILE ASBESTOS

PA00002632

TWO WORLD TRADE CENTER  
FLOOR: 70

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
6123	2WTC-06123	CERAMITIC INSULATION MATERIAL EXPOSED ON WITHIN THE WEST WALL CONVECTOR.	1-3% CHRYSOTILE ASBESTOS
6124	2WTC-06124	CERAMITIC INSULATION MATERIAL EXPOSED ON WITHIN THE WEST WALL CONVECTOR UNIT.	1-3% CHRYSOTILE ASBESTOS
6127	2WTC-06127	CERAMITIC INSULATION MATERIAL EXPOSED ON WITHIN THE NORTH WALL CONVECTOR.	1-3% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 71

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
4030	2WTC-04010	CONDITIOUS INSULATION MATERIAL SPRAYED ON AT THE EAST WALL IN THE NORTHEAST QUADRANT.	1-37 CHRYSOTILE ASBESTOS
4133	2WTC-04133	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	1-31 CHRYSOTILE ASBESTOS
4133	2WTC-14487	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM AT SAMPLE #4133.	<10 CHRYSOTILE ASBESTOS *
4133	2WTC-14488	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM AT SAMPLE #4133.	<10 CHRYSOTILE ASBESTOS *
4133	2WTC-14489	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM AT SAMPLE #4133.	31 CHRYSOTILE ASBESTOS

\* NOTE: Ben Asbestos Containing Material as per USEPA - see acts on page 146.

WORLD TRADE CENTER  
FLOOR: 71

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
7176	WTC-07176	CONDENSATION INSULATION MATERIAL TROVELED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR.	5% CHRYSOTILE ASBESTOS
7177	WTC-07177	CONDENSATION INSULATION MATERIAL TROVELED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR.	13% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 72

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
6014	2WTC-06014	CONDENSITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE EAST WALL CONVECTOR.	1-12 CHRYSOTILE ASBESTOS
6016	2WTC-06016	CONDENSITIOUS INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED WITHIN THE NORTH WALL CONVECTOR.	1-12 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR, 7A

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
137	2WTC-07137	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	40% CHRYSOTILE ASBESTOS
137	2WTC-07138	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	10% CHRYSOTILE ASBESTOS
137	2WTC-07139	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	10% CHRYSOTILE ASBESTOS
137	2WTC-07140	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	10% CHRYSOTILE ASBESTOS
137	2WTC-07141	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	10% CHRYSOTILE ASBESTOS
137	2WTC-07142	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	15% CHRYSOTILE ASBESTOS
137	2WTC-07143	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	15% CHRYSOTILE ASBESTOS
137	2WTC-07144	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	10% CHRYSOTILE ASBESTOS
137	2WTC-12005	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	1% CHRYSOTILE ASBESTOS
139	2WTC-12005	CONVENTIONAL INSULATION MATERIAL SPRAYED ON A BEAM AT THE NORTH WALL IN THE PLENUM OF THE OF THE NORTHEAST QUADRANT.	1% CHRYSOTILE ASBESTOS
140	2WTC-07137	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 140.	40% CHRYSOTILE ASBESTOS
140	2WTC-07138	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 140.	50% CHRYSOTILE ASBESTOS
140	2WTC-07139	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 140.	3% CHRYSOTILE ASBESTOS
140	2WTC-07140	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 140.	70% CHRYSOTILE ASBESTOS
140	2WTC-14005	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	1% CHRYSOTILE ASBESTOS
141	2WTC-07145	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 141.	10% CHRYSOTILE ASBESTOS
141	2WTC-07146	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 141.	10% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR, 74

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
137	2WTC-07137	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	40% CHRYSOTILE ASBESTOS
137	2WTC-07138	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	30% CHRYSOTILE ASBESTOS
137	2WTC-07139	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	30% CHRYSOTILE ASBESTOS
137	2WTC-07140	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	30% CHRYSOTILE ASBESTOS
137	2WTC-07141	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	30% CHRYSOTILE ASBESTOS
137	2WTC-07142	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	15% CHRYSOTILE ASBESTOS
137	2WTC-07143	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	15% CHRYSOTILE ASBESTOS
137	2WTC-07144	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 137 AND 138.	10% CHRYSOTILE ASBESTOS
137	2WTC-137C1	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	3% CHRYSOTILE ASBESTOS
139	2WTC-139C3	CERAMITIC INSULATION MATERIAL SPRAYED ON A BEAM AT THE NORTH WALL IN THE PLENUM OF THE OF THE NORTHEAST QUADRANT.	3% CHRYSOTILE ASBESTOS
140	2WTC-07157	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 140.	40% CHRYSOTILE ASBESTOS
140	2WTC-07158	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 140.	30% CHRYSOTILE ASBESTOS
140	2WTC-07159	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 140.	3% CHRYSOTILE ASBESTOS
140	2WTC-07160	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 140.	20% CHRYSOTILE ASBESTOS
140	2WTC-140C3	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	3% CHRYSOTILE ASBESTOS
141	2WTC-07145	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 141.	30% CHRYSOTILE ASBESTOS
141	2WTC-07146	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 141.	30% CHRYSOTILE ASBESTOS



TWO WORLD TRADE CENTER  
FLOOR: 7A

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
141	2WTC-07147	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 141.	101 CHRYSOTILE ASBESTOS
141	2WTC-07148	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLE 141.	101 CHRYSOTILE ASBESTOS
141	2WTC-141CS	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	12 CHRYSOTILE ASBESTOS
142	2WTC-07149	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 142 AND 143.	252 CHRYSOTILE ASBESTOS
142	2WTC-07150	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 142 AND 143.	151 CHRYSOTILE ASBESTOS
142	2WTC-07151	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 142 AND 143.	101 CHRYSOTILE ASBESTOS
142	2WTC-07152	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE NORTHEAST QUADRANT NEAR SAMPLES 142 AND 143.	202 CHRYSOTILE ASBESTOS
142	2WTC-142CS	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	11 CHRYSOTILE ASBESTOS
143	2WTC-143CS	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	201 CHRYSOTILE ASBESTOS
147	2WTC-147CS	FLUFFY FALLOUT MATERIAL IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
149	2WTC-149CS	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
152	2WTC-152CS	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OF THE SOUTHEAST QUADRANT.	201 CHRYSOTILE ASBESTOS
153	2WTC-153CS	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
157	2WTC-157CS	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	202 CHRYSOTILE ASBESTOS
160	2WTC-160CS	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
161	2WTC-161CS	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
164	2WTC-164CS	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS

PAG002638

TWO WORLD TRADE CENTER  
FLOOR 7A

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
163	2WTC-16305	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
12904	2WTC-12904	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE SOUTHWEST QUADRANT.	10% CHRYSOTILE ASBESTOS
12906	2WTC-12906	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE CORE IN THE SOUTHWEST QUADRANT.	1-3% CHRYSOTILE ASBESTOS
12908	2WTC-12908	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE CORE IN THE SOUTHWEST QUADRANT.	5% CHRYSOTILE ASBESTOS
12910	2WTC-12910	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE SOUTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
12913	2WTC-12913	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE SOUTHWEST QUADRANT.	1-3% CHRYSOTILE ASBESTOS
12916	2WTC-12916	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
12920	2WTC-12920	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
12923	2WTC-12923	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE ELECTRICAL CLOSET IN THE SOUTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
12925	2WTC-12925	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE A.C. AIR SHAFT IN THE SOUTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
12928	2WTC-12928	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE NORTHEAST QUADRANT.	10% CHRYSOTILE ASBESTOS
12929	2WTC-12929	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE NORTHEAST QUADRANT.	60% CHRYSOTILE ASBESTOS
12930	2WTC-12930	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE NORTHEAST QUADRANT.	20% CHRYSOTILE ASBESTOS
12939	2WTC-12939	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE POWER CORE OFFICE AREA IN THE NORTHEAST QUADRANT.	1-3% CHRYSOTILE ASBESTOS
12940	2WTC-12940	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE NORTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS
12941	2WTC-12941	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE NORTHEAST QUADRANT.	40% CHRYSOTILE ASBESTOS
12942	2WTC-12942	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE FLETH OF THE NORTHEAST QUADRANT.	30% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 74

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
12944	2WTC-12944	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
12945	2WTC-12945	FLUFFY SPRAYED ON BEAM INSULATION MATERIAL IN THE PLENUM NEAR THE 92ND STAIR IN THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
12946	2WTC-12946	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
12949	2WTC-12949	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM NEAR THE SOUTHWEST TELEPHONE CLOSET.	101 CHRYSOTILE ASBESTOS
12950	2WTC-12950	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM NEAR PASSENGER ELEVATOR #12 IN THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
12979	2WTC-12979	CONVENTIONAL INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	1-31 CHRYSOTILE ASBESTOS
12977	2WTC-12977	CONVENTIONAL INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	1-31 CHRYSOTILE ASBESTOS
12981	2WTC-12981	CONVENTIONAL INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	1-31 CHRYSOTILE ASBESTOS
12982	2WTC-12982	CONVENTIONAL INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT.	101 CHRYSOTILE ASBESTOS
12987	2WTC-12987	CONVENTIONAL INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE NORTHEAST QUADRANT.	101 CHRYSOTILE ASBESTOS
12993	2WTC-12993	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	201 CHRYSOTILE ASBESTOS
12994	2WTC-12994	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE NORTHWEST QUADRANT.	201 CHRYSOTILE ASBESTOS
12995	2WTC-12995	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
12996	2WTC-12996	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
12997	2WTC-12997	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
12998	2WTC-12998	FLUFFY INSULATION MATERIAL SPRAYED ON A JOIST IN THE PLENUM OF THE SOUTHWEST QUADRANT.	401 CHRYSOTILE ASBESTOS
12999	2WTC-12999	CONVENTIONAL FROCELED ON INSULATION MATERIAL TAKEN FROM A BEAM IN THE PLENUM AT SAMPLE 2WTC-12979.	101 CHRYSOTILE ASBESTOS

PAG002640

TWO WORLD TRADE CENTER  
FLOOR: 7A

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
13913	2WTC-13913	CONDITITIOUS TROWELED ON INSULATION MATERIAL TAKEN FROM THE METAL DECKING IN THE PLENUM OVER SAMPLE 2WTC-13976.	63% CHRYSOTILE ASBESTOS
13914	2WTC-13914	FLUFFY SPRAYED ON INSULATION MATERIAL TAKEN FROM THE METAL DECKING IN THE PLENUM UNDER SAMPLE 2WTC-13933.	3% CHRYSOTILE ASBESTOS
13915	2WTC-13915	CONDITITIOUS INSULATION MATERIAL TROWELED ON A BEAM IN THE PLENUM AT SAMPLE 2WTC-13977.	1-32 CHRYSOTILE ASBESTOS
13917	2WTC-13917	CONDITITIOUS INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OVER SAMPLE 2WTC-13977.	20% CHRYSOTILE ASBESTOS
13918	2WTC-13918	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM UNDER UNDER SAMPLE 2WTC-13937.	25% CHRYSOTILE ASBESTOS
13919	2WTC-13919	CONDITITIOUS INSULATION MATERIAL TROWELED ON A BEAM ON THE WALL IN THE PLENUM AT SAMPLE 2WTC-13981.	3% CHRYSOTILE ASBESTOS
13941	2WTC-13941	CONDITITIOUS SPRAYED ON INSULATION MATERIAL TAKEN FROM THE METAL DECKING IN THE PLENUM OVER SAMPLE 2WTC-13981.	40% CHRYSOTILE ASBESTOS
13942	2WTC-13942	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM UNDER UNDER SAMPLE 2WTC-13941.	1-33 CHRYSOTILE ASBESTOS
13943	2WTC-13943	CONDITITIOUS INSULATION MATERIAL TROWELED ON A BEAM IN THE PLENUM AT SAMPLE 2WTC-13982.	5% CHRYSOTILE ASBESTOS
13943	2WTC-13943	CONDITITIOUS INSULATION MATERIAL TROWELED ON THE METAL DECK IN THE PLENUM OVER SAMPLE 2WTC-13982.	40% CHRYSOTILE ASBESTOS
13944	2WTC-13944	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM UNDER UNDER SAMPLE 2WTC-13943.	20% CHRYSOTILE ASBESTOS
13947	2WTC-13947	CONDITITIOUS INSULATION MATERIAL TROWELED ON A BEAM IN THE PLENUM OVER SAMPLE 2WTC-13987.	25% CHRYSOTILE ASBESTOS
13949	2WTC-13949	CONDITITIOUS INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM OVER SAMPLE 2WTC-13987.	30% CHRYSOTILE ASBESTOS
13950	2WTC-13950	FLUFFY INSULATION MATERIAL SPRAYED ON THE METAL DECK IN THE PLENUM UNDER UNDER SAMPLE 2WTC-13949.	10% CHRYSOTILE ASBESTOS

PA0002641

TWO WORLD TRADE CENTER  
FLOOR, 73

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
1494	2WTC-01494	FLUFFY FALLOUT MATERIAL FROM THE FLOOR LOCATED NEAR THE ACS 73.3 UNIT.	10% CHRYSOTILE ASBESTOS
1531	2WTC-01531	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED NEAR SHAFT ROOM 3-1.	25% CHRYSOTILE ASBESTOS
1641	2WTC-01641	FALLOUT MATERIAL LOCATED INSIDE THE ACS 73.16 UNIT.	3% CHRYSOTILE ASBESTOS
1676	2WTC-01676	CONDENSATION INSULATION MATERIAL ENCASED ON A BEAM LOCATED ABOVE THE NORTHEAST RETURN AIR SHAFT.	25% CHRYSOTILE ASBESTOS
1677	2WTC-01677	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ABOVE THE NORTHEAST RETURN AIR SHAFT.	10% CHRYSOTILE ASBESTOS
1720	2WTC-01720	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB LOCATED ABOVE THE E.S.S. E-73-22 UNIT.	10% CHRYSOTILE ASBESTOS
1721	2WTC-01721	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ABOVE THE E.S.S. E-73-22 UNIT.	3% CHRYSOTILE ASBESTOS
1722	2WTC-01722	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB LOCATED ABOVE THE E.S.S. E-73-22 UNIT.	3% CHRYSOTILE ASBESTOS
1723	2WTC-01723	FLUFFY PRE-MOLDED INSULATION MATERIAL FROM A HEAT TRANSFER PIPE LOCATED ABOVE THE E.S.S. E-73-22 UNIT.	20% AMOSITE ASBESTOS
1724	2WTC-01724	FLUFFY PRE-MOLDED INSULATION MATERIAL FROM A HEAT TRANSFER PIPE LOCATED ABOVE THE E.S.S. E-73-22 UNIT.	30% AMOSITE ASBESTOS
1728	2WTC-01728	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB LOCATED ABOVE THE E.S.S. E-73-21 UNIT.	30% CHRYSOTILE ASBESTOS
1739	2WTC-01739	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ABOVE THE E.S.S. E-73-21 UNIT.	20% CHRYSOTILE ASBESTOS
1740	2WTC-01740	FLUFFY INSULATION MATERIAL SPRAYED ON THE CONCRETE SLAB LOCATED ABOVE THE E.S.S. E-73-21 UNIT.	40% CHRYSOTILE ASBESTOS

PAG002642

TWO WORLD TRADE CENTER  
FLOOR: 78

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
8078	IVTC-08078	CONSTITUTIONS INSULATION MATERIAL SPRAYED ON AT WEST WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	1-1% CHRYSOTILE ASBESTOS
8080	IVTC-08080	CONSTITUTIONS INSULATION MATERIAL SPRAYED ON AT EAST WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	1-1% CHRYSOTILE ASBESTOS
8083	IVTC-08083	CONSTITUTIONS INSULATION MATERIAL SPRAYED ON AT SOUTH WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT.	1-1% CHRYSOTILE ASBESTOS

PA0002043

PA0002043

TWO WORLD TRADE CENTER  
FLOOR: 79

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
8132	2WTC-08132	CEMENTITIOUS INSULATION MATERIAL SPRAYED ON AT SOUTH WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	1-12 CEMENTITIOUS ASPHALTOS

TWO WORLD TRADE CENTER  
FLOOR: 81

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
8367	2WTC-08367	CONDENSATION INSULATION MATERIAL SPRAYED ON A BEAM AT THE EAST WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT.	1-1% CHRYSOTILE ASBESTOS
8373	2WTC-08373	CONDENSATION INSULATION MATERIAL SPRAYED ON A BEAM AT THE SOUTH WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	1-1% CHRYSOTILE ASBESTOS



TWO WORLD TRADE CENTER  
FLOOR: 84

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
8813	2WTC-08613	OPACITIOUS INSULATION MATERIAL SPRAYED ON A BEAM AT THE NORTH WALL, CONVECTOR UNIT IN THE NORTHEAST QUADRANT.	1-13 CHRYSOPTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 88

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
8881	2WTC-08381	CONVENTIONAL INSULATION MATERIAL SPRAYED ON AT WEST WALL CONVECTOR UNIT IN THE NORTHWEST QUADRANT.	31 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 87

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
8661	2WTC-86661	CERAMITIC INSULATION MATERIAL SPRAYED ON A BEAM AT THE WEST WALL CONNECTOR IN THE SOUTHWEST QUADRANT.	1-11 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 93

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
8755	EWTC-88755	CONDENSIBLE INSULATION MATERIAL SPRAYED ON A BEAM AT THE WEST WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	1-35 CHRISTIANE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 94

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3474	ZWTC-03474	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM AT THE EAST WALL CONVECTOR UNIT IN THE SOUTHEAST QUADRANT.	3% CHRYSOTILE ASBESTOS
3489	ZWTC-03489	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM AT THE WEST WALL CONVECTOR UNIT IN THE SOUTHWEST QUADRANT.	3% CHRYSOTILE ASBESTOS
3703	ZWTC-03703	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM AT THE NORTH WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT.	1-3% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
FLOOR: 108

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1872	INTC-01621	CONVENTIONAL INSULATION MATERIAL TAKEN FROM A 12" O.D. ELAS TRANSFER PIPE COUPLING LOCATED IN THE NORTH CORN CORRIDOR.	30% CHRYSOTILE ASBESTOS

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
FLO WORLD TRADE CENTER

ELEVATOR SHAFT - 01

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	14

ELEVATOR SHAFT - 03

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	12

ELEVATOR SHAFT - 05

	<u>SAMPLES</u>
POSITIVE	5
TOTAL	15

ELEVATOR SHAFT - 07

	<u>SAMPLES</u>
POSITIVE	6
TOTAL	26

ELEVATOR SHAFT - 08

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	14

ELEVATOR SHAFT - 09

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	1

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

ELEVATOR SHAFT - 10

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	5

ELEVATOR SHAFT - 11

	<u>SAMPLES</u>
POSITIVE	11
TOTAL	13

ELEVATOR SHAFT - 12

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	17

ELEVATOR SHAFT - 13

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	14

ELEVATOR SHAFT - 14

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	18

ELEVATOR SHAFT - 15

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	14



WORLD TRADE CENTER  
ASBESTOS SULE SAMPLING REPORT  
TWO WORLD TRADE CENTER

ELEVATOR SHAFT - 21

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	16

ELEVATOR SHAFT - 12

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	17

ELEVATOR SHAFT - 24

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

ELEVATOR SHAFT - 29

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

ELEVATOR SHAFT - 31

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	3

ELEVATOR SHAFT - 33

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	3

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

ELEVATOR SHAFT - 38

	<u>SAMPLES</u>
POSITIVE	7
TOTAL	7

ELEVATOR SHAFT - 41

	<u>SAMPLES</u>
POSITIVE	7
TOTAL	7

ELEVATOR SHAFT - 44

	<u>SAMPLES</u>
POSITIVE	7
TOTAL	7

ELEVATOR SHAFT - 45

	<u>SAMPLES</u>
POSITIVE	2
TOTAL	6

ELEVATOR SHAFT - 49

	<u>SAMPLES</u>
POSITIVE	8
TOTAL	16

ELEVATOR SHAFT - 52

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	6

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

ELEVATOR SHAFT - 54

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

ELEVATOR SHAFT - 57

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	3

ELEVATOR SHAFT - 62

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	3

ELEVATOR SHAFT - 64

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	7

ELEVATOR SHAFT - 68

	<u>SAMPLES</u>
POSITIVE	6
TOTAL	6

ELEVATOR SHAFT - 69

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	10

WORLD TRADE CENTER  
 AIRBORNE BULK SAMPLING REPORT  
 TWO WORLD TRADE CENTER

ELEVATOR SHAFT - 74

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	7

ELEVATOR SHAFT - 75

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	4

ELEVATOR SHAFT - 78

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	4

ELEVATOR SHAFT - 81

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	5

ELEVATOR SHAFT - 85

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	5

ELEVATOR SHAFT - 87

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	7

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

ELEVATOR SHAFT - 90

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	7

ELEVATOR SHAFT - 91

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	8

ELEVATOR SHAFT - 92

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	8

PA0002658

WORLD TRADE CENTER  
ELEVATOR SHAFT, 01

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14938	WTC-14938	FLUTTY INSULATION MATERIAL SPRAYED ON THE WEST WALL ABOVE THE 10TH FLOOR.	75% CHRYSOTILE ASBESTOS

PAG002659

TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 03

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1-178	2WTC-1-178	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 7TH FLOOR.	25% CHRYSOTILE ASBESTOS
1-180	2WTC-1-180	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 13TH FLOOR.	25% CHRYSOTILE ASBESTOS
1-183	2WTC-1-183	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 23RD FLOOR.	25% CHRYSOTILE ASBESTOS
1-183	2WTC-1-183	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 28TH FLOOR.	30% CHRYSOTILE ASBESTOS
1-188	2WTC-1-188	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE EAST WALL ABOVE THE 39TH FLOOR.	25% CHRYSOTILE ASBESTOS

PAG002660

TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 10

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
12678	2WTC-12678	FLUFFY INSULATION MATERIAL SPRAYED ON THE SOUTH OF THE CONCOURSE LEVEL DOORS.	10% CHRYSOTILE ASBESTOS
12680	2WTC-12680	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE NORTHWEST CORNER.	10% CHRYSOTILE ASBESTOS
12681	2WTC-12681	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE NORTH WALL.	10% CHRYSOTILE ASBESTOS
12682	2WTC-12682	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE NORTH WALL.	5% CHRYSOTILE ASBESTOS



TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 11

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
12673	2WTC-12673	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE SOUTH WALL.	131 CHRYSOTILE ASBESTOS
12676	2WTC-12676	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE SOUTHWEST CORNER.	131 CHRYSOTILE ASBESTOS
12677	2WTC-12677	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE SOUTH WALL.	131 CHRYSOTILE ASBESTOS
14933	2WTC-14933	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE SOUTH WALL ABOVE THE 44TH FLOOR.	101 CHRYSOTILE ASBESTOS
14934	2WTC-14934	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE SOUTH WALL ABOVE THE 40TH FLOOR.	101 CHRYSOTILE ASBESTOS TRACE AMOSITE ASBESTOS
14938	2WTC-14938	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE SOUTH WALL ABOVE THE 34TH FLOOR.	201 CHRYSOTILE ASBESTOS
14940	2WTC-14940	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE SOUTH WALL ABOVE THE 38TH FLOOR.	101 CHRYSOTILE ASBESTOS
14941	2WTC-14941	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE SOUTH WALL ABOVE THE 26TH FLOOR.	501 CHRYSOTILE ASBESTOS
14942	2WTC-14942	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ON THE SOUTH WALL ABOVE THE 22ND FLOOR.	101 CHRYSOTILE ASBESTOS
14972	2WTC-14972	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE SOUTH WALL ABOVE THE 18TH FLOOR.	101 CHRYSOTILE ASBESTOS
14974	2WTC-14974	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED ON THE SOUTH WALL ABOVE THE 7TH FLOOR.	1-11 CHRYSOTILE ASBESTOS

PA0002662

WORLD TRADE CENTER  
ELEVATOR SHAFT, 1A

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
13019	WTC-13019	CONDENSATION INSULATION MATERIAL TRAPPED ON A COLUMN LOCATED ON THE SOUTH WALL ABOVE THE 11TH FLOOR.	13% CHRYSOTILE ASBESTOS
13020	WTC-13020	CONDENSATION INSULATION MATERIAL TRAPPED ON A COLUMN LOCATED ON THE SOUTH WALL ABOVE THE 4TH FLOOR.	10% CHRYSOTILE ASBESTOS
13021	WTC-13021	CONDENSATION INSULATION MATERIAL TRAPPED ON A COLUMN LOCATED ON THE SOUTH WALL ABOVE THE 1ST FLOOR.	3% CHRYSOTILE ASBESTOS

PAG002663

TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 24

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14320	1WTC-14320	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 6TH FLOOR.	5% CHRYSOTILE ASBESTOS
14321	1WTC-14321	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 9TH FLOOR ENTRANCE.	10% CHRYSOTILE ASBESTOS
14322	1WTC-14322	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 12TH FLOOR ENTRANCE.	5% CHRYSOTILE ASBESTOS
14323	1WTC-14323	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 15TH FLOOR ENTRANCE.	10% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 29

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
14324	2WTC-14324	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 13TH FLOOR.	5% CHRYSOTILE ASBESTOS
14325	2WTC-14325	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 17TH FLOOR.	5% CHRYSOTILE ASBESTOS
14326	2WTC-14326	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 11TH FLOOR ENTRANCE.	15% CHRYSOTILE ASBESTOS
14327	2WTC-14327	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 14TH FLOOR ENTRANCE.	20% CHRYSOTILE ASBESTOS

WORLD TRADE CENTER  
ELEVATOR SHAFT: 31

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
14328	2WTC-14328	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 23RD FLOOR ENTRANCE.	5% CHRYSOTILE ASBESTOS
14329	2WTC-14329	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 23TH FLOOR ENTRANCE.	10% CHRYSOTILE ASBESTOS
14330	2WTC-14330	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 17TH FLOOR ENTRANCE.	5% CHRYSOTILE ASBESTOS
14331	2WTC-14331	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 15TH FLOOR.	5% CHRYSOTILE ASBESTOS
14332	2WTC-14332	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 2ND FLOOR.	35% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 22

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14333	2WTC-14333	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 18D FLOOR.	10% CHRYSOTILE ASBESTOS
14334	2WTC-14334	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 16TH FLOOR.	15% CHRYSOTILE ASBESTOS
14335	2WTC-14335	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 19TH FLOOR ENTRANCE.	15% CHRYSOTILE ASBESTOS
14336	2WTC-14336	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 21ST FLOOR ENTRANCE.	20% CHRYSOTILE ASBESTOS
14337	2WTC-14337	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 23RD FLOOR ENTRANCE.	15% CHRYSOTILE ASBESTOS

WTC WORLD TRADE CENTER  
ELEVATOR SHAFT: 18

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
14358	WTC-14358	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 2ND FLOOR.	40% CHRYSOTILE ASBESTOS
14359	WTC-14359	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 8TH FLOOR.	70% CHRYSOTILE ASBESTOS
14360	WTC-14360	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 23RD FLOOR.	13% CHRYSOTILE ASBESTOS
14361	WTC-14361	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 25TH FLOOR ENTRANCE.	20% CHRYSOTILE ASBESTOS
14362	WTC-14362	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 28TH FLOOR ENTRANCE.	70% CHRYSOTILE ASBESTOS
14363	WTC-14363	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 30TH FLOOR ENTRANCE.	45% CHRYSOTILE ASBESTOS
14364	WTC-14364	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 32ND FLOOR ENTRANCE.	80% CHRYSOTILE ASBESTOS

PAG002658

TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 41

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14331	2WTC-14331	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 18D FLOOR.	20% CHRYSOTILE ASBESTOS
14332	2WTC-14332	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 11TH FLOOR.	10% CHRYSOTILE ASBESTOS
14333	2WTC-14333	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 18TH FLOOR.	20% CHRYSOTILE ASBESTOS
14334	2WTC-14334	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 25TH FLOOR ENTRANCE.	20% CHRYSOTILE ASBESTOS
14335	2WTC-14335	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 28TH FLOOR ENTRANCE.	10% CHRYSOTILE ASBESTOS
14336	2WTC-14336	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 30TH FLOOR ENTRANCE.	10% CHRYSOTILE ASBESTOS
14337	2WTC-14337	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 32ND FLOOR ENTRANCE.	10% CHRYSOTILE ASBESTOS



TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 1A

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1A344	2WTC-1A344	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 2ND FLOOR.	40% CHRYSOTILE ASBESTOS
1A345	2WTC-1A345	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 12TH FLOOR.	30% CHRYSOTILE ASBESTOS
1A346	2WTC-1A346	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 31ST FLOOR.	25% CHRYSOTILE ASBESTOS
1A347	2WTC-1A347	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 33RD FLOOR ENTRANCE.	5% CHRYSOTILE ASBESTOS
1A348	2WTC-1A348	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 33TH FLOOR ENTRANCE.	15% CHRYSOTILE ASBESTOS
1A349	2WTC-1A349	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 37TH FLOOR ENTRANCE.	30% CHRYSOTILE ASBESTOS
1A350	2WTC-1A350	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 39TH FLOOR ENTRANCE.	40% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 45

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14338	2WTC-14338	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 12TH FLOOR.	101 CHRYSOTILE ASBESTOS
14339	2WTC-14339	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 16TH FLOOR.	203 CHRYSOTILE ASBESTOS
14341	2WTC-14341	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 33RD FLOOR ENTRANCE.	151 CHRYSOTILE ASBESTOS
14342	2WTC-14342	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 34TH FLOOR ENTRANCE.	102 CHRYSOTILE ASBESTOS
14343	2WTC-14343	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 39TH FLOOR ENTRANCE.	231 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 54

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14369	2WTC-14369	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 45TH FLOOR.	701 CHRYSOTILE ASBESTOS
14370	2WTC-14370	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 46TH FLOOR ENTRANCE.	101 CHRYSOTILE ASBESTOS
14371	2WTC-14371	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 51ST FLOOR ENTRANCE.	151 CHRYSOTILE ASBESTOS
14372	2WTC-14372	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 54TH FLOOR ENTRANCE.	751 CHRYSOTILE ASBESTOS

PAG002672

TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 57

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14373	2WTC-14373	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 45TH FLOOR.	25% CHERYSOTILE ASBESTOS
14374	2WTC-14374	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 35TH FLOOR ENTRANCE.	40% CHERYSOTILE ASBESTOS
14375	2WTC-14375	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 37TH FLOOR ENTRANCE.	60% CHERYSOTILE ASBESTOS
14376	2WTC-14376	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 39TH FLOOR ENTRANCE.	30% CHERYSOTILE ASBESTOS
14377	2WTC-14377	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 31ST FLOOR ENTRANCE.	75% CHERYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
ELEVATOR SHAFT: 66

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
14707	2WTC-14707	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 43TH FLOOR.	50% CHRYSOTILE ASBESTOS
14708	2WTC-14708	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 51ST FLOOR.	40% CHRYSOTILE ASBESTOS
14709	2WTC-14709	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 57TH FLOOR.	30% CHRYSOTILE ASBESTOS
14710	2WTC-14710	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 63RD FLOOR ENTRANCE.	55% CHRYSOTILE ASBESTOS
14711	2WTC-14711	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 65TH FLOOR ENTRANCE.	3% CHRYSOTILE ASBESTOS
14712	2WTC-14712	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 67TH FLOOR ENTRANCE.	30% CHRYSOTILE ASBESTOS

PAG002674

WORLD TRADE CENTER  
ASBESTOS SOIL SAMPLING REPORT  
TWO WORLD TRADE CENTER

ELEVATOR FITS - 01-02

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	3

ELEVATOR FITS - 03-04

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	2

ELEVATOR FITS - 05

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	1

ELEVATOR FITS - 06-07

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	2

ELEVATOR FITS - 16-17

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	2

ELEVATOR FITS - 18-19

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	3

WORLD TRADE CENTER  
 ASBESTOS Bulk SAMPLING REPORT  
 TWO WORLD TRADE CENTER

ELEVATOR PIT - 20-21

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	1

ELEVATOR PIT - 21-23

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT - 27

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	2

ELEVATOR PIT - 28-29

	<u>SAMPLES</u>
POSITIVE	2
TOTAL	3

ELEVATOR PIT - 30-31

	<u>SAMPLES</u>
POSITIVE	4
TOTAL	4

ELEVATOR PIT - 32

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

PA0002675

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 TWO WORLD TRADE CENTER

ELEVATOR PIT - 33

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR FITS - 34-35

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	3

ELEVATOR PIT - 36

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	3

ELEVATOR FITS - 37-38

	<u>SAMPLES</u>
POSITIVE	3
TOTAL	3

ELEVATOR FITS - 39-40

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	3

ELEVATOR PIT - 41

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	3



WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TWO WORLD TRADE CENTER

ELEVATOR PIT - 41

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT - 43-44

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT - 45-46

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT - 47

	<u>SAMPLES</u>
POSITIVE	1
TOTAL	1

ELEVATOR PIT - 48

	<u>SAMPLES</u>
POSITIVE	2
TOTAL	2

ELEVATOR PIT - 49

	<u>SAMPLES</u>
POSITIVE	0
TOTAL	1

TWO WORLD TRADE CENTER  
ELEVATOR FITS: 1A-25

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1032	EWTC-03032	FLUTTY FALLOUT MATERIAL FROM THE FLOOR LOCATED AT THE 31 LEVEL.	15% CHRYSOTILE ASBESTOS
1033	EWTC-03033	FLUTTY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 31 LEVEL.	15% CHRYSOTILE ASBESTOS

PAG002678

TWO WORLD TRADE CENTER  
ELEVATOR PITS, 18-19

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1028	2WTC-01018	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 18 LEVEL.	15% CHRYSOTILE ASBESTOS
1030	1WTC-01010	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 18 LEVEL.	15% CHRYSOTILE ASBESTOS

PAG0002679

TWO WORLD TRADE CENTER  
ELEVATOR FITS: 30-31

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULTS</u>
23-7	2WTC-02347	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 31 LEVEL.	13% CHRYSOTILE ASBESTOS
23-8	2WTC-02348	CONVENTIONAL INSULATION MATERIAL TROWELED ON A COLUMN LOCATED AT THE 31 LEVEL.	13% CHRYSOTILE ASBESTOS
23-9	2WTC-02349	FLUFFY FALLOUT MATERIAL FROM THE FLOOR LOCATED AT THE 31 LEVEL.	10% CHRYSOTILE ASBESTOS
23-10	2WTC-02350	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 31 LEVEL.	10% CHRYSOTILE ASBESTOS

PAG002600

TWO WORLD TRADE CENTER  
ELEVATOR PIT: 12

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
2367	WTC-02367	FALLOUT MATERIAL FROM THE ELEVATOR PIT FLOOR LOCATED AT THE 12 LEVEL.	15% CHRYSOTILE ASBESTOS

PAG002681

TWO WORLD TRADE CENTER  
ELEVATOR PIT: 33

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
2348	2WTC-02348	FALLOUT MATERIAL FROM THE ELEVATOR PIT FLOOR LOCATED AT THE 33 LEVEL.	31 CRYSTALLINE AIRBORNE

FAC002002

TWO WORLD TRADE CENTER  
ELEVATOR FITS. 1A-1B

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
2551	INTC-0531	FIBRE INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 81 LEVEL.	100 CHRYSOTILE ASBESTOS

PA0002633

TWO WORLD TRADE CENTER  
ELEVATOR PIT: 16

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1048	2WTC-01048	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 13 LEVEL.	100% CHRYSOTILE ASBESTOS

PAG0002684



TWO WORLD TRADE CENTER  
ELEVATOR PIT: 37-38

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
2334	2WTC-02334	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 31 LEVEL.	10% CHRYSOTILE ASBESTOS
2333	2WTC-02333	CONDENSATION INSULATION MATERIAL TRAPPED ON A COLUMN LOCATED AT THE 31 LEVEL.	13% CHRYSOTILE ASBESTOS
2334	2WTC-02334	FLUFFY FALLOUT MATERIAL FROM THE FLOOR LOCATED AT THE 31 LEVEL.	20% CHRYSOTILE ASBESTOS

PA0002685

TWO WORLD TRADE CENTER  
ELEVATOR FITS: 39-40

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
2337	WTC-02337	FLOTTY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 31 LEVEL.	31 CHRYSOTILE ASBESTOS
2338	WTC-02338	FLOTTY INSULATION MATERIAL SPRAYED ON COLUMN LOCATED AT THE 31 LEVEL.	131 CHRYSOTILE ASBESTOS

PA0002686

TWO WORLD TRADE CENTER  
ELEVATOR PIT: 41

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3302	1970-01132	FLUTTY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 33 LEVEL.	100 PERCENTILE ASBESTOS

PAG0002687

TWO WORLD TRADE CENTER  
ELEVATOR PIT: 42

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3308	2WTC-03308	FLUTTY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 81 LEVEL.	152 CHRYSOTILE ASBESTOS
3310	2WTC-03310	FALL-OUT MATERIAL FROM THE ELEVATOR PIT FLOOR LOCATED AT THE 81 LEVEL.	131 CHRYSOTILE ASBESTOS

PA0002608

TWO WORLD TRADE CENTER  
ELEVATOR FITS. 43-44

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
3037	2WTC-03037	FLOTTY FALLOUT MATERIAL FROM THE FLOOR LOCATED AT THE 81 LEVEL.	12% CHRYSOTILE ASBESTOS
3038	2WTC-03038	FLOTTY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 81 LEVEL.	10% CHRYSOTILE ASBESTOS

PA0002689

TWO WORLD TRADE CENTER  
ELEVATOR FITS: 45-46

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
303A	ZWTC-0303A	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 81 LEVEL.	13% CHRYSOTILE ASBESTOS
303B	ZWTC-0303B	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 81 LEVEL.	13% CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
ELEVATOR PIT: 47

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULTS
3303	2WTC-03303	FLEET INSULATION MATERIAL STRIPPED ON A COLUMN LOCATED AT THE 47 LEVEL.	131 CHRYSOTILE ASBESTOS

TWO WORLD TRADE CENTER  
ELEVATOR PIT: 48

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
2344	2WTC-02244	FLUFFY INSULATION MATERIAL SPRAYED ON A COLUMN LOCATED AT THE 48 LEVEL.	10% CHRYSOTILE ASBESTOS
2345	2WTC-02245	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED AT THE 48 LEVEL.	10% CHRYSOTILE ASBESTOS



WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
TOWER WORLD TRADE CENTER

FLOORS WITH NON-ACM CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACM SAMPLES</u>
1	10	10

PA0002693

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 THREE WORLD TRADE CENTER

FLOOR - 1

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALL OUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	10	10	0	0	0	0

PAG002694

WORLD TRADE CENTER  
ASBESTOS FIBER SAMPLING REPORT  
FOUR WORLD TRADE CENTER

FLOORS WITH SCF-ACH CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACH SAMPLES</u>
2	43	43
3	43	43
4	43	43
5	43	43
6	46	46
7	41	41
8	30	30
9	43	43

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 FOUR WORLD TRADE CENTER

FLOOR - 2

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	43	43	0	2	0	0

FLOOR - 3

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	43	43	0	0	0	0

FLOOR - 4

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	43	43	0	0	0	0

FLOOR - 5

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	43	43	0	0	0	0

FLOOR - 6

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	20	20	0	0	0	0

PA0002696

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 FOUR WORLD TRADE CENTER

FLOOR - 7

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	4	0	0	0	0	0
TOTAL	41	41	0	0	0	0

FLOOR - 8

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	10	10	0	0	0	0

FLOOR - 9

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	43	43	0	17	1	0

PA0002697

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
FIVE WORLD TRADE CENTER

FLOORS WITH NON-ACM CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACM SAMPLES</u>
1	28	28
2	94	94
3	92	92
4	84	84
5	111	111
7	98	98
8	89	89

WORLD TRADE CENTER  
 ASBESTOS SOIL SAMPLING REPORT  
 FIVE WORLD TRADE CENTER

FLOOR - 1

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	28	20	0	10	0	0

FLOOR - 2

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	0	0	3	0	0
TOTAL	18	94	0	8	0	0

FLOOR - 3

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	92	92	0	0	0	0

FLOOR - 4

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	1	0	0	0
TOTAL	90	84	8	0	0	0

FLOOR - 5

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	6	8	0	0	0	0
TOTAL	102	96	6	0	0	0

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 FIVE WORLD TRADE CENTER

FLOOR - 6

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	111	111	0	0	0	0

FLOOR - 7

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	98	98	0	0	0	0

FLOOR - 8

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	90	89	0	1	0	0

FLOOR - 9

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	3	1	0	2	0	0
TOTAL	132	89	0	33	9	1

PAG002699



FIVE WORLD TRADE CENTER

FLOOR: 2

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
10776	SWTC-13776	CEMENTITIOUS INSULATION MATERIAL TAKEN FROM A HEAT TRANSFER PIPE ELBOW LOCATED IN THE NORTHWEST QUADRANT OF THE EAST WING.	801 CHRYSOTILE ASBESTOS
13369	SWTC-13369	FIBROUS PRE-WOLDED INSULATION MATERIAL TAKEN FROM AN EXPOSED DUCT LOCATED IN SHAFT NO. 4A OF THE WEST WING.	302 CHRYSOTILE ASBESTOS
13370	SWTC-13370	CEMENTITIOUS INSULATION MATERIAL TROWELED ON AN EXPOSED DUCT LOCATED IN SHAFT NO. 4A OF THE WEST WING.	301 CHRYSOTILE ASBESTOS

FIVE WORLD TRADE CENTER  
FLOOR: 4

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
10302	SWTC-10302	CEMENTITIOUS INSULATION MATERIAL TROWELED ON A BEAM AT THE EAST WALL CONVECTOR UNIT IN THE NORTHEAST QUADRANT OF THE SOUTH WING.	1-11 CROTSOLITE ASBESTOS

FIVE WORLD TRADE CENTER  
FLOOR: 5

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
11048	SWTC-11048	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT OF THE SOUTH WING.	70% CHRYSOTILE ASBESTOS
11048	SWTC-14294	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT OF THE SOUTH WING.	NON ASBESTOS
11048	SWTC-14297	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT OF THE SOUTH WING.	70% CHRYSOTILE ASBESTOS
11048	SWTC-14298	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT OF THE SOUTH WING.	25% CHRYSOTILE ASBESTOS
11048	SWTC-14299	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT OF THE SOUTH WING.	33% CHRYSOTILE ASBESTOS
11048	SWTC-14300	CONVENTIONAL INSULATION MATERIAL TROWELED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT OF THE SOUTH WING.	75% CHRYSOTILE ASBESTOS
11048	SWTC-14301	CONVENTIONAL INSULATION MATERIAL TROWELED ON A BEAM IN THE PLENUM OF THE SOUTHWEST QUADRANT OF THE SOUTH WING.	70% CHRYSOTILE ASBESTOS

FIVE WORLD TRADE CENTER  
FLOOR: 9

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
2270	SWTC-02270	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE LOCATED WEST OF AGE-9-1N UNIT IN THE MECHANICAL EQUIPMENT ROOM.	40% AMOSITE ASBESTOS 60% CHERYSOTILE ASBESTOS
2273	SWTC-02273	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE LOCATED WEST OF THE RETURN AIR SHAFT.	60% CHERYSOTILE ASBESTOS
2274	SWTC-02274	CONVENTIONAL INSULATION MATERIAL TROVELED ON A BEAM WEST OF THE RETURN AIR SHAFT.	50% CHERYSOTILE ASBESTOS

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
SIX WORLD TRADE CENTER

FLOORS WITH NON-ACM CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACM SAMPLES</u>
2	10	10

PA0002704

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 SIX WORLD TRADE CENTER

FLOOR - 2

	<u>SAMPLES</u>	<u>CYLING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	10	10	0	0	0	0

PAG002705

WORLD TRADE CENTER  
ASBESTOS SOLE SAMPLING REPORT  
NORTHEAST N.Y.C. SUBLEVELS

FLOORS WITH NON-ACM CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACM SAMPLES</u>
11	19	19
12	90	90
14	73	73

PAG002706

WORLD TRADE CENTER  
 ASBESTOS SOLE SAMPLING REPORT  
 NORTHEAST W.T.C. SUBLEVELS

FLOOR - B1

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	1	0	0	1	0	0
TOTAL	43	19	0	20	6	0

FLOOR - B2

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	93	90	0	3	0	0

FLOOR - B4

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	73	73	0	0	0	0



NORTHEAST W.T.C. SURVEILLS

FLOOR: R1

<u>AREA</u> <u>NUMBER</u>	<u>SAMPLE</u> <u>NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
1088	SUTC-01088	CONDOTTIOUS INSULATION MATERIAL FROM A HEAT TRANSFER PIPE ELBOW AT SUT-12-1A UNIT IN THE MECHANICAL EQUIPMENT ROOM.	5% CHRYSOOTILE ASBESTOS

PA0002708

WORLD TRADE CENTER  
ASBESTOS SULK SAMPLING REPORT  
NORTHWEST W.T.C. SUBLEVELS

FLOORS WITH NON-ACH CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACH SAMPLES</u>
83	28	28

PA0002709

WORLD TRADE CENTER  
ASBESTOS SULK SAMPLING REPORT  
NORTHWEST W.T.C. SUBLEVELS

FLOOR - 81

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	28	27	0	1	0	0
TOTAL	88	77	0	10	1	0

FLOOR - 82

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	14	10	0	3	1	0
TOTAL	34	40	0	13	1	0

FLOOR - 83

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	41	28	0	12	1	0

FLOOR - 84

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	4	3	0	1	0	0
TOTAL	30	23	0	4	1	0

FLOOR - 85

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	3	0	0	1	0	0

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 NORTHWEST W.T.C. SUBLEVELS

FLOOR - 34

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/MEAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	13	0	0	13	0	0

PAG002711

NORTHWEST W.T.C. STREVEVELS  
FLOOR: 81

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
477	1WTC-00477	CONDITIOUS INSULATION MATERIAL TROWELED ON A BEAM LOCATED NEAR THE BARCLAY STREET RAMP.	51 CHRYSOTILE ASBESTOS
478	1WTC-00478	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED NEAR THE BARCLAY STREET RAMP.	51 CHRYSOTILE ASBESTOS
481	1WTC-00481	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED NEAR THE BARCLAY STREET RAMP.	51 CHRYSOTILE ASBESTOS
483	1WTC-00483	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED NEAR THE BARCLAY STREET RAMP.	101 CHRYSOTILE ASBESTOS
485	1WTC-00485	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED NEAR THE BARCLAY STREET RAMP.	101 CHRYSOTILE ASBESTOS
487	1WTC-00487	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED NEAR THE BARCLAY STREET RAMP.	51 CHRYSOTILE ASBESTOS
488	1WTC-00488	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED NEAR THE BARCLAY STREET RAMP.	51 CHRYSOTILE ASBESTOS
489	1WTC-00489	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED NEAR THE BARCLAY STREET RAMP.	51 CHRYSOTILE ASBESTOS
492	1WTC-00492	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED WITHIN THE ENVELOPE VENDING ROOM.	201 CHRYSOTILE ASBESTOS
493	1WTC-00493	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED WITHIN THE ENVELOPE VENDING ROOM.	201 CHRYSOTILE ASBESTOS
494	1WTC-00494	CONDITIOUS INSULATION MATERIAL FROM A 4" O.D. HEAT TRANSFER PIPE COUPLING LOCATED WITHIN THE ENVELOPE VENDING ROOM.	101 CHRYSOTILE ASBESTOS
10464	1WTC-10464	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE EAST SIDE OF THE W.T.C. MAINTENANCE STOCKROOM.	251 CHRYSOTILE ASBESTOS
10465	1WTC-10465	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE SOUTH SIDE OF THE W.T.C. MAINTENANCE STOCKROOM.	101 CHRYSOTILE ASBESTOS
10466	1WTC-10466	CONDITIOUS INSULATION MATERIAL TROWELED ON A BEAM EXPOSED AT THE SOUTH SIDE OF THE W.T.C. MAINTENANCE STOCKROOM.	101 CHRYSOTILE ASBESTOS
10467	1WTC-10467	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE SOUTH WEST CORNER OF THE W.T.C. MAINTENANCE STOCKROOM.	101 CHRYSOTILE ASBESTOS
10469	1WTC-10469	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE WEST SIDE OF THE W.T.C. MAINTENANCE STOCKROOM.	101 CHRYSOTILE ASBESTOS
10470	1WTC-10470	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE NORTH SIDE OF THE W.T.C. MAINTENANCE STOCKROOM AT COLUMN J-21.	401 CHRYSOTILE ASBESTOS

NORTHWEST W.T.C. SUBLEVEL  
FLOOR: 31

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
10471	1WTC-10471	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE NORTH SIDE OF THE W.T.C. MAINTENANCE STOCKROOM.	15% CHRYSOTILE ASBESTOS
10472	1WTC-10472	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE NORTH SIDE OF THE W.T.C. STOCKROOM.	20% CHRYSOTILE ASBESTOS
10474	1WTC-10474	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED EAST OF COLUMN J-21 IN THE W.T.C. MAINTENANCE STOCKROOM.	40% CHRYSOTILE ASBESTOS
10473	1WTC-10473	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE WEST SIDE OF THE W.T.C. MAINTENANCE STOCKROOM.	40% CHRYSOTILE ASBESTOS
10479	1WTC-10479	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM EXPOSED AT THE SOUTH SIDE OF THE W.T.C. MAINTENANCE STOCKROOM.	70% CHRYSOTILE ASBESTOS
13872	6WTC-13872	FLUFFY INSULATION MATERIAL SPRAYED ON AN EXPOSED BEAM LOCATED ABOVE THE TRUCK DOCK AREA NEAR COLUMN J72-4.	30% CHRYSOTILE ASBESTOS
14250	6WTC-14250	FLUFFY INSULATION MATERIAL SPRAYED ON AN EXPOSED BEAM LOCATED IN THE OLD U.S. CUSTOMS HOUSE PARKING AREA NEAR COLUMN J1-4.	2-5% CHRYSOTILE ASBESTOS
14252	6WTC-14252	FLUFFY INSULATION MATERIAL SPRAYED ON AN EXPOSED BEAM LOCATED IN THE OLD U.S. CUSTOMS HOUSE PARKING AREA NEAR COLUMN J2-4.	50% CHRYSOTILE ASBESTOS
14253	6WTC-14253	FLUFFY INSULATION MATERIAL SPRAYED ON AN EXPOSED BEAM LOCATED ABOVE THE BARCLAY STREET RAMP NEAR COLUMN J1-20.	40% CHRYSOTILE ASBESTOS
14496	6WTC-14496	FLUFFY INSULATION MATERIAL SPRAYED ON AN EXPOSED BEAM LOCATED AT THE EAST WALL SOUTH OF COLUMN J12-8.	33% CHRYSOTILE ASBESTOS
14499	6WTC-14499	FLUFFY INSULATION MATERIAL SPRAYED ON AN EXPOSED BEAM SOUTH OF COLUMN J12-1.	40% CHRYSOTILE ASBESTOS

PA0002713

NORTHWEST W.T.C. SUBLEVELS  
FLOOR 12

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
	639	1WTC-00639 FLUFFY INSULATION MATERIAL SPRAYED ON A TRUSS LOCATED AT COLUMN J3-4.	10% CHRYSOTILE ASBESTOS
	640	1WTC-00640 FLUFFY INSULATION MATERIAL SPRAYED ON A TRUSS LOCATED AT COLUMN J4-4.	10% CHRYSOTILE ASBESTOS
	641	1WTC-00641 CONVENTIONAL INSULATION MATERIAL TRAVELED ON A BEAM LOCATED AT COLUMN J2-7.	3% CHRYSOTILE ASBESTOS
	642	1WTC-00642 FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED BETWEEN COLUMNS J2-7 AND J3-4.	15% CHRYSOTILE ASBESTOS
	646	1WTC-00646 FLUFFY FALLOUT MATERIAL FROM THE FLOOR LOCATED NEAR COLUMN J3-4.	15% CHRYSOTILE ASBESTOS
	648	1WTC-00648 CONVENTIONAL INSULATION MATERIAL FROM A HEAT TRANSFER PIPE ELBOW LOCATED BY COLUMN J7-12.	15% AMOSITE ASBESTOS 3% CHRYSOTILE ASBESTOS
	649	1WTC-00649 CONVENTIONAL INSULATION MATERIAL FROM A HEAT TRANSFER PIPE LOCATED BY COLUMN J8-10.	15% CHRYSOTILE ASBESTOS
	670	1WTC-40670 FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE LOCATED BY COLUMN J9-8.	15% CHRYSOTILE ASBESTOS
13277	0WTC-13277	FLUFFY INSULATION MATERIAL SPRAYED ON AN EXPOSED TRUSS IN THE PARKING AREA NEAR COLUMN J4-1.	30% CHRYSOTILE ASBESTOS
13280	0WTC-13280	FLUFFY INSULATION MATERIAL SPRAYED ON AN EXPOSED TRUSS LOCATED IN THE PARKING AREA NEAR COLUMN J3-4.	45% CHRYSOTILE ASBESTOS
13281	0WTC-13281	FLUFFY INSULATION MATERIAL SPRAYED ON AN EXPOSED BEAM LOCATED IN THE PARKING AREA BETWEEN COLUMNS J3-4 AND J4-1.	20% CHRYSOTILE ASBESTOS
13284	0WTC-13284	CONVENTIONAL INSULATION MATERIAL TRAVELED ON AN EXPOSED BEAM LOCATED NEAR RAMP "B" BY COLUMN J72-6.	3% CHRYSOTILE ASBESTOS
13296	0WTC-13296	FLUFFY INSULATION MATERIAL SPRAYED ON AN EXPOSED BEAM LOCATED IN THE PARKING AREA NEAR COLUMN J73-8.	1-1% CHRYSOTILE ASBESTOS
13299	0WTC-13299	CONVENTIONAL INSULATION MATERIAL TRAVELED ON AN EXPOSED BEAM LOCATED IN THE PARKING AREA NEAR COLUMN J73-7.	3% CHRYSOTILE ASBESTOS

NORTHWEST V.T.C. SUBLEVELS  
FLOOR: 34

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
617	1WTC-00617	FLUFFY SPRAYED ON TROSS INSULATION MATERIAL BETWEEN COLUMNS J-1-10 AND J-8-10.	5% CHRYSOTILE ASBESTOS
821	1WTC-00621	FALLOUT MATERIAL FROM TROSS BETWEEN COLUMNS J-5-14 AND J-8-12.	5% CHRYSOTILE ASBESTOS
825	1WTC-00626	FLUFFY INSULATION MATERIAL SPRAYED ON COLUMN J-75-2.	50% CHRYSOTILE ASBESTOS
627	1WTC-00627	TROWELED ON PATCH INSULATION MATERIAL ON A BEAM NEAR COLUMN J-75-2.	5% CHRYSOTILE ASBESTOS
825	1WTC-00628	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM NEAR COLUMN J-74-2.	25% CHRYSOTILE ASBESTOS
825	1WTC-00629	CONVENTIONAL INSULATION MATERIAL ON A PIPE AT COLUMN J-6-10.	25% CHRYSOTILE ASBESTOS

PA0002715



WORLD TRADE CENTER  
ASBESTOS SOIL SAMPLING REPORT  
SOUTHEAST W.T.C. SUBLEVELS

FLOORS WITH NON-ACM CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACM SAMPLES</u>
21	24	24
22	28	28
24	27	27

PAG002716

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 SOUTHEAST W.T.C. SUBLEVELS

FLOOR - 31

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	37	24	0	23	8	0

FLOOR - 32

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	96	86	0	12	0	0

FLOOR - 34

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/HVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	27	27	0	0	0	0

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING REPORT  
SOUTHWEST W.T.C. SUBLEVELS

FLOORS WITH NON-ACM CEILING STRUCTURES

<u>FLOOR</u>	<u>SAMPLES</u>	<u>NON-ACM SAMPLES</u>
13	11	11
14	3	3
16	10	10

PA0002718

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 SOUTHWEST W.T.C. SUBLEVELS

FLOOR - B1

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	10	16	0	14	0	0
TOTAL	253	183	0	63	3	0

FLOOR - B2

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	4	2	0	2	0	0
TOTAL	43	23	0	12	0	0

FLOOR - B3

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	28	11	0	17	0	0

FLOOR - B4

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	19	3	0	7	0	0

FLOOR - B5

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	19	0	0	19	0	0

PAG002719

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 SOUTHWEST W.T.C. SUBLEVELS

FLOOR - 86

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	18	0	0	28	0	0
TOTAL	88	10	0	78	0	0

SOUTHWEST W.T.C. SPILLEVELS  
FLOOR: 21

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
784	1WTC-00784	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE POLICE TERMINAL ROOM.	10% CHRYSOTILE ASBESTOS
785	1WTC-00785	FLUFFY INSULATION MATERIAL FROM A 8" O.D. HEAT TRANSFER PIPE LOCATED IN THE POLICE TERMINAL ROOM.	10% AMOSITE ASBESTOS 5% CHRYSOTILE ASBESTOS
786	1WTC-00786	FLUFFY INSULATION MATERIAL FROM A 8" O.D. HEAT TRANSFER PIPE LOCATED IN THE POLICE TERMINAL ROOM.	25% AMOSITE ASBESTOS
789	1WTC-00789	FLUFFY INSULATION MATERIAL FROM A 8" O.D. HEAT TRANSFER PIPE LOCATED IN THE POLICE CORRIDOR.	10% AMOSITE ASBESTOS
814	1WTC-00814	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE PLENUM OF THE INTELCO CORRIDOR.	15% CHRYSOTILE ASBESTOS
815	1WTC-00815	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED WITHIN THE INTELCO ENGINEERING SHOP.	15% CHRYSOTILE ASBESTOS
816	1WTC-00816	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED WITHIN THE INTELCO ENGINEERING SHOP.	20% CHRYSOTILE ASBESTOS
818	1WTC-00818	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED WITHIN THE INTELCO ENGINEERING SHOP.	15% CHRYSOTILE ASBESTOS
820	1WTC-00820	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE PLENUM OF THE INTELCO LOCKER AREA.	55% CHRYSOTILE ASBESTOS
822	1WTC-00822	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE PLENUM OF INTELCO LOCKER AREA.	10% CHRYSOTILE ASBESTOS
823	1WTC-00823	FLUFFY INSULATION MATERIAL LOCATED IN THE PLENUM OF THE INTELCO CORRIDOR.	20% CHRYSOTILE ASBESTOS
826	1WTC-00826	FLUFFY FALLOUT INSULATION MATERIAL LOCATED WITHIN THE INTELCO COLD KITCHEN.	10% CHRYSOTILE ASBESTOS
827	1WTC-00827	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE PLENUM OF THE INTELCO COLD KITCHEN CLOSET.	15% CHRYSOTILE ASBESTOS
840	1WTC-00840	FLUFFY INSULATION MATERIAL FROM A 8" O.D. HEAT TRANSFER PIPE LOCATED WITHIN THE INTELCO CANNED FOOD STORAGE ROOM.	50% AMOSITE ASBESTOS 10% CHRYSOTILE ASBESTOS
878	1WTC-00878	FLUFFY INSULATION MATERIAL FROM A 8" O.D. HIGH PRESSURE STEAM PIPE LOCATED ABOVE THE LOADING DOCK PLATFORM.	10% AMOSITE ASBESTOS 5% CHRYSOTILE ASBESTOS
887	1WTC-00887	CONDENSATION INSULATION MATERIAL FROM A HIGH PRESSURE STEAM PIPE ELBOW LOCATED ABOVE THE LOADING DOCK PLATFORM.	20% AMOSITE ASBESTOS
888	1WTC-00888	CONDENSATION INSULATION MATERIAL FROM A 12" O.D. HIGH PRESSURE STEAM PIPE LOCATED ABOVE THE LOADING DOCK PLATFORM.	60% AMOSITE ASBESTOS

PAG002721

SOUTHWEST V.T.C. SUBLEVELS  
FLOOR: 21

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
9017	QVTC-09017	CONVENTIONAL INSULATION MATERIAL FROM A 24" O.D. HEAT TRANSFER PIPE GATE VALVE STEM LOCATED WITHIN THE TRUCK DOCK AREA VALVE ROOM.	70% CHRYSOTILE ASBESTOS
13219	QVTC-13219	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED ABOVE THE EXIST SIDE OF RAMP "M".	40% CHRYSOTILE ASBESTOS
13221	QVTC-13221	FLUFFY INSULATION MATERIAL SPRAYED ON A CONCRETE SLAB LOCATED ABOVE THE EXIST SIDE OF RAMP "M".	30% CHRYSOTILE ASBESTOS
13237	QVTC-13237	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED NEAR THE VISTA HOTEL GENERAL STORAGE ROOM.	33% CHRYSOTILE ASBESTOS
13238	QVTC-13238	FLUFFY INSULATION MATERIAL SPRAYED ON A BEAM LOCATED IN THE VISTA HOTEL GENERAL STORAGE ROOM.	35% CHRYSOTILE ASBESTOS
13243	QVTC-13243	CONVENTIONAL INSULATION MATERIAL FROM A 4" D.D. HEAT TRANSFER PIPE VALVE LOCATED IN THE NORTHEAST CORNER OF THE DIESEL MECHANICAL EQUIPMENT ROOM.	80% CHRYSOTILE ASBESTOS
13254	QVTC-13254	CONVENTIONAL INSULATION MATERIAL FROM A 4" O.D. HEAT TRANSFER PIPE COUPLING LOCATED ON THE LARGE DUCT IN THE DIESEL MECHANICAL EQUIPMENT ROOM.	30% CHRYSOTILE ASBESTOS
14301	QVTC-14301	FLUFFY INSULATION MATERIAL FROM A PAD COVERING A 6" O.D. HEAT TRANSFER PIPE LOCATED WEST OF THE ENTRANCE TO THE ELEVATOR MACHINE ROOM.	1-3% AMOSITE ASBESTOS
14313	QVTC-14313	FLUFFY INSULATION MATERIAL FROM A PRE-MOLDED 18" O.D. HEAT TRANSFER PIPE LOCATED IN THE NORTHEAST CORNER OF THE FIRE COMMAND STATION.	15% AMOSITE ASBESTOS 41% CHRYSOTILE ASBESTOS
15234	QVTC-15234	FIBROUS PRE-MOLDED INSULATION MATERIAL FROM A 20" O.D. HEAT TRANSFER PIPE LOCATED AT THE TRUCK DOCK AREA VALVE ROOM.	90% AMOSITE ASBESTOS
15235	QVTC-15235	FIBROUS PRE-MOLDED INSULATION MATERIAL FROM A 24" O.D. HEAT TRANSFER PIPE LOCATED AT THE TRUCK DOCK AREA VALVE ROOM.	70% CHRYSOTILE ASBESTOS
15237	QVTC-15237	FIBROUS PRE-MOLDED INSULATION MATERIAL FROM A 20" O.D. HEAT TRANSFER PIPE LOCATED AT THE TRUCK DOCK AREA VALVE ROOM.	85% AMOSITE ASBESTOS
15240	QVTC-15240	FIBROUS PRE-MOLDED INSULATION MATERIAL FROM A 24" D.D. HEAT TRANSFER PIPE LOCATED AT THE TRUCK DOCK AREA VALVE ROOM.	90% AMOSITE ASBESTOS

PAG002722

SOUTHWEST W.T.C. SUBLEVELS  
FLOOR 32

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
13304	OWTC-13304	CENTENTIIONS INSULATION MATERIAL TROWELED ON AN EXPOSED BEAM LOCATED IN THE PARKING AREA NEAR COLUMN K75.19.	51 CHRYSOTILE ASBESTOS
13313	OWTC-13313	CENTENTIIONS INSULATION MATERIAL TROWELED ON AN EXPOSED BEAM LOCATED IN THE PARKING AREA NEAR COLUMN K76.4.	701 CHRYSOTILE ASBESTOS
13321	OWTC-13321	CENTENTIIONS INSULATION MATERIAL TAKEN FROM A 9" O.D. HEAT TRANSFER PIPE ELBOW LOCATED ABOVE THE EXIT LANE ALONG THE SOUTH WALL OF TOWER ONE.	1-11 CHRYSOTILE ASBESTOS
13322	OWTC-13322	FIBROUS PRE-MOLDED INSULATION MATERIAL TAKEN FROM A 10" O.D. HEAT TRANSFER PIPE LOCATED ABOVE THE EXIT LANE ALONG THE SOUTH WALL OF TOWER ONE.	1-11 AMOSTIX ASBESTOS



SOUTHWEST V.I.C. SUBLEVELS  
FLOOR: 56

AREA NUMBER	SAMPLE NUMBER	LOCATION	RESULT
180	1WTC-00160	CEMENTITIOUS INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
182	1WTC-00162	CEMENTITIOUS INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
183	1WTC-00163	FLUFFY INSULATION MATERIAL IN THE SOUTHWEST CORNER OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
184	1WTC-00164	FLUFFY INSULATION MATERIAL AT THE WEST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
185	1WTC-00165	FLUFFY INSULATION MATERIAL IN THE CEILING OF THE MAINTENANCE STOREROOM.	52 AMOSITE ASBESTOS
186	1WTC-00166	FLUFFY INSULATION MATERIAL IN THE CEILING OF THE MAINTENANCE STOREROOM.	52 AMOSITE ASBESTOS
187	1WTC-00167	FLUFFY INSULATION MATERIAL IN THE CEILING OF THE MAINTENANCE STOREROOM.	52 AMOSITE ASBESTOS
188	1WTC-00168	FLUFFY INSULATION MATERIAL IN THE CEILING OF THE MAINTENANCE STOREROOM.	52 AMOSITE ASBESTOS
275	1WTC-00275	FLUFFY INSULATION MATERIAL AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
276	1WTC-00276	FLUFFY INSULATION MATERIAL AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
279	1WTC-00279	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
280	1WTC-00280	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
281	1WTC-00281	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
283	1WTC-00283	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
287	1WTC-00287	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
289	1WTC-00289	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
291	1WTC-00291	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
291	1WTC-00293	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS
294	1WTC-00294	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	52 AMOSITE ASBESTOS

SOUTHWEST U.T.C. TUNNELS  
FLOOR: 86

<u>AREA NUMBER</u>	<u>SAMPLE NUMBER</u>	<u>LOCATION</u>	<u>RESULT</u>
295	1WTC-00295	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	SI AMOSITE ASBESTOS
296	1WTC-00296	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	SI AMOSITE ASBESTOS
300	1WTC-00300	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	SI CHRYSOTILE ASBESTOS
301	1WTC-00301	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	SI AMOSITE ASBESTOS
307	1WTC-00307	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	SI AMOSITE ASBESTOS
309	1WTC-00309	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	SI AMOSITE ASBESTOS
311	1WTC-00311	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	SI CHRYSOTILE ASBESTOS
312	1WTC-00312	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	SI AMOSITE ASBESTOS
313	1WTC-00313	FLUFFY INSULATION MATERIAL FROM A HEAT TRANSFER PIPE AT THE EAST WALL OF THE STEAM METER ROOM.	SI CHRYSOTILE ASBESTOS

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING REPORT  
 RIVER WATER PUMPING STATION

FLOOR - 1507

	<u>SAMPLES</u>	<u>CEILING STRUCTURES</u>	<u>CONVECTOR UNITS</u>	<u>PIPING/EVAC</u>	<u>FALLOUT</u>	<u>OTHER</u>
POSITIVE	0	0	0	0	0	0
TOTAL	0	0	0	0	0	0

PA0002726

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING SUMMARY  
 CONCOURSE

TOTAL SAMPLES	POSITIVE SAMPLES	TOTAL CEILING SAMPLES	POSITIVE CEILING SAMPLES	TOTAL PIPING/DUCT SAMPLES	POSITIVE PIPING/DUCT SAMPLES	TOTAL FALLOUT SAMPLES	POSITIVE FALLOUT SAMPLES	TOTAL TILE/OTHER SAMPLES	POSITIVE TILE/OTHER SAMPLES
199	10	170	0	21	10	7	0	1	0

Page No. 1  
03/10/88

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
ONE WORLD TRADE CENTER

	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE
FLOOR SAMPLES	CEILING SAMPLES	CEILING SAMPLES	CONVECTOR SAMPLES	CONVECTOR SAMPLES	PIPING/DUCT SAMPLES	PIPING/DUCT SAMPLES	FALLOUT SAMPLES	FALLOUT SAMPLES	TILE/OTHER SAMPLES	TILE/OTHER SAMPLES	TILE/OTHER SAMPLES	TILE/OTHER SAMPLES
31	86	47	38	44	0	0	23	1	1	1	4	1
32	20	8	9	9	0	0	10	1	1	1	0	0
33	2	1	0	0	0	0	1	1	0	0	1	0
34	4	1	0	0	0	0	2	1	1	0	1	3
35	11	0	3	0	0	0	8	0	0	0	0	0
36	137	42	81	10	0	0	99	8	7	4	0	0
1	11	3	9	1	0	0	2	3	0	0	0	0
2	20	17	20	17	0	0	0	0	0	0	0	0
3	15	15	15	15	0	0	0	0	0	0	0	0
4	12	10	12	10	0	3	0	0	0	0	0	0
5	13	9	12	9	0	0	0	0	0	0	0	0
6	33	27	33	27	0	0	0	0	0	0	0	0
7	84	37	39	31	0	3	43	4	2	2	0	0
8	18	7	16	8	2	1	0	0	0	0	0	0
10	23	21	23	21	0	0	0	0	2	0	0	0
11	21	14	21	14	0	9	0	8	0	0	0	0
12	20	14	15	12	1	1	0	3	0	0	4	1
13	47	32	33	30	12	1	9	0	0	0	0	0
14	18	14	18	12	2	2	0	8	0	0	1	0
15	19	12	18	12	2	0	0	0	0	0	1	0
16	33	21	23	21	3	0	0	3	0	0	0	0
17	47	24	33	24	12	0	0	9	0	0	0	0
18	24	16	19	14	1	1	0	0	0	3	4	1

PA0002728

Page No. 2  
03/10/88

WORLD TRADE CENTER  
ASBESTOS FGLX SAMPLING SUMMARY  
ONE WORLD TRADE CENTER

		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE	
	TOTAL POSITIVE	CEILING	CEILING	CONVECTOR	CONVECTOR	PIPING/DUCT	PIPING/DUCT	FALLOUT	FALLOUT	TILE/OTHER	TILE/OTHER		
FLOOR	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES		
19	48	33	36	33	12	0	0	0	0	0	0	0	0
20	21	9	17	9	1	0	0	0	0	0	1	0	0
21	43	23	22	25	8	8	0	0	0	0	1	0	0
22	43	29	28	29	3	8	0	0	0	8	2	3	3
23	28	14	27	14	0	4	0	0	0	0	1	0	0
24	38	40	48	39	12	1	0	0	0	0	0	0	0
25	42	31	40	32	2	0	0	0	0	3	0	0	0
26	23	17	20	13	1	0	0	0	0	0	2	2	2
27	54	34	42	34	12	0	0	0	0	0	0	0	0
28	27	21	24	21	0	0	0	0	0	0	1	0	0
29	12	8	12	8	0	0	0	0	0	0	0	0	0
30	52	27	40	27	12	0	0	0	0	0	0	0	0
31	33	32	31	32	4	0	0	0	0	0	0	0	0
32	142	29	142	29	3	0	0	0	0	0	0	0	0
33	64	13	32	13	12	0	0	0	0	0	0	0	0
34	19	7	18	7	0	0	0	0	0	0	1	0	0
35	47	26	33	38	12	0	0	0	0	8	0	0	0
36	47	27	33	28	12	1	0	0	0	0	0	0	0
37	97	39	84	39	13	0	0	0	0	0	0	0	0
38	78	2	47	2	9	0	0	0	0	0	2	0	0
39	47	2	41	2	4	0	0	0	0	0	0	0	0
40	81	33	33	33	7	0	0	0	0	0	3	0	0
41	83	18	30	3	0	0	32	4	2	1	1	1	1

Page No. 3  
03/13/00

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
ONE WORLD TRADE CENTER

		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE	
	TOTAL POSITIVE	CEILING	CEILING	CONVECTION	CONVECTION	PIPING/DOCT	PIPING/DOCT	FALLOUT	FALLOUT	TILE/OTHER	TILE/OTHER		
FLOOR SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES		
12	30	0	35	0	12	0	0	0	3	0	0	0	0
44	48	1	33	0	12	0	1	1	0	0	0	0	3
45	49	0	48	0	1	0	0	0	0	0	0	0	0
46	30	0	28	0	2	0	0	0	0	0	0	0	0
47	30	0	29	0	1	0	0	0	0	0	0	0	0
48	77	0	74	0	3	0	0	0	0	0	0	0	0
49	38	0	36	0	2	0	0	0	0	0	0	0	0
50	53	0	41	0	12	0	0	0	0	0	0	0	0
52	40	0	44	0	2	0	0	0	0	0	0	0	0
52	64	0	52	0	12	0	0	0	0	0	0	0	0
53	44	0	32	0	12	0	0	0	0	0	0	0	0
54	60	0	57	0	3	0	0	0	0	0	0	0	0
55	41	0	40	0	1	0	0	0	0	0	0	0	0
58	44	2	32	0	12	2	0	0	0	0	0	0	0
57	33	1	42	0	12	1	0	0	0	0	0	0	0
58	44	0	32	0	12	0	0	0	0	0	0	0	0
59	44	0	32	0	12	0	0	0	0	0	0	0	0
60	44	0	32	0	12	0	0	0	0	0	0	0	0
61	42	0	40	0	2	0	0	0	0	0	0	0	0
62	44	0	44	0	0	0	0	0	0	0	0	0	0
63	47	0	32	0	13	0	0	0	0	0	0	0	0
84	31	0	31	0	0	0	0	0	0	0	0	0	0
63	47	2	47	0	20	2	0	0	0	0	0	0	0

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
ONE WORLD TRADE CENTER

	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE
FLOOR SAMPLES	CEILING SAMPLES	CEILING SAMPLES	CONVECTOR SAMPLES	CONVECTOR SAMPLES	PIPING/DOCT SAMPLES	PIPING/DOCT SAMPLES	FALLOUT SAMPLES	FALLOUT SAMPLES	FILE/OTHER SAMPLES	FILE/OTHER SAMPLES	FILE/OTHER SAMPLES	FILE/OTHER SAMPLES
66	42	0	42	0	0	0	0	0	0	0	0	0
67	50	0	47	0	3	0	0	0	0	0	0	0
68	41	0	41	0	0	0	0	0	0	0	0	0
69	31	0	31	0	0	0	0	0	0	0	0	0
70	43	0	43	0	0	0	0	0	0	0	0	0
71	38	0	38	0	0	0	0	0	0	0	0	0
72	68	4	64	4	0	0	0	0	0	0	0	0
73	54	1	50	0	4	1	0	0	0	0	0	0
74	29	20	29	20	0	0	0	0	0	0	0	3
75	90	18	32	0	0	0	11	10	17	2	3	0
77	44	2	32	0	12	2	0	0	0	0	3	0
78	53	0	41	0	12	0	0	0	0	0	0	0
79	45	1	33	0	12	1	0	0	0	0	0	0
80	47	0	41	0	6	0	0	0	0	0	0	0
81	48	0	45	0	2	0	1	0	0	0	0	0
82	46	18	96	18	0	0	0	0	0	0	0	0
83	58	3	56	3	2	0	0	0	0	0	0	0
84	43	0	42	0	1	0	0	0	0	0	0	0
85	44	0	32	0	12	0	0	0	0	0	0	0
86	23	0	25	0	0	0	0	0	0	0	0	0
87	39	0	38	0	1	0	0	0	0	0	0	0
88	44	1	32	0	12	1	0	0	0	0	0	0
89	44	0	32	0	11	0	0	0	0	0	0	0



Page No. 3  
03/10/88

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
ONE WORLD TRADE CENTER

	TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE	
	FLOOR	SAMPLES	CEILING	CEILING	CONVECTOR	CONVECTOR	PIPING/DOCT	PIPING/DOCT	FALLOUT	FALLOUT	PILE/OTHER	PILE/OTHER
	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES
80	44	0	32	0	12	0	0	0	0	0	0	0
81	31	8	30	0	1	0	0	0	0	0	0	0
82	32	0	30	0	2	0	0	0	0	0	0	0
83	26	0	23	0	3	0	0	0	0	0	0	0
84	43	0	31	0	12	0	0	3	0	0	0	0
93	44	0	32	0	12	0	0	0	0	0	0	0
86	33	0	37	0	16	0	0	8	0	0	0	0
97	44	2	32	0	12	2	0	6	0	0	0	0
98	63	0	32	0	11	0	0	3	0	0	0	0
89	44	0	32	0	12	0	0	0	0	0	0	0
100	37	0	43	0	12	0	0	0	0	0	0	0
101	43	1	33	0	12	1	0	0	0	0	0	0
102	40	2	60	2	0	0	0	0	0	0	0	0
103	44	2	32	0	12	2	0	0	0	0	0	0
104	63	16	82	16	3	0	0	0	0	0	0	0
105	44	1	40	0	4	1	0	0	0	0	0	0
106	66	1	34	0	12	1	0	0	0	0	0	0
107	31	30	39	23	12	3	0	0	0	0	0	0
108	83	3	31	0	8	0	33	3	9	0	0	0
110	7	8	7	0	0	0	0	0	0	0	0	0
*** Total ***												
	3180	1043	4173	860	603	31	318	38	43	11	17	3

Page No. 1  
02/10/88

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
ONE WORLD TRADE CENTER  
ELEVATOR SHAFTS

ELEVATOR SHAFT	TOTAL SAMPLES	POSITIVE SAMPLES
01	8	8
03	18	18
04	10	1
05	13	4
07	24	3
08	28	24
09	4	4
10	13	13
12	4	4
13	19	13
15	19	7
16	17	3
18	17	6
20	16	3
23	14	14
25	4	4
26	18	17
29	4	4
31	6	6
33	6	6
37	3	3
39	3	3
43	6	6

Page No. 2  
07/10/88

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
ONE WORLD TRADE CENTER  
ELEVATOR SHAFTS

ELEVATOR SHAFT	TOTAL SAMPLES	POSITIVE SAMPLES
47	8	8
48	7	7
49	13	11
52	3	3
55	3	3
57	4	4
61	4	4
65	4	3
66	5	4
70	3	0
73	3	3
74	2	0
79	2	0
81	6	0
82	2	0
83	2	0
84	3	0
85	2	0
86	3	0
89	4	0
91	4	0
93	4	0
98	4	0

Page No. 3  
83/10/88

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
ONE WORLD TRADE CENTER  
ELEVATOR SHAFTS

ELEVATOR SHAFT	TOTAL SAMPLES	POSITIVE SAMPLES
*** Total ***	389	238

PA0002735

Page No. 1  
03/10/88

WORLD TRADE CENTER  
ASBESTOS DULK SAMPLING SUMMARY  
ONE WORLD TRADE CENTER  
ELEVATOR PITS

ELEVATOR PIT	TOTAL SAMPLES	POSITIVE SAMPLES
03-04	2	2
06-09	1	1
10-11	1	1
12-13	1	1
14-15	26	20
20-21	2	1
24	1	1
25-26	1	1
29	1	1
30	1	1
33-34	1	1
35	1	1
37-38	1	1
39-40	2	1
43-44	2	2
45-46	2	2
*** Total ***	50	36

Page 86. 1  
03/10/88

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
TWO WORLD TRADE CENTER

	TOTAL POSITIVE FLOOR SAMPLES	TOTAL POSITIVE CEILING SAMPLES	TOTAL POSITIVE CEILING CONVECTOR SAMPLES	TOTAL POSITIVE CONVECTOR SAMPLES	TOTAL POSITIVE PIPING/DUCT SAMPLES	TOTAL POSITIVE PIPING/DUCT SAMPLES	TOTAL POSITIVE FALLOUT SAMPLES	TOTAL POSITIVE FALLOUT SAMPLES	TOTAL POSITIVE TILE/OTHER SAMPLES	TOTAL POSITIVE TILE/OTHER SAMPLES
81	93	0	77	0	0	0	15	0	1	0
82	19	2	8	1	0	0	11	1	0	0
83	3	0	1	0	0	0	2	0	0	0
84	21	0	1	0	0	0	20	0	0	0
88	44	1	28	1	0	0	18	0	0	0
1	12	3	12	3	0	0	0	0	0	0
2	3	0	3	0	0	0	0	0	0	0
3	13	0	33	0	0	0	0	0	0	0
4	26	0	26	0	0	0	0	0	0	0
5	21	0	18	0	0	0	0	0	2	0
6	22	18	22	18	0	0	0	0	0	0
7	163	75	127	65	0	0	27	7	8	1
9	74	2	38	0	16	2	0	0	0	2
10	31	28	30	28	0	0	0	0	0	1
11	31	32	30	32	0	0	0	0	0	1
12	33	16	32	16	1	0	0	0	0	2
13	77	11	88	11	11	0	0	0	0	0
14	32	1	40	8	12	1	8	8	0	0
15	32	0	40	0	12	0	0	8	0	0
16	30	0	38	0	12	0	0	0	0	0
17	62	0	30	0	12	0	0	8	0	0
18	32	0	38	0	12	0	1	0	0	0
19	38	3	42	1	16	0	1	0	0	0

Page No. 2  
03/10/88

WORLD TRADE CENTER  
ASBESTOS RULE SAMPLING SUMMARY  
TWO WORLD TRADE CENTER

		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE	
		CEILING	CEILING	CONVECTOR	CONVECTOR	PIPING/DUCT	PIPING/DUCT	FALLOUT	FALLOUT	TILE/OTHER	TILE/OTHER		
FLOOR	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES
20	92	2	89	2	3	0	0	0	0	0	0	0	0
21	32	0	42	8	13	0	0	0	0	0	0	0	0
22	60	1	32	0	16	1	0	0	0	0	0	0	0
23	32	1	40	0	12	1	0	0	0	0	0	0	0
24	33	1	40	0	12	1	0	0	0	0	0	0	0
25	31	0	41	0	12	0	0	0	0	0	0	0	0
26	73	9	81	9	12	0	0	0	0	0	0	0	0
27	34	0	42	0	12	0	0	0	0	0	0	0	0
28	83	0	73	0	12	0	0	0	0	0	0	0	0
29	31	0	40	0	11	0	0	0	0	0	0	0	0
30	90	4	78	0	12	0	0	0	0	0	0	0	0
31	30	0	38	0	12	0	0	0	0	0	0	0	0
32	37	2	43	2	12	0	0	0	0	0	0	0	0
33	189	3	171	3	18	0	0	0	0	0	0	0	0
34	44	0	42	0	2	0	0	0	0	0	0	0	0
35	32	0	40	0	12	0	0	0	0	0	0	0	0
36	72	8	60	0	12	8	0	0	0	0	0	0	0
37	32	0	40	0	12	0	0	0	0	0	0	0	0
38	32	0	48	0	12	0	0	0	0	0	0	0	0
39	33	1	41	0	12	1	0	0	0	0	3	0	0
40	33	22	43	22	12	0	0	0	0	0	0	0	0
41	133	33	99	31	0	0	22	1	14	3	0	0	0
42	90	11	72	8	12	0	6	3	0	0	0	0	0

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
TWO WORLD TRADE CENTER

		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE	
		FLOOR SAMPLES	CEILING SAMPLES	CEILING SAMPLES	CONVECTOR SAMPLES	CONVECTOR SAMPLES	PIPING/DOCT SAMPLES	PIPING/DOCT SAMPLES	FALLOUT SAMPLES	FALLOUT SAMPLES	TILE/OTHER SAMPLES
44	53	0	43	0	12	0	0	0	0	0	0
45	61	0	35	0	26	0	0	0	0	0	0
46	63	3	42	0	21	3	0	0	0	0	0
47	63	2	50	0	15	2	0	0	0	0	0
48	74	3	49	0	25	3	0	0	0	0	0
49	57	0	45	0	12	0	0	0	0	0	0
50	52	0	40	0	12	0	0	0	0	0	0
51	46	1	33	0	13	1	0	0	0	0	0
52	48	0	36	0	12	0	0	0	0	0	0
53	44	1	34	0	12	1	0	0	0	0	0
54	35	0	23	0	12	0	0	0	0	0	0
55	62	0	30	0	12	0	0	0	0	0	0
56	64	0	32	0	12	0	0	0	0	0	0
57	72	2	60	0	12	1	0	0	0	0	0
58	44	0	32	0	12	0	0	0	0	0	0
59	108	1	92	0	16	1	0	0	0	0	0
60	42	0	30	0	12	0	0	0	0	0	0
61	40	0	26	0	12	0	0	0	0	0	0
62	40	0	36	0	12	0	0	0	0	0	0
63	63	0	33	0	12	0	0	0	0	0	0
64	56	0	41	0	13	0	0	0	0	0	0
65	37	1	42	0	13	1	0	0	0	0	0
66	56	4	41	0	13	4	0	0	0	0	0



Page No. 4  
03/10/88

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
TWO WORLD TRADE CENTER

		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE	
		CEILING	CEILING	CONVECTOR	CONVECTOR	PIPING/DUCT	PIPING/DUCT	FALLOUT	FALLOUT	TILE/OTHER	TILE/OTHER		
FLOOR	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES
67	46	7	32	0	12	7	0	0	0	0	0	0	0
68	49	3	37	0	12	3	0	0	0	0	0	0	0
69	81	0	48	0	13	0	0	0	0	0	0	0	0
70	82	3	30	0	12	3	0	0	0	0	0	0	0
71	31	3	38	2	13	1	0	0	0	0	0	0	0
72	44	2	32	0	12	2	0	0	0	0	0	0	0
73	46	2	34	0	12	2	0	0	0	0	0	0	0
74	181	82	147	82	13	0	0	0	0	0	1	0	0
75	183	13	48	8	0	0	101	2	14	2	0	0	0
77	47	0	33	0	12	0	0	0	0	0	0	0	0
78	47	3	33	0	12	3	0	0	0	0	0	0	0
79	44	1	32	0	12	1	0	0	0	0	0	0	0
80	44	0	32	0	12	0	0	0	0	0	0	0	0
81	44	2	32	0	12	2	0	0	0	0	0	0	0
82	31	0	31	0	0	0	0	0	0	0	0	0	0
83	44	0	32	0	12	0	0	0	0	0	0	0	0
84	48	1	34	0	12	1	0	0	0	0	0	0	0
85	32	0	31	0	1	0	0	0	0	0	0	0	0
86	44	1	32	0	12	1	0	0	0	0	0	0	0
87	43	1	31	0	12	1	0	0	0	0	0	0	0
88	32	3	30	0	2	0	0	0	0	0	0	0	0
89	31	0	30	0	2	0	0	0	0	0	0	0	0
90	44	0	32	0	12	0	0	0	0	0	0	0	0

Page No. 3  
03/10/88

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
TWO WORLD TRADE CENTER

		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE	
FLOOR	SAMPLES	CEILING	CEILING	CONVECTOR	CONVECTOR	PIPING/DUCT	PIPING/DUCT	FALLOUT	FALLOUT	FIRE/OTHER	FIRE/OTHER	SAMPLES	SAMPLES
91	51	0	30	0	2	0	0	0	0	0	0	0	0
92	37	0	33	0	2	0	0	0	0	0	0	0	0
93	47	1	33	0	13	1	0	0	0	0	0	0	0
94	18	0	42	0	6	0	0	0	0	0	0	0	0
95	47	0	43	0	4	0	0	0	0	0	0	0	0
96	33	3	44	0	9	3	0	0	0	0	0	0	0
97	36	0	32	0	4	0	0	0	0	0	0	0	0
98	69	0	37	0	12	0	0	0	0	0	0	0	0
99	43	0	33	0	12	0	0	0	0	0	0	0	0
100	47	0	33	0	12	0	3	0	0	0	0	0	0
101	30	0	30	0	0	0	0	0	0	3	0	0	0
102	31	0	49	0	3	0	0	0	0	0	0	0	0
103	31	0	49	0	2	0	0	0	0	0	0	0	0
104	63	0	33	0	12	0	0	0	0	0	0	0	0
105	44	0	33	0	12	0	0	0	0	0	0	0	0
106	44	0	32	0	13	0	0	0	0	0	0	0	0
107	34	0	34	0	0	0	0	0	0	0	0	0	0
108	112	2	70	0	0	0	23	1	11	0	0	0	0
110	18	0	18	0	0	0	0	0	0	0	0	0	0
--- Total ---													
	9335	430	3167	340	1024	30	232	13	32	0	10	0	0

PAG002741

Page No. 1  
03/10/88

WORLD TRADE CENTER  
ASBESTOS SOLE SAMPLING SUMMARY  
TWO WORLD TRADE CENTER  
ELEVATOR SHAFTS

ELEVATOR SHAFT	TOTAL SAMPLES	POSITIVE SAMPLES
01	14	0
03	12	1
05	13	3
07	26	0
08	18	0
09	3	0
10	3	4
12	15	11
13	17	0
14	14	3
16	18	0
18	14	0
21	16	0
23	17	0
24	4	4
29	4	4
31	3	3
33	3	3
38	7	7
41	7	7
44	7	7
45	4	3
49	16	0

Page No. 2  
03/10/88

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
TWO WORLD TRADE CENTER  
ELEVATOR SHAFTS

ELEVATOR SHAFT	TOTAL SAMPLES	POSITIVE SAMPLES
32	4	0
34	4	4
37	3	3
42	3	0
44	7	0
46	6	6
48	10	0
74	7	0
75	4	0
76	4	0
81	3	0
83	3	0
87	7	0
90	7	0
82	6	0
98	8	0
*** Total ***	277	82

Page No. 1  
03/10/86

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
TWO WORLD TRADE CENTER  
ELEVATOR PITS

ELEVATOR PIT	TOTAL SAMPLES	POSITIVE SAMPLES
01-02	3	0
03-04	2	0
05	1	0
06-07	2	0
16-17	2	0
18-19	2	0
20-21	3	0
24-25	3	2
27	2	0
28-29	3	2
30-31	4	4
32	1	1
33	1	1
34-35	3	1
36	3	1
37-38	2	3
39-40	2	2
41	3	1
42	3	2
43-44	3	2
45-46	3	2
47	3	1
48	2	2

Page No. 2  
03/10/86

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
TWO WORLD TRADE CENTER  
ELEVATOR FITS

ELEVATOR FIT	TOTAL SAMPLES	POSITIVE SAMPLES
49	3	0
*** Total ***	61	27

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING SUMMARY  
 THREE WORLD TRADE CENTER

FLOOR	TOTAL SAMPLES	POSITIVE SAMPLES	TOTAL CEILING SAMPLES	POSITIVE CEILING SAMPLES
1	10	0	10	0
*** Total ***	10	0	10	0

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING SUMMARY  
 FOUR WORLD TRADE CENTER

		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE		TOTAL POSITIVE	
	TOTAL POSITIVE	Ceiling	Ceiling	CONVECTOR	CONVECTOR	PIPING/DUCT	PIPING/DUCT	FALLOUT	FALLOUT	TILE/OTHER	TILE/OTHER
FLOOR SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES	SAMPLES
2	43	0	43	0	0	0	2	0	0	0	0
3	43	0	43	0	0	0	0	0	0	0	0
4	43	0	43	0	0	0	0	0	0	0	0
5	43	0	43	0	0	0	0	0	0	0	0
6	86	0	86	0	0	0	0	0	0	0	0
7	61	0	61	0	0	0	0	0	0	0	0
8	30	0	30	0	0	0	0	0	0	0	0
9	83	0	83	0	0	0	17	0	1	0	0
*** Total ***	440	0	440	0	0	0	19	0	1	0	0

PAG002747



WORLD TRADE CENTER  
 AIRBORNE BULK SAMPLING SUMMARY  
 FIVE WORLD TRADE CENTER

	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE	TOTAL POSITIVE
	FLOOR SAMPLES	CEILING SAMPLES	CEILING SAMPLES	CONVECTOR SAMPLES	CONVECTOR SAMPLES	PIPING/DUCT SAMPLES	PIPING/DUCT SAMPLES	FALLOUT SAMPLES	FALLOUT SAMPLES	TILE/OTHER SAMPLES	TILE/OTHER SAMPLES	TILE/OTHER SAMPLES
1	38	0	29	0	0	0	10	0	0	0	0	0
2	98	3	94	0	0	0	4	3	0	0	0	0
3	92	0	92	0	0	0	0	0	0	0	0	0
4	90	1	84	0	8	1	0	0	0	0	0	0
5	102	6	98	8	8	0	0	0	0	0	0	0
6	111	0	111	0	0	0	0	0	0	0	0	0
7	98	0	98	0	0	0	0	0	0	0	0	0
8	90	0	89	0	0	0	1	0	0	0	0	0
9	112	3	89	1	0	0	11	2	9	0	1	0
--- Total ---	831	13	781	7	12	1	48	3	9	0	1	0

PAG002748

WORLD TRADE CENTER  
 AIRBORNE BULK SAMPLING SUMMARY  
 SIX WORLD TRADE CENTER

FLOOR	TOTAL SAMPLES	POSITIVE SAMPLES	TOTAL CEILING SAMPLES	POSITIVE CEILING SAMPLES
1	10	0	10	0
*** Total ***	10	0	10	0

PA0002749

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING SUMMARY  
 NORTHEAST W.T.C. SUBLEVELS

FLOOR	TOTAL SAMPLES	POSITIVE SAMPLES	TOTAL CEILING SAMPLES	POSITIVE CEILING SAMPLES	TOTAL PIPING/DUCT SAMPLES	POSITIVE PIPING/DUCT SAMPLES	TOTAL FALLOUT SAMPLES	POSITIVE FALLOUT SAMPLES
11	43	1	19	0	20	1	6	0
12	93	0	90	0	3	0	0	0
14	73	0	73	0	0	0	0	0
*** Total ***	213	1	184	0	23	1	6	0

PAG002750

WORLD TRADE CENTER  
 ASBESTOS AIR SAMPLE SUMMARY  
 NORTHWEST W.T.C. SUBLEVELS

FLOOR	TOTAL SAMPLES	POSITIVE SAMPLES	TOTAL CEILING SAMPLES	POSITIVE CEILING SAMPLES	TOTAL PIPING/DOCT SAMPLES	POSITIVE PIPING/DOCT SAMPLES	TOTAL FALLOUT SAMPLES	POSITIVE FALLOUT SAMPLES
11	88	28	77	27	10	1	1	0
12	34	14	40	10	13	3	1	1
13	41	0	28	0	12	0	1	0
14	30	8	23	3	4	1	1	0
15	3	0	0	0	3	0	0	0
16	13	0	0	0	13	0	0	0
*** Total ***	131	48	170	42	37	3	4	1

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING SUMMARY  
 SOUTHEAST W.T.C. SUBLEVELS

FLOOR	TOTAL SAMPLES	POSITIVE SAMPLES	TOTAL CEILING SAMPLES	POSITIVE CEILING SAMPLES	TOTAL PIPING/DUCT SAMPLES	POSITIVE PIPING/DUCT SAMPLES	TOTAL FALLOUT SAMPLES	POSITIVE FALLOUT SAMPLES
B1	37	0	24	0	23	0	8	0
B2	96	0	86	0	10	0	0	0
B4	27	0	27	0	0	0	0	0
*** Total ***	160	0	137	0	33	0	8	0

WORLD TRADE CENTER  
 ASBESTOS BULK SAMPLING SUMMARY  
 SOUTHWEST W.T.C. SUBLEVELS

FLOOR	TOTAL SAMPLES	POSITIVE SAMPLES	TOTAL CEILING SAMPLES	POSITIVE CEILING SAMPLES	TOTAL PIPING/DUCT SAMPLES	POSITIVE PIPING/DUCT SAMPLES	TOTAL FALLOUT SAMPLES	POSITIVE FALLOUT SAMPLES
21	233	30	185	16	45	14	3	0
22	43	4	23	2	22	2	0	0
23	28	0	11	0	17	0	0	0
24	10	0	3	0	7	0	0	0
25	19	0	0	0	19	0	0	0
26	88	28	10	0	78	28	6	0
*** Total ***	443	62	232	18	208	44	3	0

PA0002753

WORLD TRADE CENTER  
ASBESTOS BULK SAMPLING SUMMARY  
RIVER WATER PUMPING STATION

TOTAL SAMPLES	POSITIVE SAMPLES	TOTAL PIPING/DUCT SAMPLES	POSITIVE PIPING/DUCT SAMPLES
------------------	---------------------	---------------------------------	------------------------------------

8	0	8	0
---	---	---	---

#### LABORATORY PROCEDURES

The analytical techniques used in this project are EPA-600/M4-82-020 and NIOSH 7400. Samples were analyzed in the Environmental/Industrial Hygiene Laboratory located at 25 Journal Square, Jersey City, New Jersey. All analyses were performed by Hans Brown, Marc Fish and Iradj Youssefnia under the supervision of David Platt.

The laboratory staff participates in the USEPA Bulk Asbestos Quality Assurance Program, identification number 2159; and NIOSH Proficiency Analytical Testing Program, identification number 07036-001. The laboratory has maintained a quality control and assurance program using McCrone Environmental Services Inc., Natick, Mass., as the reference laboratory.

All samples are documented from sample procurement, through analysis, to disposal using a state approved contractor. Disposal contractor's receipts are required to insure a legal final disposition of all asbestos waste.

\* Note: "Asbestos Containing Material" (ACM) is defined by the United States Environmental Protection Agency as any substance which contains more than 1% asbestos.

The symbol "<" means less than, and "TRACE" means a barely perceptible indication of asbestos that is much less than the USEPA limit for ACM.

PA0002755